

# Field Biologist Site Inspection for Family Mart

FamilyMart Peramu Pekan / 15 Jul 2025	Complete
Document No.	000147
Audit Title	Post-Opening Site Inspection
Site Name	FamilyMart Peramu Pekan
Location	Kampung Jambu, 26600 Pekan, Pahang, Malaysia (3.537317, 103.385329)
Contractor Present	Yes
Name	Ho Kok Wai
Project PIC Present	Yes
Name	Sim Hant Shen
Inspected by	
Arif Zulrushdi	
Inspection Date	15.07.2025
Prepared by	Arif Zulrushdi

#### Disclaimer

The assessors believe the information contained within this inspection report to be correct at the time of printing. The assessors do not accept responsibility for any consequences arising from the use of the information herein. The report is based on matters which were observed or came to the attention of the assessors during the day of the inspection and should not be relied upon as an exhaustive record of all possible risks or hazards that may exist or potential improvements that can be made.

#### Introduction

Our inspections are based on Integrated Pest Management (IPM) principles. Where pests are concerned we believe prevention is better than cure.

IPM achieves best results when we are able to work in partnership with our clients in order to minimise conditions that are, or could be conducive to pest activity.

Conditions observed during the inspection and consequent remedial actions needed are categorised as follows:

- Environmental/habitat management externally to minimize potential pest harborage and/or any other attraction for pests (eg food source).
- Proofing of buildings to reduce the risk of pest ingress
- Stacking of stored items to minimize the potential for pest harborage and to allow access for inspection and cleaning
- Housekeeping to minimize potential sources of food and harborage for pests.

Recommendations are allocated Red - Yellow - Green status as follows:

#### Red

High priority is the urgency to implement recommendation given. Negligence of recommendation may contribute to pest outbreak or re-occurrence of pest infestation.

#### Yellow

Medium priority is the action to be considered. Conditions attractive to pests. The action required to be accomplished.

#### Green

Low priority is the preventive action to be taken. If neglected, conditions may become attractive to pests.

## **Instructions for Inspection Report**

PB to check all area in the premise for potential entry points and potential harbourage areas in the premise.
Property and post-opening inspection, please send the report as soon as possible for customer to align with contractor at site. Please communicate with PIC for any arrangement.
To ensure findings on pre-inspection to be remained on post-inspection with remark with current proofing condition (whether it's done or not up to satisfaction).
Please send all pest related reports to fm-pestgroup@ql.com.my and CC to NKAM and servicing branch personnel.

## **Inspection Checklist for External Area**

To identify any potential entry points and harbourage area from external perimeter.

Trucking / Ducting / Piping from External

- Air-cond compressor conduits hole- Electrical Panel/DB box gaps
- Drain pipes gaps

#### Observation



Photo 1



Photo 3



Photo 2



Photo 4

#### **Remarks: Potential Pests**

Rats	Cockroach	Ants
		Termites

## **Findings**

Gaps around the aircond conduit

#### Recommendation

Seal the gaps

Updates on 15.7.2025

1: DONE

#### 2: DONE 13: NEW FINDING



Photo 5



Photo 6



Photo 7

## Landscaping

- Plant bed area potential burrowsVegetation around perimeter

#### Observation

### **Remarks: Potential Pests**

#### **Findings**

#### Recommendation

### Structural frame

- Window frame
- Door frame
- Grill
- Louver

#### Observation

#### **Remarks: Potential Pests**

## **Findings**

#### **Inspection Checklist for Entrance**

To identify any potential entry points and harbourage area at front door and its perimeter.

#### Front door

- Double glass door (all sides)
- Sliding door gaps

#### Observation



Photo 8



Photo 10



Photo 9




Photo 11

#### **Remarks: Potential Pests**

Rats	Flying Insects	Cockroach
------	----------------	-----------

#### **Findings**

Work in progress. Door is not installed yet.

Gap observed at the glass frame.

#### Recommendation

Please seal all gaps after door installation done.

Updates on 15.7.2025

3: DONE



Photo 12



Photo 13



Photo 14

## Shutter door

- Shutter door frameShutter roller casing at ceiling level

#### Observation

#### **Remarks: Potential Pests**

## **Findings**

## **Inspection Checklist for Front Ceiling**

To identify any potential entry points and harbourage area from overhead trunking connected to external perimeter.

- Trunking/ducting/piping building-shared
   Trunking/ducting connection into the premise
   From external

#### Observation



Photo 15




Photo 17



Photo 19




Photo 16



Photo 18

#### **Remarks: Potential Pests**

Ants	Cockroach	Termites
------	-----------	----------

## **Findings**

Gaps observes around the wiring conduits at wall.

#### Recommendation

Please seal the gaps

Updates on 15.7.2025

- 4: DONE
- 5: DONE
- 6: DONE



Photo 20




Photo 21



Photo 22

#### Structural beam

- Mounting poles for TV/hanging board

#### Observation

#### **Remarks: Potential Pests**

## **Findings**

## **Inspection Checklist for Counter**

To identify any potential entry points and harbourage area at counter area and its surrounding

#### Counter cabinet

- Base gapsWiring holes
- Wall-cabinet gaps
- Coffee machine drain/piping holes
- Chest freezer
- Ice machine
- Plug points

#### **Observation**



Photo 23



Photo 25




Photo 24

## **Remarks: Potential Pests**

Cockroach	Ants	Termites
-----------	------	----------

#### **Findings**

Work in progress. Gaps observed at the plugpoints.

#### Recommendation

Please close the gaps after wiring works/installation done.

#### Updates on 15.7.2025

- 7: DONE 8: DONE
- 9: DONE



Photo 26



Photo 27




Photo 28

## Sink

- Piping gaps Floor trap
- Grease trap
- Crevices along sink structures

#### Observation

#### **Remarks: Potential Pests**

#### **Findings**

#### **Inspection Checklist for Sales Floor**

To identify any potential entry points and harbourage area at sales floor, seating/dining area, waste bins, chillers, etc.

### Seating area

- Waste bin
- Wall panels, floor panels gap

#### Observation

#### **Remarks: Potential Pests**

#### **Findings**

#### Recommendation

Chillers; Reach-in-chiller/ Open-case-chiller

- Compressor conduits
- Drain trap/piping

#### Observation

#### **Remarks: Potential Pests**

#### **Findings**

## **Inspection Checklist for Sales Floor Ceiling**

To identify any potential entry points and harbourage area from overhead trunking connecting between internal areas/external.

Trunking/ducting/piping building-shared

- Trunking/ducting connection between areas inside premise

Observation	
Remarks: Potential Pests	
Findings	
Recommendation	

## **Inspection Checklist for Back Room**

To identify any potential entry points and harbourage area at storage area, manager area, back entrance.

### Manager Area

- Wiring holes/trunking/ducting
- Server rack
- Plug points

#### Observation



Photo 29

#### **Remarks: Potential Pests**

Cockroach	Ants Termites
-----------	---------------

#### **Findings**

Work in progress. No PA system installed yet.

### Recommendation

Updates on 15.7.2025

#### 14: NEW FINDING



Photo 30



Photo 31

Mop Sink/cleaning equipment storage

- Piping gaps

- Floor trap
- Wall tiles gaps

#### Observation

#### **Remarks: Potential Pests**

## **Findings**

#### Recommendation

#### **Back Door**

- Frame/door base gap

#### **Observation**



Photo 32

#### **Remarks: Potential Pests**

Rats	Cockroach	Ants
------	-----------	------

## **Findings**

Work in progress. Door is not installed yet.

#### Recommendation

Updates on 15.7.2025

15: NEW FINDING





Photo 33 Photo 34

#### Chiller

- Drain trap/pipingCompressor conduits

#### Observation

**Remarks: Potential Pests** 

**Findings** 

#### **Inspection Checklist for Back Room Ceiling**

To identify any potential entry points and harbourage area from overhead trunking connected to external perimeter.

## Trunking/ducting/piping

- Trunking/ducting connection into the back room.

#### Observation

#### **Remarks: Potential Pests**

#### **Findings**

#### Recommendation

#### Ducting/trunking

- DB box/panel
- AC conduits

#### **Observation**



Photo 35

#### **Remarks: Potential Pests**

Rats	Cockroach	Ants
		Termites

#### **Findings**

Work in progress. DB box installation is not yet complete.

#### Recommendation

Updates on 15.7.2025

DONE

16: NEW FINDING



Photo 36



Photo 37



Photo 38

## **Inspection Checklist for Toilet**

To identify any potential entry points and harbourage area for outlet with in-house toilet.

## Pipe gap

#### Observation



Photo 39




Photo 41



Photo 43



Photo 40



Photo 42



Photo 44



Photo 45

#### **Remarks: Potential Pests**

Ants	Termites	Cockroach
------	----------	-----------

## **Findings**

Some gaps observed around the pipings and conduits.

## Recommendation

Please seal the gaps

Updates on 15.7.2025

10: DONE 11: DONE 12: DONE



Photo 46



Photo 48




Photo 47



Photo 49

Observation

Remarks: Potential Pests

Findings

Recommendation

Exhaust fan

Observation

Remarks: Potential Pests

Findings

Recommendation

## **Inspection Checklist for Monitoring Units**

To verify and recommend location for monitoring trap(s) at site.

## **Insect Light Traps**

Post-Opening Inspection

#### **Recommendation / Observation**

Updates on 15.7.2025

Plugpoints has been installed





Photo 50

Photo 51

**Rodent Glue Traps** 

## **Placement Suggestion**

#### **Recommendation / Observation**

#### **Summary**

Summary

#### **Overall Remarks**

Please follow all recommendations given to minimize pest issue and entry in the future.

Above are the recommendations provided to your site based on our inspection at the current moment. Please act on the recommendations for better control of pest activity in the premise. Together with our planned pest control programme, we believe the level of pest infestation will be reduced further.

Thank you for selecting Rentokil Initial as your Pest Control service provider.

Do contact us if there's a need for further clarification.

## **Inspector's Signature**



Arif Zulrushdi 15.07.2025 11:33 +08

## Media summary




Photo 1



Photo 2



Photo 3




Photo 4



Photo 5



Photo 6



Photo 7




Photo 8



Photo 9




Photo 10




Photo 11



Photo 12



Photo 13



Photo 14




Photo 15




Photo 16




Photo 17



Photo 18




Photo 19



Photo 20



Photo 21



Photo 22



Photo 23




Photo 24



Photo 25



Photo 26



Photo 27




Photo 28



Photo 29



Photo 30



Photo 31




Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42




Photo 43



Photo 44



Photo 45



Photo 46




Photo 47



Photo 48




Photo 49



Photo 50



Photo 51