



Pest Inspection Report (Entopest)

Post-Inspection Report / 0501 Family Mart Wangsa Link / 17 Jul 2025

Complete

Score	0 / 0 (0%)	Flagged items	2	Actions	0
Inspection				Post-I	nspection Report
Store ID and Name				0501 Family Mart Wangsa Link	
Tracker					Other pest
Inspector					Amirul Mukmin
Project Team PIC					Yuziir
Project Team Present					Yes
Contractor PIC					Sam
Contractor Present					No
Issue Date					03.07.2025
Inspection Date	•				17.07.2025
Report Date					17.07.2025
Handover Date					17.07.2025



Flagged items	2 flagged
Findings / Findings #21 Status	New Findings
Findings / Findings #22 Status	New Findings



Findings 2 flagged

Findings #1

Location External (Back Area)

Observations





Photo 1

Photo 2

Findings

Found gap in between the air cond piping and wall.

Recommendation

Recommend to seal the highlighted gap

Status







Photo 3

Photo 4

Findings #2

Location Entrance Door (Front)

Observations





Photo 5

Photo 6

Findings

Gaps were observed in between the doors

Recommendation

Kindly to seal the gap

Status













Photo 9

Photo 10

Photo 11

Location Selling Floor (Wall)

Observations





Photo 12

Photo 13

Findings

Gap was observed in between piping and ceiling

Done

Recommendation

Kindly seal the gap as highlighted

Status





Photo 14

Photo 15

Findings #4

Location Selling Floor (Wall)

Observations







Photo 16

Photo 17

Photo 18

Findings

Gaps was observed in between wall and ceiling

Recommendation

Kindly seal the highlighted gaps

Status







Photo 19

Photo 20

Location

Selling Floor (Items racking)

Observations





Photo 21

Photo 22

Findings

Found gap in between wall and floor tiles

Recommendation

Kindly to seal the gaps

Done

Status





Photo 23

Photo 24

Findings #6

Location

Selling Floor (Chiller)

Observations







Photo 25

Photo 26

Photo 27

Findings

Gaps were observed at the wall and chiller base.

Recommendation

Recommend to seal the highlighted gap

Status









Photo 28

Photo 29

Photo 30

Location

Selling Floor (Chiller Store)

Observations









Photo 31

Photo 32

Photo 33

Photo 34

Findings

Found gap in between the piping and wall

Recommendation

Kindly seal the highlighted gap

Status

Done









Photo 35

Photo 36

Photo 37

Photo 38

Findings #8

Location

Selling Floor (Chiller Store)

Observations







Photo 39

Photo 40

Photo 41

Findings

Gap between floor titles was observed

Recommendation

Kindly seal the gap

Status









Photo 42

Photo 44

Location Selling Floor (Chiller Store)

Observations





Photo 45

Photo 46

Findings

Gap between floor titles was observed

Recommendation

Kindly seal the gap

Done

Status





Photo 47

Photo 48

Findings #10

Location Selling Floor (Chiller)

Observations





Photo 49

Photo 50

Findings

Detached rubber strip, potential pest hiding spot

Recommendation

Kindly fix the detached part of the rubber strip

Status

Done







Photo 51

Photo 52

Location Selling Floor (Chiller)

Observations







Photo 53

Photo 54

Photo 55

Findings

Gap was observed in between the wall and the chiller top

Recommendation

Kindly seal the gap as highlighted

Done

Status









Photo 56

Photo 57

Photo 58

Photo 59

Findings #12

Location

Food Preparation Area (Sink Area)

Observations








Photo 60

Photo 61

Photo 62

Findings

Found open piping, potential pest pathway

Recommendation

Recommend to seal the open piping

Status

Done







Photo 63

Photo 6/

Findings #13

Location

Food Preparation Area (LCD Screen Area)

Observations







Photo 65

Photo 67

Findings

Gap was observed between the wiring hole and the wall tiles

Recommendation

Recommend to seal the gap when the LCD was installed

Status







Photo 68

Photo 69

Findings #14

Location Cashier Counter

Observations











Photo 70

Photo 71 Pho

Photo 72 Photo 73

Photo 74

Findings

Gaps between cabinet will provide pest hiding spot

Recommendation

Recommend to seal the gaps



Status Done





Photo 76



Photo 75

Photo 77

Findings #15

Location Food Preparation Area

Observations











Photo 78

Photo 79

Photo 80

Photo 81

Photo 82

Findings

Found gaps at the corner of the tabletop

Recommendation

Recommend to seal the highlighted gaps

Done

Status









Photo 83

Photo 84

Photo 85

Photo 86

Findings #16

Location Toilet

Observations







Photo 87

Photo 88

Photo 89

Findings

Found gap in between the water pipe

Recommendation

Recommend to seal the gap



Status Done







Photo 90

Photo 91 Photo 92

Findings #17

Location Toilet

Observations







Photo 93

Photo 94

Photo 95

Findings

Found an opening/hole at the wall

Recommendation

Recommend to seal the gap, using wire mesh also recommended

Done

Status





Photo 96

Photo 97

Findings #18

Location Back Area

Observations







Photo 98

Photo 99

Photo 100

Findings

Gap between the cover and the tiles

Recommendation

Recommend to seal the gaps if



possible.

Status

Done







Photo 101

Photo 103

Findings #19

Location Back Area (Exit Door)

Observations





Photo 104

Photo 105

Findings

Gap between door and floor

Recommendation

Recommend to seal the gap with door sealant

Status

Done





Photo 106

Photo 107

Findings #20

Location Back Area

Observations







Photo 108

Photo 109

Photo 110

Findings

Found gap behind the trunking/wire casing, there was gap between the wire casing and



floor tiles

Recommendation

Recommend to seal the gap

Status

Done





Photo 112



Photo 111

Photo 11

Findings #21

1 flagged

Location

Selling Floor

Observations





Photo 114

Photo 115

Findings

Suggested ILT Location #1

Recommendation

To install ILT

Status

New Findings

Findings #22

1 flagged

Location

Selling Floor

Observations





Photo 116

Photo 117

Findings

Suggested ILT Location #2

Recommendation

To install ILT

Status

New Findings



Media summary



Photo 1



Photo 3



Photo 2



Photo 4





Photo 5




Photo 7




Photo 6



Photo 8





Photo 9



Photo 11




Photo 10




Photo 12





Photo 13



Photo 15



Photo 14



Photo 16





Photo 17




Photo 19



Photo 18



Photo 20






Photo 21



Photo 23




Photo 22



Photo 24





Photo 25



Photo 27



Photo 26



Photo 28









Photo 31



Photo 30



Photo 32





Photo 33




Photo 35



Photo 34



Photo 36










Photo 39



Photo 38



Photo 40










Photo 43



Photo 42



Photo 44










Photo 47



Photo 46




Photo 48









Photo 51



Photo 50



Photo 52





Photo 53



Photo 55




Photo 54



Photo 56





Photo 57



Photo 59



Photo 58



Photo 60





Photo 61




Photo 63




Photo 62



Photo 64






Photo 65




Photo 67



Photo 66





Photo 68










Photo 71




Photo 70




Photo 72





Photo 73




Photo 75




Photo 74



Photo 76










Photo 79



Photo 78




Photo 80





Photo 81



Photo 83



Photo 82




Photo 84









Photo 87




Photo 86



Photo 88





Photo 89




Photo 91



Photo 90



Photo 92






Photo 93



Photo 95



Photo 94




Photo 96





Photo 97




Photo 99



Photo 98



Photo 100









Photo 103



Photo 102



Photo 104





Photo 105



Photo 107



Photo 106



Photo 108









Photo 111



Photo 110



Photo 112





Photo 113




Photo 115




Photo 114



Photo 116




Photo 117