



Pest Inspection Report (Entopest)

Post-Inspection Report / MFM0523 FamilyMart AEON Taiping / 29 Jul 2025

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
Inspection				Post-Inspection Report	
Store ID and Name				MFM0523 FamilyMart AEON Taiping	
Tracker				Other pest	
Inspector				Adilia	
Project Team PIC				Khairul	
Project Team Present					Yes
Contractor PIC				Lim Boon Chai	
Contractor Present				Yes	
Inspection Date				29 Jul 2025 17:39 +08	
Report Date				29 Jul 2025 00:00 +08	
Handover Date				29 Jul 2025 00:00 +08	



Findings

Findings #1

Location Backroom area

Observations





Photo 1

Photo 2

Findings

Found gap surround piping connected to ceiling.

Recommendation

Kindly seal off the gap to prevent pest entry.

Status





Photo 3

Findings #2

Location Backroom area

Observations





Photo 4

Photo 5

Findings

Gap noted around yellow piping.

Recommendation

Kindly seal off the gap to prevent pest entry into internal area.

Status





Photo 6

Findings #3

Location Backroom area

Observations





Photo 7

Photo 8

Findings

Gap observed around piping serve as potential harbourage area for pest.

Recommendation

Kindly close the gap using sturdy material to help prevent pest harbourage site.

Status

Done



Photo 9

Findings #4

Location Backroom area

Observations





Photo 10

Photo 11

Findings

Gap observed around trunking pipe provides potential pathway for pest.

Recommendation

Gap need to be close to avoid pest



from using it as entry point.

Status

Done



Photo 12

Findings #5

Location Backroom area

Observations





Photo 13

Photo 14

Findings

Found gap around piping at ceiling area.

Recommendation

Kindly seal off the gap to prevent pest entry into internal area.

Status

Done



Photo 15

Findings #6

Location Backroom area

Observations





Photo 16

Photo 17

Findings

Gap noted at fire sprinkler.



Recommendation

Kindly seal off the gap to prevent pest entry into internal area.

Status

Done



Photo 18

Findings #7

Location Food preparation area

Observations





Photo 19

Photo 20

Findings

Gap noted at the side of cabinet.

Recommendation

Kindly seal off the gap to prevent pest breeding site.

Status

Done



Photo 21

Findings #8

Location Food prepration area

Observations





Photo 22

Photo 23

Findings

Found gap between power sockets.



Recommendation

Gap need to be seal off with silicone to avoid pest from using it as harbourage area.

Status





Photo 24

Findings #9

Location Food preparation area

Observations





Photo 25

Photo 26

Findings

Gap noted along mosaic tiles.

Recommendation

Gap need to be seal off with silicone to avoid pest from using it as harbourage area.

Status





Photo 27

Findings #10

Location Food preparation area

Observations





Photo 28

Photo 29



Findings

Gap observed between power sockets.

Recommendation

Gap need to be seal off with silicone to avoid pest from using it as harbourage area.

Status





Photo 30

Findings #11

Location Food preparation area

Observations





Photo 31

Photo 32

Findings

Recommendation

Found gap beneath counter area.

Gap need to be seal off with silicone to avoid pest from using it as harbourage area.

Status





Photo 33

Findings #12

Location Food preparation area

Observations



Done





Photo 34

Photo 35

Findings

Gap noted underneath counter cabinet.

Recommendation

Gap need to be seal off with silicone to avoid pest from using it as harbourage area.

Status



Photo 36

Findings #13

Location Selling floor

Observations





Photo 37

Findings

Photo 38

Recommendation

Kindly seal off with silicone to avoid pest from using it as harbourage area.

Gap observed underneath chiller.

Status



Photo 39

Findings #14

Location Selling floor



Observations





Photo 40

Photo 41

Findings

Gap noted at corner of chiller.

Recommendation

Gap need to be seal off with silicone to avoid pest from using it as harbourage area.

Status





Photo 42

Findings #15

Location Counter cabinet

Observations





Photo 43

Photo 44

Findings

Gap noted under counter area.

Recommendation

Kindly seal off the gap using silicone to avoid pest using it as harbourage area.

Status

Done



Photo 45

Findings #16



Done

Location Food preparation area

Observations





Photo 46

Photo 47

Findings

Gap noted between mosaic tiles.

Recommendation

Kindly seal off the gap using silicone to avoid pest using it as harbourage area.

Status



Photo 48

Findings #17

Location Food preparation area

Observations





Photo 49

Photo 50

Findings

Incomplete sealed gap observed.

Recommendation

Kindly seal off the gap using silicone as highlighted.

Done

Status



Photo 51

Findings #18

Private & confidential



Location Selling floor

Observations





Photo 52

Photo 53

Findings

Incomplete sealed gap was observed underneath chiller.

Recommendation

Kindly seal off the gap using silicone as highlighted.

Done

Status



Photo 54

Findings #19

Location Counter cabinet

Observations





Photo 55

Photo 56

Findings

Hole was observed at corner of cabinet.

Recommendation

Kindly seal off the hole using silicone as highlighted.

Status



Photo 57



Findings #20

Location Counter cabinet

Observations







Photo 58

Photo 59

Photo 60

Findings

Gap was observed between mosaic tiles at floor.

Recommendation

Kindly seal off the gap using silicone as highlighted.

Done

Status





Photo 61

Photo 62

Findings #21

Location Selling floor

Observations





Photo 63

Photo 64

Findings

Hole was observed on the wall.

Recommendation

Kindly seal off the hole using silicone as highlighted.

Status



Photo 65



Findings #22

Location Dining area

Observations





Photo 66

Photo 67

Findings

Gap was observed on the floor at dining area.

Recommendation

Kindly seal off the gap using silicone as highlighted.

Status





Photo 68

Findings #23

Location Selling floor

Observations





Photo 69

Photo 70

Findings

Hole was observed on the side of wall.

Recommendation

Kindly seal off the hole using silicone as highlighted.

Status





Photo 71

Findings #24

Location Selling floor

Observations





Photo 72

Photo 73

Findings

Insect light trap will be place at this area.

Status Done

Private & confidential



Media summary



Photo 1



Photo 3



Photo 5



Photo 2



Photo 4



Photo 6

Private & confidential





Photo 7



Photo 9



Photo 11




Photo 13



Photo 8



Photo 10



Photo 12



Photo 14



Photo 15




Photo 17



Photo 19



Photo 21



Photo 16



Photo 18



Photo 20




Photo 22



Photo 23



Photo 25



Photo 27



Photo 29



Photo 24



Photo 26




Photo 28



Photo 30





Photo 31



Photo 33



Photo 35



Photo 37



Photo 32



Photo 34



Photo 36



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46

Private & confidential 20/24





Photo 47



Photo 49



Photo 51



Photo 53



Photo 48



Photo 50



Photo 52



Photo 54



Photo 55



Photo 57



Photo 59



Photo 61



Photo 56



Photo 58



Photo 60



Photo 62





Photo 63




Photo 64



Photo 65



Photo 66



Photo 67



Photo 68

Private & confidential 23/24





Photo 69



Photo 71



Photo 73



Photo 70



Photo 72