TRUEFIELD CLOSE-OUT FORM (PUMP-07 / BRG-1)

WO: (as issued)

Technician: Kwame Asante

Root cause: Outer-race spalling on BRG-1

Matches diagnosis: yes

Actions done: Applied LOTO per LOTO-PUMP-07; Replaced bearing BRG-ZA2115; Flushed and refilled oil

Parts used: BRG-ZA2115 x1; OIL-ISO68-5L x2

Actual downtime minutes: 95

LOTO removed by: Kwame Asante

Follow up: Re-check vibration after 24 h