

Integrator/CM7TDMI User Guide

ARM DUI 0126B

Errata 01

This errata corrects incorrect information given in the diagrams in section A.2 of the user guide.

Text changes

No changes.

Text additions

No additions.

Tables

No changes

Figures

In Figures A-2 and A-3, pins 110 and 111 are incorrectly given as 150 and 151. The corrected figures are shown below.




Figure A-2 HDRB socket pin numbering




Figure A-3 HDRB plug pin numbering