Houston Power Saver

INVOICE

TACLB020326E

 10222 Inwood Dr
 DATE:
 June 10, 2021

 Houston, Texas 77042
 INVOICE # 01210610

 Office: (832) 968-0000
 FOR:
 Service/maintenace

www.HoustonPowerSavers.com

Barbara Towne 1616 Fountainview Dr #205 Houston, TX 77057 (281) 686-8178

| DESCRIPTION | AMOUNT |
|--|-----------|
| Fixed float switch wire | |
| subtotal | 97.50 |
| Rechecked freon levels and added R-22 | |
| subtotal | 100.00 |
| | |
| | |
| | |
| | |
| | |
| | |
| Notes: | |
| A/C system has a leak. We recommend either using leak stop or replacing the condenser. Leak stop will work better if the leak is small. If this is a bigger leak, we recommend installing a new R-410A system. R-410A is the new refrigerant that is | |
| more efficient and cheaper per pound. Call us for questions. | |
| | |
| TOTAL | \$ 197.50 |

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694