
How to Flash the firmware into the $$\operatorname{R36Max}$$

1.	Install the flash tools and Usb driver	2
	1.1 Install the usb driver	
	Double click the RKDevTool.exe	
	Loading the firmware u need	
	Identify the loader device	
	Flash the firmware	


1. Install the flash tools and Usb driver




1.1 Install the usb driver



2. Double click the RKDevTool.exe



3. Loading the firmware u need



4. Identify the loader device

Use a data cable to connect one end to the computer and the other end to the device's OTG port.

Method 1: While the device is powered off, hold down the volume up button and then press and hold the power button.

Method 2: While the device is powered on, hold down the volume up button and then briefly press the reset (RST) button.

5. Flash the firmware

After identifying the MaskROM/Loader device, click "Upgrade," and the right side will prompt you that once the download is complete, the device will automatically restart and boot into the system interface.