

SAMPLE VEHICLE REPAIR ESTIMATE

FOR TRAINING / DEMONSTRATION ONLY — NOT A REAL INVOICE

Garage	Pune Auto Care Centre
Estimate No.	PAC-EST-2026-0918-117
Customer	Rajesh Sharma
Vehicle	Maruti Suzuki Baleno
Registration No.	MH 12 AB 1234
Inspection Date	18 September 2026

Item	Estimated Cost (₹)
Front bumper replacement	28,000
Left headlamp assembly	18,500
Bonnet repair and paint	22,000
Left fender repair and paint	16,000
Labor and alignment	12,000
Consumables	3,500
Subtotal	1,00,000
GST (18%)	18,000
TOTAL ESTIMATE	1,18,000

Estimated repair cost: ₹1,18,000. Final cost may vary after dismantling and inspection.