## Safety & Personal Protective Equipment (PPE) Guidelines

- Closed-toe shoes and rated eye protection must be worn in the Fabrication Lab at all times.
- Do not operate heavy equipment if you are overly fatigued or otherwise impaired.
- Students may **never** work in the Fabrication Lab alone.
- Loose clothing, long hair, dangling items, and anything else that could pose an entanglement hazard must be removed or tied back prior to entering the fabrication lab.
- Hearing protection should be worn when performing or working adjacent to loud tools (cf. "EARS" communication).
- Respiratory protection should be worn when performing or working adjacent to activity that generates dust or fumes for a prolonged period. (cf. "dust/fumes" communication)
- Work gloves may be worn during some activities handling rough materials or large objects, however they may not be worn when they could pose an entanglement hazard such as with a band saw or stationary belt sander.
- **Rubber gloves** may be worn when working with paints or adhesives. Consult with faculty before using rubber gloves to handle a solvent.
- Some specific tasks in the Prototyping Lab also require PPE.