






Identifying failure with Current Signature Analysis of point motors




Carbon brush worn out




More current at locking time due to spring




Obstruction in Point Motor



More friction due to lubrication problem



Problem in Unlocking



Problem in locking position