## INSTR\_RETIRED\_ANY Schd=Static Chk=1 5E+10 4.5E+10 4E+10 Thread 1 3.5E+10 Thread 2 Thread 3 INSTR\_RETIRED\_ANY 3E+10 Thread 4 Thread 5 2.5E+10 Thread 6 Thread 7 2E+10 ■ Thread 8 Thread 9 1.5E+10 Thread 10 Thread 11 1E+10 Thread 12 5E+09 core 5 core 6 core 7 core 0 core 1 core 2 core 3 core 4 core 8 core 9 core 10 core 11 Cores