## INSTR\_RETIRED\_ANY Schd=Static Chk=2 5E+10 Thread 1 4.5E+10 Thread 2 Thread 3 4E+10 Thread 4 Thread 5 3.5E+10 Thread 6 Thread 7 INSTR\_RETIRED\_ANY 3E+10 Thread 8 Thread 9 2.5E+10 Thread 10 2E+10 Thread 11 Thread 12 1.5E+10 Thread 1 Thread 2 1E+10 Thread 3 Thread 4 5E+09 Thread 5 Thread 6 core 2 core 7 core 0 core 1 core 3 core 5 core 6 core 8 core 9 core 10 core 4 core 11 Thread 7 Cores