

FORM

RMA REPAIR SUMMARY

Document Code: D-RMA-0002-02 Effective Date: 11 March 2024

Page No.: 01 of 01

RMA Number	HTR24010051		Customer	ATS-F	
Part Number	300-60511-11		Serial Numb	oer 0157544	
Part Description	FOX-P 128 HCCM wit	th HEATSINK			
Failure Information	PM-U30 BAD				
Work Perfomed					
Installed missing U34, U Replaced burnt PM_U3 Reprogram firmware		C31			
Testing Result					
Calibration	PASSED	BTS: Short Duration Run		Bench Test	
TLB Test	PASSED	BTS: Long Duration Run		PG Test	
Slot Diagnostic		BTS: Over Night Run		PGD Test	
Special Test Run		Device Test			
Repair Time					
Start Repair Date		2-Apr-24 Er	nd Repair Date		5-Apr-24
Upgrade Time		(Hours)	est Time		1 (Hours)
Repair Time		15 (Hours)	vernight Run Time		(Hours)
Calibration		1 (Hours)	pecial Test Time		(Hours)
Repaired by: MARK JOSEPH ZARADULLA					
Approvals					
MITE		Julie Ann Sto 9	Domingo	- Carmul	

ARWAYNE HIPOLITO Repair Engineering Head

Date: April 11, 2024

NOUT

JULIE ANN STO. DOMINGO

Sr. Quality Engineer

Date: April 11, 2024

^ *O'*

RICKY GO

Operations Manager

Date: April 11, 2024



