



Figure 3: the progression of the indentation of bearing 4A; a) initial defect; b) after 19 hours at various load and speed conditions; c) after 70 hours ; d) after 124 hours; e) after 332 hours – c), d) and e) at 300 rpm and 1800 N