

Update history :

- 2.5.1 - Fixed intermittent lock up issues.
- 2.5.0 - Improved workflow efficiency when using the Stompbox Mode:
if both footswitches are held down while a 'bank-change'
is in progress the pedal promptly switches to stompbox mode,
reverting to the currently active preset.
 - Minimized the extraneous noises emitted by some algorithms
when no input is present. Update instruction:
 1. Download "SymmLabPatch-112025" and install (double click,
then follow the instruction on screen).
 2. Apply the firmware update.
 3. Apply Library Update: "Menu > Update Library".
 4. Refresh your existing presets by executing the following
sequence in the SymmLab editor:
 - A. Menu > Backup
(this creates a backup file to be used in the next step).
 - B. Menu > Restore
(use the backup file created in the previous step).
- 2.4.9 - Improved handling of out-of-range MIDI CC values.
 - Modified the display behavior so that continuous stream of
tap tempo signal on the Aux input doesn't lock the display.
- 2.4.8 - Fixed intermittent lock up during power up, due to changes
made in previous update.
- 2.4.7 - Fixed an issue where certain algorithms are not producing
outputs when a preset is called via midi.
 - Fixed intermittent lock up issues when turning DSP-X
On and Off via Midi.
- 2.4.6 - Added 'Pre/Post Toggle' function to Aux switch functions list.
 - Added 'Patch Up/Down' function to MIDI CC implementation.
 - Added Pre or Post indication in the home scene display.
 - Algo modifications:
 - * Fixed volume jumps in "Slow Volume" algorithm.
 - * Fine tuned intensity of the Vinyl Dust effect in "Record"
algorithm.
 - Bugs fixes:
 - * Fixed FREQUENCY parameter display not working on the
Wah Filter algorithm.
- 2.4.5 - Fixed midi CC#30's and CC#36's reversed control with the
Tremolo algorithm.
 - Fixed midi CC#30's and CC#36 not working with with the
Harmonic Trem and Chopper algorithms.
 - Fixed a few other minor bugs.
- 2.4.4 - Fixed Tremolo algorithm + expression pedal bug.
- 2.4.3 - Fixed expression pedal not controlling 'Fast Speed'

parameter correctly on Horn and Drum algorithms.

- 2.4.2 - Disable auto engage when scrolling algorithms in Stompbox Mode.
- 2.4.1 - Added Active Sensing message filter to MIDI reception.
 - Added 'Running Status' handling capability.
- 2.4.0 - Fixed a bug in MIDI reception.
- 2.3.9 - Fixed volume drop issue.
- 2.3.8 - Fixed a bug with effect loading on DSP-X.
- 2.3.7 - Improve robustness of MIDI receive buffering system.
- 2.3.6 - Fixed pitch-gliding and fading-in artefacts on the DSP-X side when going from bypassed state to engaged state.
- 2.3.5 - Improved Arp-sequence reset operation.
 - Fixed bugs in Chopper algorithm.
- 2.3.4 - Minor bug fixes.
- 2.3.3 - Fixed bug with Favorite Preset operation.
- 2.3.2 - Improved operational stability.
- 2.3.1 - Fixed bug where the Aux Patch-Up/Down functions not remembering the last-used bank.
- 2.3.0 - Added 'Wah' algorithm.
 - Added Bypass-on-PC option.
 - Fixed bug with Tap-div control via MIDI.
 - Fixed bug with DSP-Y Tap-div setting via Option menu.
- 2.2.2 - Fixed CC#42 bug.
- 2.2.1 - Fixed issues with certain Midi CC messages.
- 2.2.0 - Fixed bugs in Midi CC message handling.
 - Improved Arp Filter algorithm.
 - Added two Aux switch functions:
 - Patch Up and Patch