
V_{BUS}
V_{3V3}
R_{SHUNT}
+
-
Current Sense Amplifier
Half-Bridge
To Motor Phase
V_{BUS}
Half-Bridge
R_{SHUNT}
To Motor Phase
-
+
Current Sense Amplifier