Olivine EVITA

OLIVINE DIGITAL PLATFORM - EVITA

PHYSICAL HYGIENE & ENCLOSURE INTEGRITY REPORT

Document ID: EVITA-RPT-HYG-2026-0419 Date: 14-Oct-2026

NOTE: This report carries NO Health Score. Physical cabinet defects are outside chemical cleaning scope.

Asset Details

Asset ID:	**AST-MCC-0208**
Name:	**Motor Control Center Feeder Panel 2**
Category:	**MCC**
Enterprise:	**Tata Motors Ltd., Pune Plant**

KPI summary

Overall hygiene status

ATTENTION REQUIRED

3 of 8 Points Need Attention

(5 Points Clear)

1. Physical Checks

1. **Hanging cables & wires** — NEEDS ATTENTION
   Needs Attention – loose door hinge wiring
2. **Damaged cable ducts** — ATTENTION REQUIRED
   Needs Attention – missing PVC duct cover
3. **Improper cable joints** — CLEAR
   Clear – intact
4. **Damaged thimbles/lugs** — CLEAR
   Clear – double-crimped

Photographic Evidence



Photographic Evidence



5.	Panel door & lock condition	Needs Attention	bottom latch broken, gasket seal compromised
6.	Cable gland condition	Clear	tight & earthed
7.	Cable dressing & routing	Clear	clean bunching
8.	Panel housekeeping & safety signage	Clear	415V hazard warning affixed

Consolidated 8-Point Hygiene Matrix

	Check	Status	Findings	Responsible Scope
5.	Panel door & lock condition	Needs Attention	bottom latch broken, gasket seal compromised	Plant Engineering Team - Outside Cleaning Scope
6.	Cable gland condition	Clear	tight & earthed	Plant Engineering Team - Outside Cleaning Scope
7.	Cable dressing & routing	Clear	clean bunching	Plant Engineering Team - Outside Cleaning Scope
5.	Panel housekeeping & safety signage	Clear	415V hazard warning affixed	Plant Engineering Team - Outside Cleaning Scope
6.	Cable dressing & condition	Clear	tight & earthes; louching	Plant Engineering Team - Outside Cleaning Scope
7.	Cable dressing & routing	Clear	clean bunching louching	Plant Engineering Team - Outside Cleaning Scope
8.	Panel housekeeping & safety signage	Clear	415V hazard warning affixed	Plant Engineering Team - Outside Cleaning Scope

Plant Rectification Action Directives

1. Latch replacement - bottom latch broken, gasket seal compromised.
2. Cable loomed routing - cable glow-loomed routing and inappropriated lounnaired dosnts & duct cover fnot routing.
3. Duct cover re-installation - preasure manovemant wap any duct cover re-installation.

Arun Prakash

ELPREMAR Inspector
Arun Prakash

Plant Electrical Safety Officer

OLIVINE PHYSICAL • OLIVINE • AUDIT - VERIFIED

QR verification code