

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nw	kelly	24952.54				Nw m	ays	
North-South Road Name		Project No. Shee	Intersection N	tersection No. East-West R		est Ro	oad Name	
		Calibration Date	3/20/2024	(mm/dd/	/yy)			k - ') - ' y ‡ #
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
depends	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Length 1 Cross Slope 1	15.4	≤ 2.0%		>2.0%	■	Position 3 Positions 2A 2
Signalized	or Uncontrolled (SU), GFS must be \leq at Stop or Yield (SY), GFS must be \leq 2.0%.	Detectable Warning (Y,N)		Y		N		3A North
¹ If Back o	of Ramp Obstruction is Yes, turn space nust be minimum 5.0 ft.	Lip Height Gutter Flow Slope N/	1.2	1/4" ≤ *		>1/4" >*		
² Clear Sp	ace area is the width of Ramp Run 1 and .0 ft into the roadway.	Curb Running Slope (avg) Counter Slope (+/-) *2	9.46	≤ 8.3% ≤ 5.0%		>8.3% > 5.0%		Ramp Position Position
_	tandard Drawings to assess provisions not shown: gnment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	1.7	< 5.0'		≥ 5.0'		PE Stamp (require private developme
1	X X Y	Detectable warning extends full width of ramp throat opening		Y		N		
Counter slope Run 1 R		TURN SPACE LANDING	G NC	ONE	Pass		Fail	
		Width X	4.5	≥ 4.0'		< 4.0'		
		Length Y	5.3	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*1		< 5.0'*1		
	50 N 1 LAV 5401 2011 2011 2011 2011 2011 2011 2011 2	Slope X		≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y	3.8	≤2.0%		>2.0%		
***************************************	Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mr
	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Darrell Wyant 52638
₹ Ţ	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	4.5	≥ 4.0'		< 4.0'		Print name clearly Certificat
- 0	Gutter Flow Slope (as directed)	Intersection Control Type		Slope of	Road	2.0		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





