

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

315th Ave	9	24952.54				Turel	Dr	
North-South Road Name		Project No. Shee	et No. Ir	ntersection N	lo.	East-W	est Ro	oad Name
		Calibration Date	11/19/20	24 (mm/dd	/yy)			k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ramp Style PR		RAMP RUN 1	_	10.20	Pass	> 0.20/	Fail	2 Corner
depends on the Midblock (MB),	ng value for Gutter Flow Slope (GFS) on the Intersection Control Type. At a (MB), GFS must be ≤ Slope of the Road, at or Uncontrolled (SU), GFS must be ≤	Running Slope 1 Length 1 Cross Slope 1 Detectable Warning (Y,N)	4.55 1.0	≤ 8.3% ≤ 2.0% Y		>8.3% >2.0% N		Corner Position 3 Positions 2A
•	p or Yield (SY), GFS must be \leq 2.0%.	Lip Height	0	1/4"		>1/4"	H	3A North
1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft. 2 Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway. See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.) PERPENDICULAR RAMP (PR) Pedestrian Access Route (to measure Clear Width)		Gutter Flow Slope Curb Running Slope (avg)		≤*		>*		2 Ramp 1
		Counter Slope (+/-) *2	5.0	5.0 ≤ 8.3% Ramp	Ramp			
		Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		private developn
		Detectable warning extends full width of ramp throat opening	Υ	Y		N		
		TURN SPACE LANDING	G NON	IE	Pass		Fail	
		Width X	7.3	≥ 4.0'		< 4.0'		
		Length Y	5.1	≥ 4.0'*¹		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)	N	≥ 5.0'*¹		< 5.0'*1		nan
		Slope X	0.8	≤2.0%		>2.0%		
	le Warning Surface	Slope Y	0.9	≤2.0%		>2.0%		L
***************************************	ope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
	Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (r
	Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Darrell Wyant 5263
Turning 8 * If const	Space (X & Y) (2.0% max. / 4' x 4' min.)* rained at back of walk, min. Y length is 5'.	Clear Width (feet)	5.1	≥ 4.0'		< 4.0'		Print name clearly Certific
→ Gutter Fl	ow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	0.5		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





