

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

OREGON		——-			- <u> </u>		·	
Nw 285	24952.54	L			Nw m	-		
North-South Road Name	Project No. Shee	et No. II	ntersection N	o.	East-W	est Ro	oad Name	
	Calibration Date	8/20/2024	(mm/dd/	/yy)			k - ') '	•
Ramp Style PR	RAMP RUN 1		-	Pass	. 0. 20/	Fail	Corner	
	Running Slope 1		≤ 8.3%		>8.3%	Ш	Corner	1
The passing value for Gutter Flow Slope (GFS)	Length 1	13.5					Position 3	01
epends on the Intersection Control Type. At a Aidblock (MB), GFS must be ≤ Slope of the Road, a	Cross Slope 1	2.5	≤ 2.0%		>2.0%		1	3
ignalized or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N		3A	
.0%, and at Stop or Yield (SY), GFS must be $\leq 2.0\%$	Lip Height		1/4"		>1/4"		2 North	
¹ If Back of Ramp Obstruction is Yes, turn space ength Y must be minimum 5.0 ft.	Gutter Flow Slope	/A 0.4			>*			
	Curb Running Slope (avg)	2.96	≤ 8.3%		>8.3%		Ramp 1 Positions	
² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.7	≤ 5.0%		> 5.0%		Position 5	
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	1.75	< 5.0'		≥ 5.0'		PE Stamp (re private deve	•
X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Y		N			
/ · · · · / · / · · · /	TURN SPACE LANDING	G NON	NE	Pass		Fail		
Aun 1/2 de	Width X	4.0	≥ 4.0'		< 4.0'			
Counter sions	Length Y	4.9	≥ 4.0'*¹		< 4.0'*1		Comments:	
	Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'*1			
PERPENDICULAR RAMP (PR)	Slope X		≤2.0%		>2.0%			
Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%			
Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail	Г	
Cross Slope (2.0% max.)	Flare Slope 1		≤ 10%	1 33	< 10%	$\overline{}$		
Running Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%	H		ate (n
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	4.0	≥ 4.0'		< 4.0'		/ /	5263
il constrained at back of wark, fillin. I length is 5.	` '	17.0	4	Da = -!		믜	Print name clearly Ce	ertifica
Gutter Flow Slope (as directed)	Intersection Control Type		Slope of				3J Consulting	
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





