	WASHINGTON COUNTY OREGON	-				
	NW 317th PI					
	North-South Road Name					
		PL				
		Ramp Sty				
dep Mid Roa mus	*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be \leq Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.					
	f Back of Ramp Obstruction is Yes ce length Y must be minimum 5.0					
* ² c and	Clear Space area is the width of Raextends 4.0 ft into the roadway.	mp Run 1				

(inlets, alignment, etc.)

18 Run 3

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

ADA Curb Ramp New Construction Inspection Form (Parallel)

24952.54

Ramp Style

	Project No. Sheet No.	Intersection No.			East-	East-West Road Name		See https://www.oregon.gov/odot/Engineering/Documents RoadwayEng/ADA_ExhibitA.pdf for more corner styles.		
	Calibration Date 1	0/22/2024	(mm	/dd/yy	')				DA_ExhibitA.pdf for m on County corner numl	
Π	RAMP RUN 1	Pass			Fail 4	4	1 111	2		
	Running Slope 1		≤ 2.0%		> 2.0%		Corner	- : 117	Corner Positions	1
	Cross Slope 1	4.0	≤ 2.0%		> 2.0%		Position	3	5	2A 1
	Detectable Warning	Υ	Y		N		-	1		3
	Lip Height	0	≤ 1/4"		> 1/4"		(3A	. . 1	
	Gutter Flow Slope	2.2	≤ *		> *			2	North	2
	Curb Running Slope(avg)	15.16	≤ 8.3%		> 8.3%>			4	Dame (1	
	Counter Slope (+/-)*2	7.8	≤ 5.0%		> 5.0%		1	12	Ramp 1 Positions	
	Det. warning full width of ramp	Υ	Υ		N		Ramp Position		5	
	RAMP RUN 2		Pass			Fail			PE Stamp (equired for
	Running Slope 2	10.3	≤ 8.3%		> 8.3%				private dev	
	Length 2	7.25								
	Cross Slope 2	1	≤ 2.0%		> 2.0%					
	RAMP RUN 3	Pass				Fail				
	Running Slope 3		≤ 8.3%		> 8.3%					
	Length 3	7.45								
	Cross Slope 3	2.7	≤ 2.0%		> 2.0%		Camanant			
TURN SPACE		Pass				Fail	Comments	S:		
	Width X	5.1	≥ 4.0'		< 4.0'		IITD			
	Length Y	5.0	≥ 4.0'*1		< 4.0'*1					
	Back of Ramp Obstruction (Y/N)	N	≥ 5.0'*¹		< 5.0'*1					
	Slope X (Cross Slope 1)	4.0	≤ 2.0%		> 2.0%					
	Slope Y (Running Slope 1)		≤ 2.0%	Ш	> 2.0%					
	MISCELLANEOUS			Pass		Fail	Inspector's S	ignature		Date (mm/dd/yy)
	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell \	•		52638.0
	Intersection Control Type	SY	Slope o	Slope of Rd. 2.3	2.7		Print name c			Certification No
	Horizontal Gaps	0	≤ 1/2" >		> 1/2"		3J Consultin	-		
					•		Company/Ag	gency		

NW North Ave

Reset Entire Form

Keep Intersection, Reset Fields



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





