

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	Constr							
Nw 2	288 ave	24952.54				Nw SI	nadd	lon st
North-	-South Road Name	Project No. Shee	et No.	Intersection N	о.	East-W	est Ro	oad Name)
		Calibration Date	3/13/2024	(mm/dd/	/yy)			k - ') - '
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a	Length 1	11.0			2.00/		Position 3 Positions 2A
•	MB), GFS must be \leq Slope of the Road, at or Uncontrolled (SU), GFS must be \leq	Cross Slope 1 Detectable Warning (Y,N)	\vdash	≤ 2.0%		>2.0% N	Н	3
•	nd at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height		1/4"		>1/4"		3A North
	FRamp Obstruction is Yes, turn space ust be minimum 5.0 ft.	Gutter Flow Slope	A 1.4	≤ *		>*		4 Ramp 1
² Clear Spa	ace area is the width of Ramp Run 1 and) ft into the roadway.	Curb Running Slope (avg) Counter Slope (+/-) *2	3.9	≤ 8.3% ≤ 5.0%		>8.3% > 5.0%		Ramp Position Positions
	andard Drawings to assess provisions not shown: nment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	1.45	< 5.0'		≥ 5.0'		PE Stamp (requi private develop
/-	We will be the second of the s	Detectable warning extends full width of ramp throat opening		Y		N		
Run 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1		TURN SPACE LANDING	G NO	NE	Pass		Fail	
		Width X	4.2	≥ 4.0'		< 4.0'		
		Length Y	5.8	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0' * 1		< 5.0'*1		
	A STATE OF THE STA	Slope X	2.6	≤2.0%		>2.0%		
	edestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		L
	etectable Warning Surface coss Slope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
	unning Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date
	ounter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Darrell Wyant 5263
₹ Tu * It	rning Space (X & Y) (2.0% max. / 4' x 4' min.)* f constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Print name clearly Certific
⊸ Gu	utter Flow Slope (as directed)	Intersection Control Type		Slope of	Road	0.8		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





