

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	L OOD	04050.54				N 2		
	Jw 288 ave	24952.54 Show	ot No	Intorcostica N	10	Nw SI		
NC	orth-South Road Name		et No.	Intersection N		East-W	est Ko	oad Name
		Calibration Date	8/13/2024	(mm/dd/	/yy) 			к -) - y ‡ #
	Ramp Style PR	RAMP RUN 1			Pass		Fail	
		Running Slope 1	7.8	≤ 8.3%		>8.3%	Ш	Corner Positions
	sing value for Gutter Flow Slope (GFS)	Length 1	5.0					Position 3
•	ds on the Intersection Control Type. At a ock (MB), GFS must be \leq Slope of the Road, at	Cross Slope 1	1.5	≤ 2.0%		>2.0%		1 3
•	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N	Ш	3A -
5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.		Lip Height		1/4"		>1/4"		North
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	0.8	≤ *		>*		
		Curb Running Slope (avg)	3.44	≤ 8.3%		>8.3%		Ramp 1 Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.4	≤ 5.0%		> 5.0%		Position 5
	o Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (require private developm
Counter slope Run 1 Gurger Flow slope		Detectable warning extends full width of ramp throat opening		Y		N		
		TURN SPACE LANDIN	G NO	NE	Pass		Fail	
		Width X	5.0	≥ 4.0'		< 4.0'		
		Length Y	5.0	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0' * 1		< 5.0'*1		
Pl	5-70 NO 11 NO 5-70 SERVICE SCHOOL SERVICE SERVICE SCHOOL SCHOOL SCHOOL SERVICE SCHOOL SERVICE SERVICE SCHOOL SERVICE SCHOOL SERVICE SCHOOL SERVICE SCHOOL SCHOOL SERVICE SCHOOL SERVICE SCHOOL SERVICE SCHOOL SCHOOL SERVICE SCHOOL SERVICE SCHOOL SERVICE SCHOOL SERVICE SCHOOL SCHOOL SERVICE SCHOOL SERVICE SCHOOL SCHOOL SERVICE SCHOOL SERVICE SCHOOL SERVICE SCHOOL SCHOOL SERVICE SCHOOL SERVICE SCHOOL SCHOOL SERVICE SCHOOL SERVICE SCHOOL SCHOOL SCHOOL SCHOOL SERVICE SCHOOL	Slope X		≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y	2.1	≤2.0%		>2.0%		
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail	
+	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%	\Box	Inspector's Signature Date (m)
A	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)		≥ 4.0'		< 4.0'	\Box	Darrell Wyant 52638 Print name clearly Certifica
**	* If constrained at back of walk, min. Y length is 5'.	Intersection Control Type		Slope of	Road			
-	Gutter Flow Slope (as directed)	Horizontal Gaps		≤1/2"		> 1/2"		3J Consulting
		110112011tai Gaps		71/2		<i>></i> 1/2		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





