

## **ADA Curb Ramp New Construction Inspection Form (Perpendicular)**

	- control									
N	lw 288 ave	24952.54					Nw Shaddon st			
No	rth-South Road Name	Project No. Shee	et No. In	tersection N	lo.	East-W	est Ro	pad Name		
		Calibration Date	8/13/202	4 (mm/dd,	/yy)			k - ') · · · · · · · · · · · · · · · · ·		
	Ramp Style PR	RAMP RUN 1			Pass		Fail			
	Trainip Style	Running Slope 1	7.8	≤ 8.3%		>8.3%	Ш	Corner		
•	sing value for Gutter Flow Slope (GFS)	Length 1	5.0					Position 3		
•	s on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1	1.5	≤ 2.0%		>2.0%		2 3		
Signalize	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Y		N		3A 1		
5.0%, ar	d at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height		1/4"		>1/4"		2 North		
	of Ramp Obstruction is Yes, turn space	Gutter Flow Slope	0.8	≤ *		>*				
length Y must be minimum 5.0 ft.		Curb Running Slope (avg)	3.44	≤ 8.3%		>8.3%		1 Ramp 1 Positions		
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.4	≤ 5.0%		> 5.0%		Position 5		
	o <u>Standard Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (required private developmen		
Counter slope		Detectable warning extends full width of ramp throat opening		Υ		N				
		TURN SPACE LANDIN	G NON	E	Pass		Fail			
		Width X	5.0	≥ 4.0'		< 4.0'				
		Length Y	5.0	≥ 4.0'*¹		< 4.0'*1		Comments:		
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'* <sup>1</sup>	П			
PE	Service and the same service service services and the service services and the services are serviced as the service services and the service services are serviced as the service service services are serviced as the service services are serviced as the service services are serviced as the service service services are serviced as the service services are serviced as the service service services are serviced as the service service services are serviced as the service service service services are serviced as the service service services are serviced as the service service service services are serviced as the service service service services are serviced as the service service service service service service services are serviced as the service service service service service servic	Slope X		≤2.0%		>2.0%				
	Pedestrian Access Route (to measure Clear Width)	Slope Y	2.1	≤2.0%		>2.0%				
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail			
<b>+</b>	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mm/		
A	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%				
<b>I</b>	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 52638 Print name clearly Certification		
	Gutter Flow Slope (as directed)	Intersection Control Type	MB	Slope of	Road	0.4		· · · · · · · · · · · · · · · · · · ·		
		Horizontal Gaps		≤1/2"		> 1/2"		3J Consulting Company/Agency		
		<u>'</u>		•		-, <del>-</del>	$\perp$	company// gency		



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





