

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

100	COMPA 1 A							
N	IW 291 st	23885.56				NW k	ing a	ve
No	orth-South Road Name	Project No. Shee	t No.	Intersection N	0.	East-W	est Ro	pad Name
		Calibration Date 0	7/23/24	(mm/dd/	'yy)			k - ')' - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner Corner
depends Midblock Signalize	ssing value for Gutter Flow Slope (GFS) Is on the Intersection Control Type. At a ck (MB), GFS must be \leq Slope of the Road, at ed or Uncontrolled (SU), GFS must be \leq nd at Stop or Yield (SY), GFS must be \leq 2.0%.	Length 1 Cross Slope 1	13.2	≤ 2.0%		>2.0%		Position 3 Positions 2A
		Detectable Warning (Y,N) Lip Height		Y 1/4"		N >1/4"		3A North
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope Curb Running Slope (avg)	1.9 4.22	≤ * ≤ 8.3%		>* >8.3%		Ramp Positions
xtends 4	4.0 ft into the roadway.	Counter Slope (+/-) *2	5.2	≤ 5.0%		> 5.0%		Ramp Position PE Stamp (re
	o Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	1.15	< 5.0'		≥ 5.0'		private develop
/	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Y		N		
	Run 1 W Le Slope Slope Ba EBPENDICUL AB BAMP (PB)	TURN SPACE ■ LANDING Width X	G NO	ONE ≥ 4.0'	Pass	< 4.0'	Fail	
Counter		Length Y Back of Ramp Obstruction (Y/N)		$\geq 4.0^{1*1}$ $\geq 5.0^{1*1}$		< 4.0'*1 < 5.0'*1		Comments: Rr1 icrr tool joints and j box in turn s
Р		Slope X		≤2.0%		>2.0%		
	Detectable Warning Surface	Slope Y MISCELLANEOUS Traversa	ble	≤2.0%	Pass	>2.0%	Fail	
# # A	Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)	Flare Slope 2		≤ 10% ≤ 10%		< 10% <10%		Inspector's Signature Date (
√ ₹	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 5263 Print name clearly Certific
-	Gutter Flow Slope (as directed)	Intersection Control Type Horizontal Gaps		Slope of ≤1/2"	Road	> 1/2"		3J Consulting Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





