

DIO5-142 NC
POSTED

EWR D&I ANNOTATION



FAN-000001L053001DP577-4587

Artemis # : 000001L053001DP577

Record Created Date : 06/14/2006

Printed Date : 06/14/2006

Description :

THE SUBJECT VEHICLE WAS BEING OPERATED ON A LOCAL HIGHWAY WHEN THE VEHICLE FOR UNKNOWN REASONS VEERED OFF THE HIGHWAY INTO THE MEDIAN AND STRUCK A TRACTOR-TRAILER HEAD-ON TRAVELING IN THE OPPOSITE DIRECTION. THE SATURN BOUNCED BACK INTO ITS ORIGINAL LANE OF TRAVEL AND WAS STRUCK BY TWO MORE TRACTOR-TRAILERS. THERE ARE CONFLICTING REPORTS AS TO WHO WAS DRIVING THE SUBJECT VEHICLE, HOWEVER OF THE TWO OCCUPANTS THERE WAS ONE INJURY, AND ONE FATALITY. A SECOND INJURY VICTIM WAS REPORTED FROM ANOTHER VEHICLE. THE POLICE REPORT APPEARS TO INDICATE THAT THE RAINY CONDITIONS SOMEHOW CONTRIBUTED TO THE CRASH. THE FATHER OF THE INJURED OCCUPANT OF THE SATURN VEHICLE ALLEGES THAT THE AIRBAGS DID NOT DEPLOY AND THAT THE DRIVER SEATBACK COLLAPSED CAUSING HIS DAUGHTER TO BE EJECTED FROM THE VEHICLE. THERE ARE NO APPARENT SAFETY RECALL RELATED TO THE ISSUES RAISED BY THIS CRASH.

Print

Close

Notes
No pursuits
ws



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

400 Seventh St., S.W.
Washington, D.C. 20590

MAR - 1 2006

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Ms. Gay P. Kent, Director
General Motors Corp.
Mail Code 480-111-E18
30200 Mound Road
Warren, MI 48090

NVS-217ph
DI05-142

Dear Ms. Kent,

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death incidents reported by General Motors Corporation in its light vehicle early warning report for the 3rd quarter of 2005. We are writing to request additional information about the following incidents:

Selected Death Incidents from the 3rd Quarter of 2005	
For Reporting Category: L	
For the following Sequence IDs (SeqID): 28, 129, 137, 173, 221, 227, 233, 238, 248, 254, 286, 291, 299, 324, 329, 337, 385, 452, 456, 459, 521, 577	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident reported in Sequence IDs identified above.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to General Motors Corporation.

Vehicle: the vehicle produced by General Motors Corporation that is identified in the claim or notice.

Tire: the tire produced by General Motors Corporation that is identified in the claim or notice.



VEHICLE SAFETY HOTLINE
888-327-4236

Equipment: the item of motor vehicle equipment produced by General Motors Corporation that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever, be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color. Furnish all documents whether verified by General Motors Corporation or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in General Motors Corporation's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After General Motors Corporation's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the claim or notice document(s) that notified General Motors Corporation of the incident, including any amendments and supplements thereto, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of all documents, photographs, videos, received from the claimant(s) or claimant's representative that identify and/or support or purport to support any allegation of a defect in the vehicle, regardless of whether General Motors Corporation disputes the assertions therein and excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices and estimates; and (c) documents related to quantification of damages.
3. Provide a copy of all investigative documents prepared by any local, state, or Federal governmental agency or personnel related to the incident, including but not limited to photographs, Police Accident Reports, or cause and origin reports.
4. At your option, provide General Motors Corporation's assessment of the circumstances that led to the incident including General Motors Corporation's analysis of the claim and/or notice regarding allegations of a defect.

This letter is being sent to General Motors Corporation pursuant to 49 U.S.C. § 30166, which authorizes NHTSA to conduct any investigation that may be necessary to enforce Chapter 301 of Title 49 and to request reports and the production of things. It constitutes a new request for information. General Motors Corporation's failure to respond promptly and fully to this letter


could subject General Motors Corporation to civil penalties pursuant to 49 U.S.C. § 30165 or lead to an action for injunctive relief pursuant to 49 U.S.C. § 30163. (Other remedies and sanctions are available as well.) Section 5(a) of the TREAD Act, codified at 49 U.S.C. § 30165(b), provides for civil penalties of up to \$5,000 per day, with a maximum of \$16,050,000 for a related series of violations, for failing or refusing to perform an act required under 49 U.S.C. § 30166. *See* 49 CFR 578.6 (as amended by 69 Fed. Reg. 57864 (Sept. 28, 2004)). This includes failing to respond to ODI information requests.

If General Motors Corporation claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, General Motors Corporation must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, Room 5219, 400 Seventh Street, S.W., Washington, D.C. 20590.

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by April 7, 2006. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,



Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS NORTH AMERICA
Structure & Safety Integration

April 6, 2006

Ms. Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement, NHTSA
400 Seventh Street, S.W.
Washington, DC 20590

GMRC022

NVS-217ph
DI05-142

Dear Ms. Morgan:

This letter is General Motors' (GM) response to your inquiry dated March 1, 2006, regarding certain death incidents reported by GM in its light vehicle early warning report for the 3rd quarter of 2005.

GM's response is comprised of 35 CDs (1 audio tape), one or more for each incident that is the subject of DI05-142.

Attachment "A" includes instructions for navigating the CD. Each CD, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 28 168230056 – 501616 2003 Cadillac CTS. When the CD is launched, this identification number appears again along with all of the documents (including photographs and videos) on the CD listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 28 168230056 – 501616_00 Request and Responses.tif. The index is numbered one through four to correspond to Inquiries no. 1 through 4 of the inquiry, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the first two Request and Responses in the index for one of the CDs are as follows:

DI05-142
28 168230056 – 501616
2003 Cadillac CTS

Request for Information:

1. Provide a complete and full copy of the claim or notice document that notified General Motors Corporation of the incident, including any amendments and supplements thereto, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Documents

2. Provide a copy of all documents concerning the alleged defect, or alleged consequences of the alleged defect, that refer to the incident excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices and estimates; and (c) documents related to quantification of damages.

Response: None.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

28 16823056 – 501616_01_001 - is the first document responsive to Inquiry no. 1.
28 16823056 – 501616_03_001 - is the first document responsive to Inquiry no. 3.
28 16823056 – 501616_03_002 - is the second document responsive to Inquiry no. 3.

Your inquiries and our corresponding replies are as follows:

Product Investigations

Mail Code: 480-111-E18 • 30200 Mound Road • Warren, MI 48090-9010
GMRC022 DI05-142 Response.doc



1. Provide a complete and full copy of the claim or notice document(s) that notified General Motors Corporation of the incident, including any amendments and supplements thereto, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

The table below lists the incidents that are the subject of DI05-082, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. § 579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR), or Rumor (RMR). Lawsuit and NISM case types generally meet the § 579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do not involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further. As such, the document included in response to Inquiry 1 that can be found on the enclosed CD for the PAR and Rumor case listed in the table may not be a claim or notice of the type generally defined as such by § 579.4(c).

SELECTED DEATH INCIDENTS FROM THE 3RD QUARTER OF 2005 REPORTING CATEGORY L (22 VEHICLES FROM TEMPLATE)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
28	1G6DM57N930 [REDACTED]	LIT
129	1G1JC12F847 [REDACTED]	LIT
137	1G1AL12F857 [REDACTED]	NISM
173	UNKNOWN	RMR
221	1GCCS14X6WK [REDACTED]	NISM
227	1GCCS19X138 [REDACTED]	NISM
233	1GNCT18WXXVK [REDACTED]	LIT
238	1GNCS13W3V2 [REDACTED]	LIT
248	1GNDT13W4Y2 [REDACTED]	NISM
254	1GNCT18W42K [REDACTED]	LIT
286	2GCEK19T841 [REDACTED]	NISM
291	2GCEC19V34 [REDACTED]	LIT
299	1GCHK29U11E [REDACTED]	NISM
324	1GNFK16Z04J [REDACTED]	LIT
329	3GNFK16Z85G [REDACTED]	NISM
337	1GNEK13Z54R [REDACTED]	LIT
385	1GNDV23L85D [REDACTED]	NISM
452	2GTEK13T551 [REDACTED]	LIT
456	1GTHC24U05E [REDACTED]	LIT
459	1GTJC33U84F [REDACTED]	NISM
521	1G2NE52T2XC [REDACTED]	LIT
577	1G8AJ52F24Z [REDACTED]	NISM

2. Provide a copy of all documents, photographs, videos, received from the claimant(s) or claimant's representative that identify and/or support or purport to support any allegation of a defect in the vehicle, regardless of whether General Motors Corporation disputes the assertions therein and excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices and estimates; and (c) documents related to quantification of damages.

See attached document.

3. **Provide a copy of all investigative documents prepared by any local, state, or Federal governmental agency or personnel related to the incident, including but not limited to photographs, Police Accident Reports, or cause and origin reports.**

See attached documents and photographs.

4. **At your option, provide General Motors Corporation's assessment of the circumstances that led to the incident including General Motors Corporation's analysis of the claim and/or notice regarding allegations of a defect.**

To date, GM's investigation of the alleged defect has not included an assessment of the cause(s) of each incident responsive to this request. Some incident reports may not contain sufficient reliable information to accurately assess cause. Assessments of other incidents (from lawsuits and claims) may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators, and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




Gay P. Kent
Director
Product Investigations


Enclosures:
35 CDs , 1 Audio tape
Attachment A

Attachment A Instructions for using CD Viewer

1. Insert the CD into the CD ROM drive; the CD will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl +PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl +PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl +PgDn** or **Ctrl +PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The image shows a legal case cover sheet for "CARDONA V. CHEVROLET" filed in the Superior Court for the State of California, Indio Court. The cover sheet includes fields for attorney information, case name, and various checkboxes for case type and complexity. To the right of the cover sheet is a software interface with a list of actions: Next Image, Previous Image, Next page, Previous page, Full screen image, Slide show, Scale to fit, Scale 50%, Scale 100%, Scale 200%, Rotate left, Rotate right, Rotate by 180°, Copy to clipboard, Copy file to, Move file to, Rename file, Delete file, Print, and Preferences. Arrows point from text boxes to specific actions in the software interface.

Step 7 Next File (Image) points to the "Next Image" button.

Step 7 Next page points to the "Next page" button.

Step 8 Scale Image points to the "Scale 100%" button.

Step 7 Image Properties points to the "Preferences" button.

DI05-142
577 135291907 – PLC200500116 - 500852
2004 SATURN ION

Request for Information:

1. Provide a complete copy of the claim or notice document(s) that notified General Motors Corporation of the incident, including any amendments and supplements thereto, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Documents and Photographs.

2. Provide a copy of all documents, photographs, videos, received from the claimant(s) or claimant's representative that identify and/or support or purport to support any allegation of a defect in the vehicle, regardless of whether General Motors Corporation disputes the assertions therein and excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices and estimates; and (c) documents related to quantification of damages.

Response: None.

3. Provide a copy of all investigative documents prepared by any local, state, or Federal governmental agency or personnel related to the incident, including but not limited to photographs, Police Accident Reports, or cause and origin reports.

Response: See Attached Document.

4. At your option, provide General Motors Corporation's assessment of the circumstances that led to the incident including General Motors Corporation's analysis of the claim and/or notice regarding allegations of a defect.

Response: To date, GM's investigation of the alleged defect has not included an assessment of the cause(s) of each incident responsive to this request. Some incident reports may not contain sufficient reliable information to accurately assess cause. Assessments of other incidents (from lawsuits and claims) may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

500 852

RECEIVED

16 JUL

NEW ALBANY GAZETTE

NEW ALBANY GAZETTE

Serving New Albany and Union County Since 1889

Monday, July 11, 2005



www.weather.com

Archives

Home

News

Local Color

Sports

Opinion

What do you think?

Obituaries

Classifieds

Business Directory

Subscribe

Contact Us

Article Search

Search

Man dead after car hits three 18-wheelers

One man died and one woman was seriously injured following a Friday afternoon collision of a car with three tractor-trailers on Highway 78 both east and west-bound.

The rain from an early evening summer rainfall was beginning to taper off when the black Saturn, headed west, lost control and crossed the median hitting an east-bound tractor-trailer head-on.

The force of the collision knocked the Saturn back across the median into 78 West where two more tractor-trailers struck the compact car.

Neither of the two people injured hails from Union County.

Crashing into the three trucks mutilated the automobile, knocking the front far into the back and spewing debris across the interstate.

On the scene a purse and a golf shoe lay on the highway and foam from the inside bumper of the car was clearly visible in the debris.

_____ of Alabama, died in the collision, according to New Albany police officer Clay Keener, who worked the accident scene for the department.

His female passenger, however, survived and was taken to The Med in Memphis, Keener said.



New Albany police officers investigate Friday afternoon's fatal car, tractor-trailer crash. One officer examines the remains of the black Saturn and the other interviews potential witnesses. Paramedics and rescue workers attended to the surviving passenger giving her a neck brace and treating her for cuts and bleeding before hoisting her onto a stretcher and taking her to The Med in Memphis. The living victim was not identified and her current status could not be determined. Photo by Ryan Bramlett/Gazette Staff

Police would not release the name of the injured female so no status report could be released from The Med.

The car bore Oklahoma plates and [REDACTED] license was issued in Alabama.

Efforts to find family of [REDACTED] were unsuccessful.

Keener said the couple appeared to be travelling.

"It was a real bad one," Keener said of the fatal crash.

It was not clear however what caused the car to lose control and cross the median, Keener said.

Due to the severe nature of the injuries to the surviving female, Keener said he has not interviewed her yet.

"They took her straight to The Med in Memphis," Keener said adding that is one of the reasons he was unable to determine the cause of the crash.

Fallout from the crash halted traffic east-bound on 78 for at least an hour.

Cars were backed up as police cleaned and investigated the scene.

The quick rain shower stopped shortly after the crash, but mud and wet conditions persisted.

The location of the accident, Highway 78 just past the downtown New Albany exit is a hot spot for crashes, but this crash is the only recent fatal accident.

[Print this story](#)

[Email this story](#)

[Home](#) | [News](#) | [Local Color](#) | [Sports](#) | [Opinion](#)
[Obituaries](#) | [Classifieds](#) | [Business Directory](#) | [Article Search](#)
[Subscribe](#) | [Contact Us](#) | [What Do You Think?](#)

** Saturn Confidential **

Print Date

Incident Date & Time 6/10/2005

Title - First Name [REDACTED] Middle - Last Name [REDACTED]

Street [REDACTED]

City Oklahoma City	State OK	Zip	Country -	Age 0
--------------------	----------	-----	-----------	-------

Home Phone [REDACTED] 0000 Work Ph. [REDACTED] 0000

If Company Owned - Name -

Title - First Name - Middle - Last Name -

Street -

City - State - Zip - Country - Age -

Home Phone _____ Work Ph. _____

Title	Mr	First Name	Middle -	Last Name
-------	----	------------	----------	-----------

Street Owners father same as owner

City -	State -	Zip -	Country -	Age -
--------	---------	-------	-----------	-------

Home Phone _____ Work Ph. _____

Attorney

Title - First Name - Middle - Last Name -

Street -

City - _____ State - _____ Zip - _____ Country - _____ Age - _____

Home Phone _____ Work Ph. _____

TA000085872

Case # (b) (6)

7/25/2005

Saturn Product Liability
Report of Preliminary Investigation
** Saturn Confidential **
Case # (b) (6)

Print Date
7/25/2005

Property Damage

Damage, Other than Owners Vehicle (Vehicle Property Yes Other Than Vehicle No)

Owner

Title - First Name - Middle - Last Name -
Street -
City - State - Zip - Country - Age 0
Home Phone Work Ph.

Driver

Title - First Name - Middle - Last Name -
Street -
City - State - Zip - Country - Age -
Home Phone Work Ph.

Vehicle

Make/Model/Year

Estimate of Speed 0

By Whom? -

Extent of Damage

One semi had major damage.

Property Owner

Title - First Name - Middle - Last Name -
Street -
City - State - Zip - Country - Age -
Home Phone Work Ph.

Kind of Damage

Extent of Damage

Additional Comments

End of Property Information

Saturn Product Liability
Report of Preliminary Investigation
** Saturn Confidential **
Case # (b) (6)

Print Date
7/25/2005

Bodily Injuries

Bodily Injuries? Yes

Number of People: 2

1)
Title - First Name [REDACTED] Middle - Last Name [REDACTED]
Street [REDACTED]
City Oklahoma City State OK Zip [REDACTED] Country USA Age -
Home Phone [REDACTED] 0000 Work Ph. [REDACTED] 0000

Location Code -

Driver's Name : -

Seating Position: Driver

Nature of Injuries:

Driver broken jaw, a lacerated liver, her arm was broken i

Where were Injuries Treated?

-

By Whom?

-

Claimant Reported: Seat Belt Usage: Yes Shoulder Belts?: Yes Lap?: Yes

2)
Title Mr First Name [REDACTED] Middle - Last Name [REDACTED]
Street Owners Husband Same as owner
City - State - Zip - Country - Age -
Home Phone Work Ph.

Location Code -

Driver's Name : -

Seating Position: Front Passenger

Nature of Injuries:

Deceased

Where were Injuries Treated?

-

By Whom?

-

Claimant Reported: Seat Belt Usage: Yes Shoulder Belts?: Yes Lap?: Yes

End of Bodily Injuries

**Saturn Product Liability
Report of Preliminary Investigation**

** Saturn Confidential **

Case # (b) (6)

Print Date
7/25/2005

Incident Information

Was Another Vehicle Involved? Yes Number of Vehicles 0

Did vehicle overturn? No

Where can vehicle be seen? State Farm has towed it to a storage facility

Principal use of vehicle Personal

Driver Description

-

Did you speak to driver? No

If No, Give Source of Driver Desc. -

Nature of Weather -

What Component(s) are Allegedly defective air bags

Who made allegation of defect Owners father

Estimated Vehicle Speed 67 MPH

Source of Estimated Vehicle Speed Owners father

Was Vehicle towed? No

Towing Co. Name -

Towing Co. Address -

Tow Driver Name -

End of Incident Information

**Saturn Product Liability
Report of Preliminary Investigation**

**** Saturn Confidential ****

Case # **(b) (6)**

Print Date
7/25/2005

Location Information

Police Report Made? Yes Report Attached? No
Station Making Report - _____

Officer
Title - First Name - Middle - Last Name -
Street -
City - State - Zip - Country - Age -
Home Phone Work Ph. _____

Witness
Title - First Name - Middle - Last Name -
Street -
City - State - Zip - Country - Age -
Home Phone Work Ph. _____

Location of Incident
- _____

Kind of Road - Kind of Shoulder -
Condition of Road - Condition of Shoulder - Posted Speed 0 MPH

Visual Obstructions
- _____

Additional Comments
- _____
- _____

End of Location Information

**Saturn Product Liability
Report of Preliminary Investigation**

**** Saturn Confidential ****

Case # (b) (6)

Print Date
7/25/2005

Retailer / Parts Detail Information

Were Photos Taken? Yes Number? 64

By Whom?

Title - First Name EAA Middle - Last Name -

Street 100 Saturn Pkwy

City Spring Hill State TN Zip 37174 Country USA Age 0

Home Phone Work Ph.

Vehicle Inspected No Inspector(s) Name EAA

CIGNA Rep. at Investigation

Selling Retailer SATURN OF OKLAHOMA CITY

City OKLAHOMA CITY State OK

Servicing Retailer SATURN OF BIRMINGHAM

City BIRMINGHAM State AL

Did Search of the National Service History Produce Customer Service Orders? Yes

How Many Line Items? 14

How & When was matter left with claimant?

I advised the owners father the SDM module had been removed from the vehicle
prior to our inspector arriving at the salvage yard.

End of Retailer Information

Saturn Product Liability
Report of Preliminary Investigation

** Saturn Confidential **

Case #

(b) (6)

Print Date
7/25/2005

General Comments

07-07-05 10:40 AM

The owners father stated his daughter is seriously injured and his son in law is deceased. They were impacted by three to five Semi trucks. The air bags did not deploy in this incident. They are unsure of what happened as their daughter was thrown from the vehicle. They are seeking information about the incident.

07-07-05 11:11 AM 205-944-8334

I was given permission to inspect the vehicle. BLB

07-08-05

Assigned to EAA via FAX. BLB

07-13-05

Inspected by EAA. BLB

07-20-05

Inspection completed. BLB

07-25-05

Recieved photos via priority mail. BLB

07-25-05 3:35 PM

I advised the owner we were advised by the tow yard personell the SDM had been removed by One of the companies from one of the other vehicles involved. I also advised him the passenger air bag was deployed and seperate from the rest of the vehicle. BLB

07-25-05 3:50 PM

I advised the Insurance agent of the removal of the air bag computer. BLB

End of General Comments

Saturn Product Liability
Report of Preliminary Investigation
** Saturn Confidential **
Case # (b) (6)

Print Date
7/25/2005

Notification / Investigator Detail Information

Saturn Notified on Incident?
How? Service Request When? 7/6/2005
Area Assigned SC

Assignment

Investigator
First Name Engineering Middle A Last Name EAA
Assignment Date 7/8/2005 Due Date 7/18/2005
Investigation Date - Received Date 7/8/2005

Info. from Further Investigation
-

CIGNA Office Code	<u>DETROIT, MI</u>	Date Sent	<u>-</u>
Area Approved By	<u>-</u>	Date	<u>-</u>
C.O. Approved By	<u>-</u>	Date	<u>-</u>

End of Notify Information

Saturn Product Liability
Report of Preliminary Investigation
** Saturn Confidential **
Case # (b) (6)

Print Date
7/25/2005

Resolution Comments

Resolution: 1241, no Saturn Resp., fwd to CIGNA, info only

End of Resolution Comments

Saturn CAC Information

** Saturn Confidential **

Case # (b) (6)

Print Date
7/8/2005

CAC Case Information

CAMIS Case Number (b) (6)

Owner:

Oklahoma City

OK

Home Phone:

Work Phone:

Source:

Family Member

Contact:

Service Request

Issue Comments:

The owner's father, (b) (6) alleges the air bags did not deploy in a collision. He stated his daughter was traveling approximately 67 mph outside of New Albany, MS when the vehicle was struck on the left front side by a semitruck vehicle at which time the vehicle spun and was struck again multiple times. He stated that his daughter slid out

Vehicle: 1G8AJ52F24Z (b) (6) 2004

Mileage: 29000

Delivery: 10/16/2003

In Warranty: Yes

Retailer: 11148

Problems: 0 s - (SIR) - DriC46 - Restraintver Front

Resolution Comments:

from behind her driver's side seat belt as well as the seatback collapsing causing her to be ejected from the vehicle out the back window sustaining multiple injuries including a broken jaw, a lacerated liver, her arm was broken in multiple places and she required multiple stitches. He also stated his son-in-law died in this accident. (b) (6) stated th

Memo: No Corporate File: Yes

Legal: No Letter: No

Close: Yes

End of CAC Case Information

Saturn CAC Information
**** Saturn Confidential ****
Case # **(b) (6)**

Print Date
7/8/2005

CAC Legal Information

CAMIS Case Number **(b) (6)**

Legal Information I

Case Type: Product Liabili
PL Basic Info: Product Liabili
Reason: -

Representation: No

Request: -
Vehicle Disposition: -

Legal Information II

Outcome: -
Legal Correspondence: No

PL Basic Information I

Allegation: The owner's father, (b) (6) alleges the air bags did
Driver at time of incident: (b) (6)
Vehicle Damage: Yes Description: Major Front End Damage, Broken rear wind
Property Damage: No Description: -
Date and Time of the incident: 6/10/2005

PL Basic Information II

Injuries: Yes Description: Driver broken jaw, a lacerated liver, he
Additional Vehicle Involved? Yes Description: One semi had major damage.
Police Report Filed? Yes Where? New Albany PD
Where is the vehicle now? State Farm has towed it to a storage facility
Contact # for vehicle location: (b) (6)
Claimant's Permission for Investigation? No

End of CAC Legal Information

Saturn CAC Information

** Saturn Confidential **

Case # (b) (6)

Print Date

7/8/2005

CAC Memopad Information

CAMIS Case Number (b) (6)

Date: 7/7/2005 8 User: KBRUMBEL Approve

Type: Approve - Contact Name: Kelly Brumbelow1241

Date: 7/6/2005 3 User: Forward

Type: Forward - Contact Name: Kelly Brumbelow

Date: 7/6/2005 1 User: Inbound Call

Type: Inbound Call - Contact Name: Owner's father stated that his daughter was involved in a collision and wanted to speak with someone higher up about why the air bags on her vehicle did not deploy. I provided information to the caller on when airbags should deploy from the air bag brochure. Owner stated: * on June 10, 2005 at around 5:00 pm his daughter was involved in an accident outside of New Albany, MS. * the vehicle was struck on the left front side by a semitruck was struck again multiple times. * his daughter slid out from behind her driver's side seat belt as well as the seatback collapsing causing her to be ejected from the vehicle out the back window sustaining multiple injuries including a broken jaw, a lacerated liver, her arm was broken in multiple places, and other injuries requiring 100-150 stitches. * also in the vehicle was his son-in-law, seated in the passenger seat, who died as a result of the accident. * there were a total of 4-5 semi trucks involved in the accident and at least one other injury to one of the drivers. * at the time of the accident there was a heavy rain and the roads were wet. * the police said that the vehicle was hydroplaning. * There is a police report with the New Albany PD, but he did not have the report number. * The vehicle was totalled by the insurance company, State Farm, as a result of the accident. * The Claim representative's name is Jerry Studdard, whose number is 205-944-8334. * the vehicle has been taken to a storage facility by State Farm after having been totaled by the retail facility. I provided callback expectations to the caller.

Date: 7/6/2005 1 User: Outbound Call

Type: Outbound Call - Contact Name: I attempted to contact State Farm Claim Representative Jerry Studdard at 205-944-8334

Date: 7/6/2005 3 User: Outbound Retailer Call

Type: Outbound Retailer Call - Contact Name: I attempted to contact the FOM at S/ Oklahoma City but was advised he won't be in for over a

Saturn CAC Information

** Saturn Confidential **

Case # (b) (6)

Print Date

7/8/2005

week. I asked for the person filling in for the FOM and was connected with Service Consultant Kyle Elmore of S? Oklahoma City. I informed him that a product allegation had been made regarding a vehicle the facility had sold.

Date: 7/6/2005 1 User: SADMIN SR Summary

SR Summary The owner's father, [REDACTED] alleges the air bags did not deploy in a collision. He stated his daughter was traveling approximately 67 mph outside of New Albany, MS when the vehicle was struck on the left front side by a semitruck vehicle at which time the vehicle spun and was struck again multiple times. He stated that his daughter slid out from behind her driver's side seat belts as well as the seatback collapsing causing her to be ejected from the vehicle out the back window sustaining multiple injuries including a broken jaw, a lacerated liver, her arm was broken in multiple places and she required multiple stitches. He also stated his son-in-law died in this accident. [REDACTED] stated the vehicle has major front end damage and the back window is broken. I advised of 7-10 day call.

Date: 7/6/2005 1 User: SADMIN Standard Questions

1. There were injuries as a result of the accident. 2. Injuries: Driver broken jaw, a lacerated liver, her arm was broken i 3. There was no property damage as a result of the accident. 4. [REDACTED] was driving at the time of the incident. 5. There were 2 occupants in the vehicle. 6. The Owner's daytime phone is [REDACTED] The Owner's evening phone is [REDACTED] The Claimant's daytime phone is [REDACTED] 7. The events leading up to the incident are as follows: The owner's father, [REDACTED] alleges the air bags did 8. The incident occurred on 06/10/2005 at 17:00. 9. Right outside of New Albany, MS 10. Heavy Rain 11. Wet Road 12. The vehicle was traveling at 67. 13. State Farm Claim Representative Jerry Studdard 205-944-8334 14: Vehicle Loc: State Farm has towed it to a storage facility 15. Vehicle Damage: Major Front End Damage, Broken rear wind 16. Police Report: New Albany PD 17. Other Damage: One semi had major damage. 18. Permission has not been granted to inspect the vehicle.

End of CAC Memopad Information

SATURN VEHICLE INVOICE

ORDER TYPE: T INVOICE DATE: 09/03/03 ORDER NUMBER: 4FJR965
PRICE EFFECTIVE: 08/26/03 SHIP DATE: 09/03/03 INVOICE AMT: 15,935.00
REFERENCE NBR: 003677647 INVOICE DUE: 09/05/03
VEHICLE IDENTIFICATION NUMBER: 1G8 AJ5 2F2 4Z HP: 142SW: 2760

CHARGE TO: 11337 SATURN OF EDMOND, INC. KEY CODE: G0950
SHIP TO: 11148 SATURN OF OKLAHOMA CITY
FINANCED BY: 0014501 BANK ONE ARIZONA

MAIL TO: SATURN OF EDMOND, INC.
505 EAST I-240 SERVICE ROAD
OKLAHOMA CITY, OK 73149

MODEL:	MSRP	INV AMT
ZAJ69 2004 ION 2SEDAN AUTOMATIC	14,635.00	13,664.55

FACTORY OPTIONS:

HCG TRAVEL PACKAGE:	200.00	186.00
* MAP LIGHTS		
* AUTO-DIMMING INSIDE MIRROR		
W/EXTERIOR TEMPERATURE GAUGE		
AND DIGITAL COMPASS		
HAA POWER PACKAGE:	825.00	767.25
* REMOTE KEYLESS ENTRY W/ALARM		
* POWER WINDOWS		
* PWR. REMOTE EXTERIOR MIRRORS		
* CRUISE CONTROL		
B37 FLOOR MATS - FRONT AND REAR	80.00	74.40
FE9 50-STATE EMISSIONS		
US9 AM/FM 6CD CHANGER WITH MP3	460.00	427.80
(REPLACES STD/OPT RADIO)		
17C GREY		
41L BLACK ONYX		
41U BLACK ONYX		

TOTAL MODEL AND OPTIONS	16,200.00	15,120.00
TRANSPORTATION CHARGE	565.00	565.00
MARKETING SERVICES CHARGE		250.00
TOTAL INVOICE	16,765.00	15,935.00

MEMO ITEMS: 486.00
HOLDBACK

GM EMPLOYEE PURCHASE - OUT OF STOCK (GMS) PRICE \$ 14,961.53
TRANSPORTATION CHARGE 565.00
TOTAL GMS PRICE \$ 15,526.53

THIS INVOICE MAY NOT REFLECT THE RETAILER'S ULTIMATE VEHICLE COST
IN VIEW OF FUTURE MANUFACTURER REBATES, ALLOWANCES, INCENTIVES, ETC.

CERTAIN CHARGES CONTAINED HEREIN ARE BEING INVOICED ON BEHALF OF
SATURN DISTRIBUTION CORPORATION.

**Saturn Product Liability
Option Report
** Saturn Confidential ****

Case Nbr: (b) (6)
Vin: 1G8AJ52F24Z

OPTION CODE	OPTION DESCRIPTION
-----	-----
C60	AIR CONDITIONING
AR9	FRT SEAT BKT
A31	POWER WINDOWS
6AB	FRT LH STRUT
HAA	POWER PACKAGE
J41	DISC/DRUM BRAKES
K34	CRUISE CONTROL
7AB	FRT RH STRUT
8AF	RR LH STRUT
41U	BLACK ONYX
41L	BLACK ONYX
9AF	RR RH STRUT
PG1	STEEL WHEEL
U79	4 SPEAKER SYSTEM
FE9	FEDERAL EMISSION
AK5	RESTRAINT SYS SEAT
AU0	RKE LOCK CONTROL
L61	4CYL 2.2L ENGINE
NK5	STD STEERING WHL
DG7	REMOTE O/S MIRROR
HCG	TRAVEL PACKAGE
DF5	MIRROR I/S R/V
FH9	TRANS RATIO 2.6
17C	GREY CLOTH
B25	TRIM EQUIP LUGG COMP
B37	FLOOR MATS
C74	DUAL READING LAMP
DL5	ROADSIDE SVC DECAL
FE1	SUSPENSION SYSTEM
IPC	TRIM INTERIOR DESIGN
K62	GENERATOR
MX0	MERCH TRANS AUTO
M43	AUTOMATIC TRANSMISSN
QTU	P195/60R15 TIRE
UH8	INSTRUMENT CLUSTER
US6	ANTENNA
V73	US/CAN VEH STATEMENT
17I	GREY INTERIOR TRIM
NT9	FEDERAL EMISS SYS
RF3	MERCH PKG L2 SDN AUT
US9	MULTI CD RADIO W/MP3
BBC	BODY COLOR ROOF RAIL

End Of Option Report

CSO History Information

Case # - (b) (6)

VIN - 1G8AJ52F24Z

Facility	CSO Nbr	Miles	Case Nbr	Case Typ	CSO Dt	Net Paid	Labor Op
10145	0133803	28214	01	VW	6/7/2005	\$80.50	J6372
	Complaint	-	L04	-	SES LIGHT		
	Conditon	-	-	-			
	Cause	-	C29	-	INOPERATIVE PART		
	Failed Labor	-					
	Failed Part Nbr	-	12568234	-	SENSOR ASM-HTD OXY (POSN 1)		
	Tech Comments	-			CUST STATES SES LIGHT COMES ON AT TIMES WHILE DRIVING,SCANNED ECM FOUND CODES P0130 AND P0134 STORED,O2 SENSOR #1 FAULTY,NECESSARY TO REPLACE FAULTY O2 SENSOR #1 AND CLEAR CODES VEHICLE OPERATING AS DESIGNED AT THIS TIME		
10145	0133803	28214	02	CP	6/7/2005	\$0.00	N9995
	Complaint	-	-	-			
	Conditon	-	-	-			
	Cause	-	-	-			
	Failed Labor	-					
	Failed Part Nbr	-	-	-			
11148	0235693	21301	01	CP	12/20/2004	\$0.00	M5005
	Complaint	-	-	-			
	Conditon	-	-	-			
	Cause	-	-	-			
	Failed Labor	-					
	Failed Part Nbr	-	-	-			
11148	0235693	21301	02	VC	12/20/2004	\$56.73	V1095
	Complaint	-	-	-			
	Conditon	-	-	-			
	Cause	-	M02	-	CAMPAIGN		
	Failed Labor	-					
	Failed Part Nbr	-	22734980	-	FILTER ASM-FUEL		
11148	0235693	21301	03	VC	12/20/2004	\$25.22	V1098
	Complaint	-	-	-			
	Conditon	-	-	-			
	Cause	-	M02	-	CAMPAIGN		
	Failed Labor	-					
	Failed Part Nbr	-	-	-			

CSO History Information

Case # - (b) (6)

VIN - 1G8AJ52F24Z

Facility	CSO Nbr	Miles	Case Nbr	Case Typ	CSO Dt	Net Paid	Labor Op
11148	0235693	21301	04	VC	12/20/2004	\$83.59	V1275
	Complaint	-	-				
	Conditon	-	-				
	Cause	-	M02	-	CAMPAIGN		
	Failed Labor	-					
	Failed Part Nbr	-	15146012	-	ATTACHMENT PKG-HDLP		
11148	0235693	21301	05	CP	12/20/2004	\$0.00	M5088
	Complaint	-	-				
	Conditon	-	-				
	Cause	-	-				
	Failed Labor	-					
	Failed Part Nbr	-	-				
11148	1021350	9	01	SY	10/16/2003	-\$396.00	X4005
	Complaint	-	-				
	Conditon	-	-				
	Cause	-	-				
	Failed Labor	-					
	Failed Part Nbr	-	-				
	Tech Comments	-	NO LEIN				
11148	1021350	9	01	SM	10/16/2003	-\$635.00	X4005
	Complaint	-	-				
	Conditon	-	-				
	Cause	-	-				
	Failed Labor	-					
	Failed Part Nbr	-	-				
	Tech Comments	-	NO LEIN				
11148	0221495	15	01	CP	10/16/2003	\$0.00	R9995
	Complaint	-	-				
	Conditon	-	-				
	Cause	-	-				
	Failed Labor	-					
	Failed Part Nbr	-	-				

CSO History Information

Case # - (b) (6)

VIN - 1G8AJ52F24Z

Facility	CSO Nbr	Miles	Case Nbr	Case Typ	CSO Dt	Net Paid	Labor Op
----------	---------	-------	----------	----------	--------	----------	----------

11148	0221495	15	02	LR	10/16/2003	\$2,000.00	X5021
-------	---------	----	----	----	------------	------------	-------

Complaint	-	-
Conditon	-	-
Cause	- M12	- MONEY BACK
Failed Labor	-	-
Failed Part Nbr	-	-
Tech Comments	-	-
DEL DATE - 10.16.03		

11148	0221495	15	03	LR	10/16/2003	\$500.00	X5026
-------	---------	----	----	----	------------	----------	-------

Complaint	-	-
Conditon	-	-
Cause	- M12	- MONEY BACK
Failed Labor	-	-
Failed Part Nbr	-	-
Tech Comments	-	-
DEL DATE - 10.16.03		

11148	0220073	1	01	PD	9/6/2003	\$88.19	Z7000
-------	---------	---	----	----	----------	---------	-------

Complaint	-	-
Conditon	-	-
Cause	- M10	- PDI
Failed Labor	-	-
Failed Part Nbr	-	-

11148	0220073	1	02	CP	9/6/2003	\$0.00	M5130
-------	---------	---	----	----	----------	--------	-------

Complaint	-	-
Conditon	-	-
Cause	-	-
Failed Labor	-	-
Failed Part Nbr	-	-

END OF CSO HISTORY REPORT

GM Vehicle Inquiry System Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G8AJ52F24Z [REDACTED]
-------	------------------------

VEHICLE INFORMATION

Merchandising Model :		ZAJ69 -2004 ION.2 MIDLEVEL SEDAN			Warranty Start Date :		10/16/2003				
BARS Order Type :		70 - RETAIL - STOCK									
Delivering Dealer :		N/A			Selling Source :		N/A				
					Site Code :		N/A				
					Business Associate Code :		N/A				
Service Contract :		Yes	Branded Title :		No	Warranty Block :		No	PDI Status :		Open

REQUIRED FIELD ACTIONS

Type	Number	Description	Posted Date	Status
RC	03068	FUEL FILTER ASSEMBLY REPLACEMENT	N/A	Closed
RC	03069	BODY CONTROL MODULE (BCM) CALIBRATION UPGRADE FOR RETAINED ACC. POWER (RAP)	N/A	Closed
RC	04095	DRL/TURN SIGNAL BULB REPLACEMENT & DRL JUMPER KIT INSTALLATION	N/A	Closed

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER	10/16/2003	9 miles	10/16/2006	36009 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH	10/16/2003	9 miles	10/16/2009	100009 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	10/16/2003	9 miles	10/16/2011	80009 miles
36/36000 FEDERAL EMISSION	10/16/2003	9 miles	10/16/2006	36009 miles

CLAIM HISTORY

Vehicle Has No Associated Claim History

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2004 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G8AJ52F24Z [REDACTED]
-------	------------------------

CLAIM HISTORY

Vehicle Has No Associated Claim History

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 1998-2004 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) -
[Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G8AJ52F24Z [REDACTED]
-------	------------------------

CLAIM HISTORY

Vehicle Has No Associated Claim History

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 1998-2004 General Motors Corporation. All Rights Reserved.

EAA Inspection Request

Date: 9/1/04

TO: Cathryn Kostaroff

EAA/SPX Field Coordinator

Phone: 313-768-2147

Fax: 313-768-2266

From: Brad Boone

Saturn Corporation

Email: Brad.Boone@gm.com

Phone: 931-489-2930ext.

Fax: 931-486-7901

Mailing Address:

100 Saturn Parkway

PO Box 1500

Springhill, TN 37174

Vehicle Information

VIN#: 1G8AJ52F24Z

Year/Make: 2004/Saturn

Model: ION2 Sedan

Contact's Name: (Name)

Contact's Number:

Vehicle Location: Midway Auto Salvage Auc

101 Highway 404

Duck Hill MS 38925

IF located at a Salvage/Auction Yard:

Ins. Adj. Name: Jerry Studdard

Phone #: 205-944-8334

Claim or Salvage ID #:

Claimant Information

SATURN File #: 1-16864042

Claimant Name:

Claimant Home #:

Claimant Work #:

Claimant Cell #:

Address: (Street Address)

(City, ST ZIP)

Required Actions:

- ☐ Advise Saturn Case Handler via voicemail/email of inspection date.
☐ Repair Estimate Required
☐ Review All Case File information

Please Use Forms:

☐ Accelerator/Throttle	☒ Restraint-SIR/Seatbelts	☐ Seats
☐ Brake/ABS/TC System(s)	☐ Side Impact	☐ Power Sliding Door
☐ Steering/Suspension/Tires&Wheels	☐ Transmission/Transaxle	☐ Hood/Hood Latch
☐ Engine	☐ Fire Collision	☐ OnStar

Special Instructions:

☐ Interview Owner	☒ Vetronix Requested	☒ Obtain Fire/Police Report
☒ Do Not Interview Owner	☒ Contact Saturn After	☒ See Attached

☐ RUSH	☐	☐ PAR Team Manager: _____	☐ Saturn Team Leader: _____
-------------------------------	--------------------------	--	--

EAA Internal Use Only

To: SA:	Date Faxed to SA: _____
From: Cathryn Kostaroff	Due Date: DUE 7 BUSINESS DAYS

EAA SA Use Only

Case Acceptance/Investigation:	☐ YES	☐ NO
Please acknowledge acceptance of this case promptly by phone or fax.		
Report Sent via Email	Date: _____	Date R.O./Police Report, etc. Faxed/Emailed to Saturn: _____

OPLA

DATE TIME TO/FROM MODE MIN/SEC PGS JOB# STATUS
06 07/08 10:46 15867533335 EC-S 02'47" 012 231 OK

EAA Inspection Request

Date: 9/1/04

TO: Cathryn Kostaroff

EAA/SPX Field Coordinator

Phone: 313-768-2147

Fax: 313-768-2266

From: Brad Boone

Saturn Corporation

Email: Brad.Boone@gm.com

Phone: 931-489-2930ext.

Fax: 931-486-7901

Mailing Address:

100 Saturn Parkway

PO Box 1500

Springhill, TN 37174

Vehicle Information

VIN#: 1G8AJ52F24Z

Year/Make: 2004/Saturn

Model: ION2 Sedan

Contact's Name: (Name)

Contact's Number:

Vehicle Location: Midway Auto Salvage Auc

101 Highway 404

Duck Hill MS 38925

IF located at a Salvage/Auction Yard:

Ins. Adj. Name: Jerry Studdard

Phone #: 205-944-8334

Claim or Salvage ID #:

Claimant Information

SATURN File #: 1-16864042

Claimant Name:

Claimant Home #:

Claimant Work #:

Claimant Cell #:

Address: (Street Address)

(City, ST ZIP)

Required Actions:

- ☐ Advise Saturn Case Handler via voicemail/email of inspection date.
☐ Repair Estimate Required
☐ Review All Case File Information

Please Use Forms:

☐ Accelerator/Throttle	☒ Restraint-SIR/Seatbelts	☐ Seats
☐ Brake/ABS/TC System(s)	☐ Side Impact	☐ Power Sliding Door
☐ Steering/Suspension/Tires&Wheels	☐ Transmission/Transaxle	☐ Hood/Hood Latch
☐ Engine	☐ Fire Collision	☐ OnStar

Special Instructions:

☐ Interview Owner	☒ Vetronix Requested	☒ Obtain Fire/Police Report
☒ Do Not Interview Owner	☒ Contact Saturn After	☒ See Attached

☐ RUSH

☐

☐ PAR Team Manager: _____

☐ Saturn Team Leader: _____

To: SA:

Date Faxed to SA: _____

From: Cathryn Kostaroff

Due Date: DUE 7 BUSINESS DAYS

Case Acceptance/Investigation:

☐ YES

☐ NO

Please acknowledge acceptance of this case promptly by phone or fax.

Report Sent via Email

Date: _____

Date R.O./Police Report, etc. Faxed/Emailed to Saturn: _____

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED] Inspection Date: 07/13/2005
 Vehicle Brand: Saturn Model: ION 2
 File # 1-16864042 VIN: 1G8AJ52F24Z [REDACTED]

Mileage at Inspection: Unknown

Inspection Location: Midway Auto Salvage Auction (662) 237-0277
 101 Highway 404, Duck Hill, MS 38925

Additional Inspection: Union County Wrecker
 (662) 534-5273
 402 Carter Avenue
 New Albany, MS 38652

Inspector's phone number: (985) 643-9566

Inspected By: Chris Marton / Engineering Analysis Associates

Section 1 **INSPECTION SUMMARY - RESTRAINT SYSTEM**

Describe the SIR-related allegation below:

- ☒ Non-deployment (the airbag did not deploy and the claimant states that it *should* have)
☐ Inadvertent deployment (the claimant states that the airbag deployed when it *should not* have)
☐ Improper deployment (e.g. the claimant states that the airbag deployed late or only partially)
☐ Inflation or deployment-induced injury (the claimant states the deployment of the airbag caused an injury)
☐ Other Describe: { _____ }
☐ None; Seat belt - related allegation only

NOTE: IF THE SIR ALLEGATION IS NON-DEPLOYMENT OF SIDE IMPACT BAGS, COMPLETE THE ADDENDUM AND ATTACH TO THIS FORM.

Describe the seat belt-related allegation below:

- ☒ Non-activation (the seat belt did not restrain an occupant and the claimant states it *should* have)
☐ Induced injury (the claimant states the seat belt system caused an injury)
☐ Other Describe: { _____ }
☐ None; SIR - related allegation only

Following the inspection, summarize the facts and observations: (Additional cmts may be placed in section 9)

Performed primary inspection at Midway Auto Salvage Auction – at this location was the body and chassis of the Vehicle. Performed secondary inspection at Union County Wrecker Service – at this location was the powertrain. Unable to locate the SDM – the connector has been disconnected and the mounting bolts removed – I was informed by an employee of Union City Wrecker Service (662-534-5273) that a representative of an insurance company for one of the OTR Trucking Companies involved removed and took the SDM from the Saturn the day after the vehicle arrived from the scene – approximately 06/13/2005.

Claimant interview not performed by direction of Saturn inspection Request.

{ _____ }

{ _____ }

{ _____ }

{ _____ }

Section 2 **INTERVIEW - INCIDENT DETAILS**

Provide a complete description of the incident according to the DRIVER / CLAIMANT

Interview mode: ☐ By Telephone ☐ In Person
 Interview date: None

Incident Date and Time: 06/10/2005 @ 5:00pm

Was a police/fire department report obtained? ☒ Yes ☐ No

Provide driver/claimant's description of incident. Describe all collision events; include description of other vehicles involved; describe all objects contacted and the sequence in which they were contacted. (Additional cmts may be placed on pg 9)

Interview not performed by direction of Saturn inspection request.

{ _____ }

{ _____ }

{ _____ }

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED] Inspection Date: 07/13/2005
 Vehicle Brand: Saturn Model: ION 2
 File # 1-16864042 VIN: 1G8AJ52F24Z [REDACTED]

Driver/other occupant's physical description (include name, gender, height, weight, & disabilities):
 {
 {

Describe extent of any injuries to the Driver: {
 {

Describe where other occupants were seated & extent of any injuries: {
 {
 {

Weather conditions & Visibility: { Approximate Temp (°F): {
 Road Surface: ☐ Concrete ☐ Asphalt ☐ Gravel ☐ Crushed rock ☐ Dirt
 Road Condition: ☐ Dry ☐ Wet ☐ Icy ☐ Other: {
 Shoulder ☐ Curb ☐: ☐ Concrete ☐ Asphalt ☐ Gravel ☐ Crushed rock ☐ Dirt
 Shoulder/Curb Condition: ☐ Dry ☐ Wet ☐ Icy ☐ Other: {

Length of Drive Prior to incident:

Total Time (hrs. & mins.): { Distance (miles): {

Estimate of vehicle speed: { mph Source of est. {

Estimated vehicle speed at impact: { mph Source of est. {

(Do not report speed information from Vetronix data)

Describe any evasive action: ☐ Turning ☐ Braking ☐ Accelerating ☐ Other: {

Describe cargo and/or trailer (if any): {

Estimated total weight of cargo & Trailer (lbs): {

Any objects in the road? (rocks, scrap metal, pothole, speed bump, etc.): {

Did the vehicle leave the roadway?: ☐ Yes ☐ No Describe: {

Objects Impacted: {

How was the vehicle transported from the incident site to the present location? ☐ Tow Truck ☐ Flat Bed ☐ Other

Additional comments concerning the incident: {
 {
 {
 {
 {

Section 3**INTERVIEW - VEHICLE HISTORY**

Source of information (name, address, phone number, & relationship if other than claimant):
 {

Comments:
 {
 {

Did the owner purchase the vehicle new? ☐ Yes ☐ No Date ____ Used? ☐ Yes ☐ No Date ____

VEHICLE MODIFICATIONS / ALTERATIONS

Are any vehicle modifications or alterations present, and has any after-market equipment been installed?
 (e.g., objects attached to the steering wheel or instrument panel, controls for disabled persons, cellular phone, modified
 body, electrical components, powertrain, suspension, wheels or tires, after-market seats, etc.) Describe:
 {
 {
 {

VEHICLE REPAIR / SERVICE HISTORY

Confidential GM/PAR

Rev. 04-19-2004

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED]

Inspection Date:

07/13/2005

Vehicle Brand:

Saturn

Model:

ION 2

File #

1-16864042

VIN:

1G8AJ52F24Z [REDACTED]

Prior electrical system service? ☐ No ☐ Yes If yes, describe: {Prior collision repair? ☐ No ☐ Yes If yes, describe: {

Repaired by whom? (name, address, phone) {

Prior SIR and/or seat belt service, repair, or replacement? ☐ No ☐ Yes If yes, describe what was done: {

SIR / airbag and/or seat belt system serviced, repaired, or replaced by whom? (name, address, phone number) {

Any other pertinent vehicle history information (from interview, GM warranty or dealership history files)? ☐ No ☐ Yes

If yes, describe: {

Section 4**VEHICLE INSPECTION - EXTERIOR****PHOTOGRAPH THE EXTERIOR OF THE VEHICLE AS FOLLOWS: VIN PLATE, QUARTER VIEWS FROM LEFT FRONT, RIGHT REAR, ARE REQUIRED AND DOCUMENT FURTHER EXTERIOR DAMAGE WITH MANY PHOTOS.**

FRONT AREA: Describe any damage to the front of the vehicle. Note (and photograph) if the hood is opened, if it contacted or penetrated the windshield, and the location of the contact:
Front windshield no longer with body of vehicle. Engine & transmission have been dislodged from the chassis. Front bumper is peeled forward.

LEFT SIDE EXTERIOR: Describe any damage to the door(s). Note if any door opened as a result of the impact and photograph the latch, striker and the hinges.

Unable to open either two left side doors. Driver's door upper frame has a gap between it and the body. Left quarter panel is gone.

RIGHT SIDE EXTERIOR: Describe any damage to the door(s). Note if any door opened as a result of the impact and photograph the latch, striker and the hinges.

Right side has a measurable maximum crush of 18" at the B-Pillar. The right door is no longer with the vehicle.

REAR AREA: Describe any damage to the rear of the vehicle. Note (and photograph) if the deck lid or rear hatch opened, and note if the spare tire separated from the vehicle.

Trunk/cargo area has been crushed under the backlite area - the backlite is shattered. Neither rear wheels have Any hangover.


ROOF / ROOF STRUCTURE: Describe any damage to the roof of the vehicle. Note if any convertible tops or removable roof panels did not remain attached, and photograph the latches.

Roof is bowed upward - though I did witness the driver of a forklift use the roof to lift and support the vehicle When moving it.

UNDERBODY / FRAME / CHASSIS AREA: The underbody should be carefully inspected and any damage to the underside of the vehicle completely described. Note the condition of the bumpers, frame, suspension, tires, wheels, & engine mount(s)/crossmember. This area of the vehicle is especially important when inadvertent deployment is alleged. Photograph any damage or signs of impact to the underbody.

Right frame rail is pushed outward at the right tip starting from front of passenger compartment.

Unable to lift and inspect the rest of the undercarriage.

STRUCTURAL DEFORMATION - CRUSH AREASRear
RightRear
Left

Rev. 04-19-2004

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED] Inspection Date: 07/13/2005
 Vehicle Brand: **Saturn** Model: **ION 2**
 File # **1-16864042** VIN: **1G8AJ52F24Z** [REDACTED]

Front
RightFront
Left

(Please check all that apply)

Type of impact(s) ☒ Frontal ☒ Side ☒ Rear ☐ Rollover ☐ Other: { _____ }

The following dimensions should be obtained, as they are important to determining the magnitude of the impact to the vehicle. See diagram for definitions of overhang. Do not report "No Change" in this section.

Driver side: Wheelbase (in.) **107** Passenger side: Wheelbase (in.) **79**
 Front overhang (in.) **0** Front overhang (in.) **0**
 Rear overhang (in.) **0** Rear overhang (in.) **0**

Maximum depth of crush: { _____ } Inches - Front { _____ } Inches - Driver side
 25 Inches - Rear 18 Inches - Passenger side
 { _____ } Inches - Roof

Additional comments concerning exterior damage: { _____ }

PRIOR DAMAGE

Describe any existing damage that appears to have been present prior to this incident:

Unable to identify any pre-existing damage

Section 5**VEHICLE INSPECTION - PASSENGER COMPARTMENT**

INTERIOR INSPECTION (Photograph the side view of the steering wheel and column, any damage to the interior and deployed airbags)

Interior reduced in size? ☐ No ☒ Yes
 Intrusion by external object? ☒ No ☐ Yes
 Loose objects inside? ☐ No ☒ Yes
 Cowl deformed? ☐ No ☒ Yes
 Floorpan/toe pan deformed? ☐ No ☒ Yes
 Headliner/visors damaged? ☐ No ☒ Yes
 Inside rear-view mirror damaged? ☐ No ☒ Yes
 Door trim damaged? ☐ No ☒ Yes
 Windshield (W/S) damaged? ☐ No ☒ Yes

W/S perimeter separated from vehicle? ☐ No ☒ Yes
 Steering wheel damage? ☐ No ☒ Yes

Indicate the "clock" position of the damage if present on the steering wheel: **12:00 & 5:00 & 7:00**
 (Note - the top of the steering wheel assembly is 12 o'clock, regardless if the wheel itself is turned)

Tilt steering wheel? ☐ No ☒ Yes
 Steering column displaced? ☐ No ☒ Yes
 Steering column capsule bracket displaced? ☐ No ☐ Yes
 Control Knobs/levers damaged? ☒ No ☐ Yes
 Accelerator / brake pedal(s) deformed? ☒ No ☐ Yes
 Instrument Panel damaged? ☐ No ☒ Yes

Where? **Passenger side pushed in 18 at B-Pillar**

Describe: { _____ }
 Describe: **Various trim and personal items loose**
 Describe: **Cowl is no longer attached, unable to view**
 Describe: **Right toe pan/floorpan pushed in and up**
 Describe: **Visors are no longer attached**
 Describe: **Unable to locate inside rearview mirror**
 Describe: **LF trim gone - LR trim damaged**

☒ Cracked ☒ Broken (Torn Inner Layer)
☐ Cracked/broken (By Occupant Contact)

100% - Approximate % of perimeter separation

☒ Rim ☐ Hub Describe: **Full rim distortion**

Position: ☐ Low ☒ Mid ☐ High

Describe: **Column dislodged from steering linkage**
 Describe: **Unknown - Unable to access and inspect**
 Describe: **Column controls intact**

Describe: { _____ }

Describe: **Unable to locate instrument panel.**

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED]

Inspection Date:

07/13/2005

Vehicle Brand:

Saturn

Model:

ION 2

File #

1-16864042

VIN:

1G8AJ52F24Z [REDACTED]

Lower I/P - knee bolster damaged? ☐ No ☒ Yes Describe: **Both knee bolsters dislodged**
 Driver Frontal airbag deployed? ☒ No ☐ Yes ☐ Not equipped If "Yes", take photos of any witness marks.
 Passenger Frontal airbag deployed? ☐ No ☒ Yes ☐ Not equipped If "Yes", take photos of any witness marks.
 Passenger Frontal airbag Suppression switch (if equipped) On ☐ Off ☐ Photograph the switch.
 Driver side-airbag deployed? ☐ No ☐ Yes ☒ Not equipped If "Yes", take photos of any witness marks.
 Passenger side-airbag deployed? ☐ No ☐ Yes ☒ Not equipped If "Yes", take photos of any witness marks.
 Roof Rail airbag deployed? ☐ No ☐ Yes ☒ Not equipped If "Yes", take photos of any witness marks.

Additional comments concerning any interior damage:

NOTE - Passenger frontal airbag was not found attached to the vehicle - it was found in a pile of parts located at Union County Wrecker Service - The airbag assembly was no longer attached to the vehicle (loose on the ground in open weather) or bracket and there were no wires connected to it.

SEAT INSPECTION (Photograph damaged areas)Type of Front Seat: ☒ Bucket ☐ Bench ☐ 50/50 Split Bench ☐ 60/40 Split Bench**DRIVER'S SEAT INFORMATION**

Seat damaged? ☐ No ☒ Yes ☐ Cushion ☒ Backrest
 Seat position? ☐ Forward ☒ Middle ☐ Rearward ☒ Tilted/Reclined
 Seat back struck by rear occupant? ☒ No ☐ Yes Describe: {

RIGHT FRONT PASSENGER SEAT INFORMATION

Seat damaged? ☐ No ☒ Yes ☒ Cushion ☒ Backrest
 Seat position? ☐ Forward ☒ Middle ☐ Rearward ☐ Tilted/Reclined
 Seat back struck by rear occupant? ☒ No ☐ Yes Describe: {

Additional comments concerning any seat damage (front or rear): **Passenger front seat position has been Twisted and compromised by a right B-pillar crush depth of 18".**

WINDOW INSPECTION (Note window condition and any unusual conditions observed)

Both left door glasses still in tact - all other glass has been damaged - Front windshield perimeter has been Separated 100%. Backlite is shattered. Two right side door glasses gone.

Section 6

RESTRAINT SYSTEM INSPECTION - SIR / Airbag**If the vehicle is not equipped with airbags, SKIP THIS SECTION****Note - Do Not "Clear Codes" from the on-board computer(s)****Describe the SIR-related allegation below:**

- ☒ Non-deployment (the airbag did not deploy and the claimant states that it *should* have)
☐ Inadvertent deployment (the claimant states that the airbag deployed when it *should not* have)
☐ Improper deployment (e.g. the claimant states that the airbag deployed late or only partially)
☐ Inflation or deployment-induced injury (the claimant states the deployment of the airbag caused an injury)
☐ Other Describe: {

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED]

Inspection Date:

07/13/2005

Vehicle Brand:

Saturn

Model:

ION 2

File #

1-16864042

VIN:

1G8AJ52F24Z [REDACTED]

☐ None; Seat belt - related allegation only**Alleged SIR Unit(s):**

☒ Driver Frontal ☒ Passenger Frontal ☐ Driver Side (door/seat) ☐ Passenger Side (door/seat)
☐ Roof rail airbag ☐ Other Describe: {

Which SIR(s) deployed?

☐ Driver Frontal ☒ Passenger Frontal ☐ Driver Side (door/seat) ☐ Passenger Side (door/seat)
☐ Roof rail airbag ☐ None

Was Vetronix CDR used? ☐ Yes ☒ No

Describe airbag light functional test results.

Unable to perform airbag light inspection – Instrument cluster**Unable to be viewed and no keys.**Describe any diagnostic (current or history) trouble codes (if Tech 2 was used): **Unable to perform tests – no keys.**

Describe any evidence that the passenger compartment may have been flooded or the SDM/DERM has incurred any damage due to moisture. (Inspect the carpet, floor pan for moisture and SDM/DERM electrical connector male and female ends for signs of corrosion.)
No water damage observed – though vehicle is not weather secure and all precipitation is getting into vehicle.

If any airbag(s) deployed, was the:**DRIVER AIRBAG**Bag material cut/torn? ☐ No ☐ Yes

Describe: {

Transfer marks present - clothing, makeup, etc.? ☐ No ☐ Yes

Describe: {

PASSENGER AIRBAGBag material cut/torn? ☒ No ☐ Yes

Describe: {

Transfer marks present - clothing, makeup, etc.? ☒ No ☐ Yes

Describe: {

DRIVER SIDE AIRBAGBag material cut/torn? ☐ No ☐ Yes

Describe: {

Transfer marks present - clothing, makeup, etc.? ☐ No ☐ Yes

Describe: {

PASSENGER SIDE AIRBAGBag material cut/torn? ☐ No ☐ Yes

Describe: {

Transfer marks present - clothing, makeup, etc.? ☐ No ☐ Yes

Describe: {

ROOF RAIL AIRBAGBag material cut/torn? ☐ No ☐ Yes

Describe: {

Transfer marks present - clothing, makeup, etc.? ☐ No ☐ Yes

Describe: {

PHOTOGRAPH THE STEERING WHEELWas the steering wheel damaged? ☐ No ☒ YesDescribe: **Rim bent forward**Were transfer marks present ☒ No ☐ Yes

Describe: {

- clothing, makeup, etc.?

INSPECT SIR WIRING, SENSORSSIR Wiring damaged? ☒ No ☐ Yes

Describe: {

SIR Sensors damaged or disconnected? ☐ No ☐ Yes

Describe: {

SIR Inflator module(s) disconnected? ☐ No ☒ YesDescribe: **Module removed prior to inspection**

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED] Inspection Date: 07/13/2005
 Vehicle Brand: Saturn Model: ION 2
 File #: 1-16864042 VIN: 1G8AJ52F24Z [REDACTED]

DERM / SDM Download

- Obtain either DERM (Diagnostic Energy Reserve Module) or SDM (Sensing and Diagnostic Module) downloads.
- OBTAIN DERM / SDM DOWNLOAD FOR ALL SEAT BELT AND/OR SIR-RELATED ALLEGATIONS
- DO NOT CLEAR CODES PRIOR TO OBTAINING THE DOWNLOAD
- DO NOT CYCLE IGNITION KEY ON/OFF PRIOR TO OBTAINING THE DOWNLOAD

Download Available? ☐ Yes ☒ No If NO, describe reason: **Unable to locate SDM**
 Download obtained from: ☐ ALDL / DLC ☐ Direct from the module (using adapter cables with the Vetronix CDR)
 Download obtained using: ☐ Vetronix CDR (Save the file as a CDR file and a PDF type file)

If the download was obtained directly from the module, was the module removed from the vehicle? ☐ Yes ☐ No
 If removed from the vehicle, describe the conditions under which the module was mounted when the download was obtained.

Additional comments concerning the airbags: **Unable to locate airbag SDM. I was informed by an employee of Union County Wrecker Service that a representative of an insurance company for one or more of the OTR trucking Companies removed and took the SDM on or about 6/13/2005.**

Section 7 RESTRAINT SYSTEM INSPECTION - Seat Belts**Describe the seat belt-related allegation below:**

- ☒ Non-activation (the seat belt did not restrain an occupant and the claimant states it *should* have)
☐ Induced injury (the claimant states the seat belt system caused an injury)
☐ Other Describe: {
☐ None; SIR - related allegation only **THE SEAT BELTS SHOULD BE INSPECTED IF A COLLISION OCCURRED, AND SHOULD BE COMPLETED FOR THE SEAT BELT(S) POSITIONS FOR ALL OCCUPANTS AT THE TIME OF COLLISION.**

Location of seat belt to be inspected?

☐ Other: { ☒ Driver ☐ Center front ☒ Right front
☐ Driver's side rear ☐ Center rear ☐ Right rear

Is the seat belt fully retracted? ☐ Yes ☒ No **IF THE ANSWER IS NO, DO NOT DISTURB BELTS AT THIS TIME.**
 - Secure webbing, measure length, photograph **Bottom Strap 47.5 & Top**

Strap 26 Inches

Turn on ignition, observe seat belt light. On? ☐ Yes ☐ No
 Buckle driver's seat belt. Seat belt light on? ☐ Yes ☐ No

Photograph:

- The overall belt assembly
- All visible components of the seat belt system and anchor points
- Identify and photograph the following items:

If so equipped, are the pretensioners activated (deployed)? ☐ No ☒ Yes
 Does the webbing spool in and out freely? If no, which one does not? ☒ No ☐ Yes
☐ Lap ☐ Shoulder ☒ Both Note: Do not use excessive force (Use less than 5 pounds of pressure)
 Marks, cuts or debris on shoulder and lap belt webbing? ☐ No ☒ Yes
 (If there are any of the above found, use photographs to document the position of the anomaly using a ruler or scale to show location relative to the buckle.)
 Webbing energy management loops (if equipped) - stitches pulled free, ☒ No ☐ Yes

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED]

Inspection Date:

07/13/2005

Vehicle Brand:

Saturn

Model:

ION 2

File #

1-16864042

VIN:

1G8AJ52F24Z [REDACTED]

unfolded, replacement/warning label exposed?

Tack stitch separated from plastic sleeve?

Seat belt webbing cut? (If yes, photograph and record length of pieces)

47.5 & 26

Guide loop assembly - striations, bent, or deformed?

Guide loop adjuster functional (if equipped)?

Buckle and latch functional together (latched)?

Buckle condition (worn, or foreign material present)?

Plastic covers and/or guides damaged?

Does the seat belt return to the stowed position?

Any components missing?

Any post-collision damage present (ex. Rescue workers)?

X No ☐ Yes

Inches

X No ☐ YesX No ☐ Yes☐ No ☐ Yes☐ No ☐ Yes☐ No X YesX No ☐ YesX No ☐ Yes☐ No X Yes**If possible, perform a dynamic "panic-stop" type test with the vehicle.**Do the retractors on the belt being inspected appear to lock and hold properly? ☐ No ☐ YesIf vehicle is not driveable, jerk each belt rapidly. (Note: Some inertia-activated retractors will not lock on this test.) Did the belt(s) lock? ☐ Yes ☐ No**Unable to perform test.**Additional comments concerning seat belts: **Unable to test panic-stop features - Left front seat belt is still buckled & Unable to disconnect. Right front seat belt has been cut and latch is still in the buckle. The release button has been shattered.****Section 8****SITE INSPECTION**Carefully consider the facts in the case and then document the basis of your decision concerning whether to inspect the site of the incident. General Motors prefers site inspections as noted on the assignment sheet. If an inspection of the site is done, it is important to move quickly so that valuable information is not lost.**Site not inspected - conditions at the site are not similar to the time of the incident.****SITE INSPECTION - PERFORM THE FOLLOWING IF ADDITIONAL INFORMATION MAY BE FOUND:**

- Check the incident scene for tire marks, gouges in the pavement, debris, or any other marks. Measure location and photograph.
- Identify evidence of whether the vehicle left the road prior to, during, or after the incident. Document all locations, distances, etc...
- Identify evidence & photograph any object struck by the vehicle on or off the road prior to, during, or after incident.
- Inspect roadway & shoulder surfaces in the area of the incident site for telltale signs of loss of control, excessive speed, severe braking, etc.

Photograph the scene and any property involved.**Comments:**

RESTRAINT SYSTEMS SIR / SEAT BELTS

Customer's Name: [REDACTED] Inspection Date: 07/13/2005
 Vehicle Brand: Saturn Model: ION 2
 File # 1-16864042 VIN: 1G8AJ52F24Z [REDACTED]

Section 9**Comment Overflow Sheet**

Please use this page if needed for additional comments from the inspection form. Please note the section and area the comments are continued from prior to each comment.

Performed initial vehicle inspection at Midway Auto Salvage Auction – at this location I found the remains of the Body. I was informed that all loose parts had not been transported to the salvage yard and they were located At Union County Wrecker Service. Upon arrival at Union County Wrecker Service I was shown a pile of parts and Debris and was told that they were from the scene of the accident.

Section 10**Other Report Information**

Check here if there was evidence of a "Fire-Related" event.

According to NHTSA, "fire" means combustion or burning of material in or from a vehicle as evidenced by flame. The term also includes, but is not limited to, thermal events and fire-related phenomena such as smoke, sparks or smoldering, but does not include events and phenomena associated with a normally functioning vehicle, such as combustion of fuel within an engine or exhaust from an engine.

Attachments: (Check all that apply)

X Photographs ☐ Data Downloads X Other Records

**PRODUCT ALLEGATION RESOLUTION
PRELIMINARY INSPECTION
FIELD PHOTOGRAPHIC NOTES**

Customer's Name: [REDACTED] Inspection Date: 07/13/2005
Vehicle Brand: Saturn Model: ION 2
File # 1-16864042 VIN: 1G8AJ52F24Z [REDACTED]

Inspector Chris Marton / Engineering Analysis Associates

Number of Rolls 3

Roll Number 1 – Order ID # 0856616 – Twin Check ID # [REDACTED]

Neg. # Description

0. _____
1. Salvage Yard Identification Label
2. VIN Plate
3. Exterior – Left
4. Exterior – Left Front Quarter
5. Exterior – Front
6. Exterior – Right Front Quarter
7. Exterior – Right
8. Exterior – Right Rear Quarter
9. Exterior – Rear
10. Exterior – Close-Up Left Corner of Engine Compartment, Cowl, & Left Fender
11. Exterior – Close-Up of Front – Shows Missing Powertrain
12. Exterior – Close-Up of Right Front Frame Rail – Shows Angle of Bend
13. Exterior – Right – Shows Damage to Cowl and Passenger Compartment Area
14. Exterior/Interior – From What Would be the Right Front Door Opening
15. Interior – Shows Front Interior Passenger Compartment
16. Interior – Front Center Console Area
17. Interior – Right Front Seat
18. Steering Wheel – Right Rim View
19. Engine Compartment – Close-Up
20. Interior – Driver's Seat – Overall Above View
21. Interior – Passenger Seat – Overall Above View
22. Exterior – Left Rear Quarter
23. Exterior – Above View of Backlite & Rear Roof
24. Exterior – Left View of Backlite
25. _____
26. _____
27. _____
28. _____
29. _____
30. _____
31. _____
32. _____
33. _____
34. _____
35. _____
36. _____
37. _____






















































**PRODUCT ALLEGATION RESOLUTION
PRELIMINARY INSPECTION
FIELD PHOTOGRAPHIC NOTES**

Customer's Name: [REDACTED] Inspection Date: 07/13/2005
Vehicle Brand: Saturn Model: ION 2
File # 1-16864042 VIN: 1G8AJ52F24Z [REDACTED]

Inspector: Chris Marton / Engineering Analysis Associates

Number of Rolls 3

Roll Number 2 – Order ID # 0856617 – Twin Check ID # [REDACTED]

<u>Neg.#</u>	<u>Description</u>
0	_____
1.	_____
2.	<u>Interior – Center Console – Parking Brake Handle & SDM Connector</u>
3.	<u>Seat Belt – Right Front – Shows Cut Webbing</u>
4.	<u>Seat Belt – Right Front - Retractor</u>
5.	<u>Seat Belt – Right Front - Label</u>
6.	<u>Seat – Left Front – Seat Back Recliner Angle</u>
7.	<u>SDM Connector & Red Security Pin – Shows Security Pin Still In Tact</u>
8.	<u>Seat – Right Front – Seat Bottom Angle</u>
9.	<u>Seat – Right Front – Seat Back Angle</u>
10.	<u>Seat Belt- Right Front – Measurement of Webbing</u>
11.	<u>Seat Belt – Right Front – Measurement of Webbing</u>
12.	<u>Wheel – Right Front – Shows Damage to Right Front Rim & Separated Right Front Axle</u>
13.	<u>Exterior – Right Front Lateral View – Close-Up</u>
14.	<u>Exterior – Left Front Lateral View</u>
15.	<u>Exterior – Right Front – Lateral</u>
16.	<u>Exterior – Right Rear Lateral</u>
17.	<u>Exterior – Left Rear Lateral</u>
18.	<u>Engine Compartment - PDC</u>
19.	<u>Exterior – Left Rear – Shows Left Rear Tire & Suspension</u>
20.	<u>Seat Belt – Right Front - Adjuster</u>
21.	<u>Seat Belt – Left Front - Overall</u>
22.	<u>Interior – Right Front Floor Board</u>
23.	<u>Frame – Right Front Frame Rail</u>
24.	<u>Engine Compartment – Right Lateral View of Cowl Area</u>
25.	_____
26.	_____
27.	_____
28.	_____
29.	_____
30.	_____
31.	_____
32.	_____
33.	_____
34.	_____
35.	_____
36.	_____
37.	_____




















































**PRODUCT ALLEGATION RESOLUTION
PRELIMINARY INSPECTION
FIELD PHOTOGRAPHIC NOTES**

Customer's Name: [REDACTED]

Inspection Date: 07/13/2005

Vehicle Brand:

Saturn

Model:

ION 2

File #

1-16864042

VIN:

1G8AJ52F24Z [REDACTED]

Inspector: Chris Marton / Engineering Analysis Associates


Number of Rolls 3


Roll Number 3 Order ID # 0856618 – Twin Check ID # [REDACTED]

<u>Neg.#</u>	<u>Description</u>
0	
1.	<u>Transmission/Engine Assembly – Found in Pile at Union County Wrecker Service</u>
2.	<u>Transmission/Engine Assembly – Found in Pile at Union County Wrecker Service</u>
3.	<u>Transmission Part Numbers – Found in Pile at Union County Wrecker Service</u>
4.	<u>Engine Head Assembly – Found in Pile at Union County Wrecker Service</u>
5.	<u>Pile of Debris & Parts Picked Up By Union County Wrecker Service (662-534-5273) at the Accident Scene</u>
6.	<u>Pile of Debris & Parts Picked Up By Union County Wrecker Service (662-534-5273) at the Accident Scene</u>
7.	<u>Pile of Debris & Parts Picked Up By Union County Wrecker Service at the Accident Scene – Includes Hood Latch</u>
8.	<u>MFD Tire Loading Label – Found at Union City Wrecker Service</u>
9.	<u>Air Bag – Passenger Air Bag Material – Found in Pile at Union County Wrecker Service</u>
10.	<u>Suspension Parts & Fuel Filler Tube – Found in Pile at Union County Wrecker Service</u>
11.	<u>Windshield – Found in Pile at Union County Wrecker Service</u>
12.	<u>Module Found In Debris Pile at Union County Wrecker Service</u>
13.	<u>Transmission/Engine Assembly – Found in Pile at Union County Wrecker Service</u>
14.	<u>Engine Assembly – Top – Found in Pile at Union County Wrecker Service</u>
15.	<u>Air Bag – Passenger – Found in Pile at Union County Wrecker Service</u>
16.	<u>Air Bag Assembly – Passenger – Found in Pile at Union County Wrecker Service</u>
17.	<u>Air Bag Assembly – Passenger – Found in Pile at Union County Wrecker Service</u>
18.	_____
19.	_____
20.	_____
21.	_____
22.	_____
23.	_____
24.	_____
25.	_____
26.	_____
27.	_____
28.	_____
29.	_____
30.	_____
31.	_____
32.	_____
33.	_____
34.	_____
35.	_____
36.	_____
37.	_____

















TIRE-LOADING INFORMATION

OCCUPANTS		VEHICLE CAPACITY WT.	
FRT.	CTR. RD.	TOTAL	
		LBS	KG
2	6	5	899
			408

MAXIMUM LOADING AT GVWR:
SAME AS VEHICLE CAPACITY WEIGHT

1G8AJ52F24Z [REDACTED]


MODEL: 2R069

	TIRE	SIZE	SPEED	RATING	COLD TIRE PRESSURE PSI/KPA
FRONT	P195	60R15			38/210
REAR	P195	60R15			38/210
SPARE	T115	70R14			50/420


IF TIRES ARE HOT, ADD 4 PSI (28 KPA)
SEE OWNER'S MANUAL FOR ADDITIONAL
INFORMATION



















STATE OF MISSISSIPPI
UNIFORM CRASH REPORT

Agency Number

7303

Agency Case Number

(b) (6)

Page 01 of 10

Agency Name New Albany Police Dept.						G1. County 73	G2. Status Code 2 C P U
G3. Reported Date (MM/DD/YYYY) 06/10/2005		G4. Reported Time (2400) 1717		G5. Officer Time Arrival Time (2400) 1721		10-24 Time (2400) 1929	
G6. Vehicles 04		G7. Killed 01		G8. Injured 02			
G9. Address Number 078				G10. Street Name South Central Ave		G11. Hwy/County Road # 078	
G12. Int. Y N				G14. Distance 200.00		G15. Direction N E S W	
G16. Intersecting Street Name South Central Ave				G17. Int. Hwy/County Road #			
G18. City Name New Albany				G19. Latitude N 34 28.812			
				G20. Longitude W 089 00.914			
Crash with CMV in road Reverses slow or stop Rear end turn Left turn same roadway Left turn cross traffic Right turn cross traffic Head on Slowswipe Angle Blind spot		Non-Crash in Road Overtake Jackknife Fall from vehicle Other Crash of MV in road with Pedestrian Parked Vehicle Train Bicyclist Duck Animal (other than deer)		Fixed Object Bridge/Culvert Embankment/Ditch/Cutb Guardrail/Modem Barrier Trees Utility pole/light support Other fixed object Sign Post Signal standard Non-fixed Object Building/Other Structure Mant. Equip. - Not Moving Mant. Equip. - Moving Other non-fixed object		G22. Crash Location Roadway Off-Roadway Median Roadside Shoulder Parking Lot Gore	
G23. Intersection Type None Four-way Inter T-Intersection Crossover Driveway Five-point or more Off Ramp On Ramp Path/Trail RR Xing Traffic Circle/Round Y-Intersection		G24. Roadway System City Street State Highway U.S. Highway County Road Parking Lot/Private Drive Interstate Off Road State Park		G25. Workzone Relationship Not Workzone Related Within Construction Zone Advance Warning Area		G26. Workzone Type (2) None Intermittent or Moving Work Lane Closure Lane Shift/Crossover Shoulder/Median Work Utility	
G27. Light Condition Daylight Dark-Lit Dark-Unlit Dawn Dusk		G28. Road Condition Dry Wet Water Sand/Mud/Dirt/Oil/Gravel Ice Slush Snow		G29. Weather/Condition (2) Clear Rain Cloudy High winds Blown Debris Fog/Smog/Smoke Sleet/Hail Snow		G30. Witness(es) First Name MI Last Name Address City State Zip Code Sex M F Age	
G31. First Name MI Last Name Address City State Zip Code Sex M F Age		G32. First Name MI Last Name Address City State Zip Code Sex M F Age		G33. First Name MI Last Name Address City State Zip Code Sex M F Age		G34. First Name MI Last Name Address City State Zip Code Sex M F Age	
G35. Investigating Officer Name (Please Print) 04 Clay Keener				G36. Officer Signature Clay Keener			
G37. Reviewing Badge Number 04		G38. Reviewing Officer Initials Clay Keener 04		G39. Photos Taken Y N		G40. Photographer and Badge # Clay Keener 04	

4479140593

PAGE 2

3625341037

JUL 11 2005 (MON) 11:17

TA000085974