


EWR D&I ANNOTATION



FAN-000001L093001DP119-9585

Artemis # : 000001L093001DP119**Record Created Date :** 09/13/2010**Printed Date :** 10/27/2010**Description :**

DI10-006. SEQ ID 119. 2009 Q3. VEHICLE IN QUESTION IS A 2006 CHEVY COBALT. THE DRIVER WAS PARKED ON THE SIDE OF THE STREET WAITING TO PICK UP SOMEONE. THE CAR WAS RUNNING AND IT SMELLED LIKE A TIRE BURNING. THE AIR BAG THEN DEPLOYED AND HORN WENT OFF WITHOUT A REASON. THERE WAS DAMAGE TO THE STEERING WHEEL FROM THE AIR BAG. THE SIR COIL SHORTED AND MADE THE AIR BAG DEPLOY. THERE WAS NO POLICE REPORT FILED. THERE ARE NO SIMILAR ISSUES IN ARTEMIS. *RM



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

July 6, 2010

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-006

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 6, 12, 13, 14, 15, 16, 17, 46, 47, 50, 60, 61, 93, 103, 105, 106, 115, 119, 129, 132, 135, 147, 161, 171, 185, 186, 187, 188, 189, 190, 192, 193, 194, 215, 231, 239, 242, 271, 278, 281, 297, 321, 326, 342, 344, 349, 350, 352, 355, 375, 384, 386, 450, 451, 452, 462, 467, 471, 478, 495	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CRF 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **August 6, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

AUG 18 2010

August 17, 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-006

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated July 6th, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2009.

GM's response is comprised of 62 disks for the incidents that are the subject of DI10-006.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 6 48649735-678866 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 6 48649735-678866_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-006
6 48649735-678866
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 6 48649735-678866 **_01_001** - is the first document responsive to Inquiry no. 1.
 6 48649735-678866 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI10-006, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(60 Vehicles from the Light Vehicle Template)			
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)		TYPE
6	5GAER23D19J		NISM
12	1G4HD57267U		NISM
13	1G4HD57287U		NISM
14	1G4HE57Y48U		NISM
15	1G4HD57278U		NISM
16	1G4HD57218U		NISM
17	1G4HD57248U		NISM
46	1G6DT57V380		NISM
47	1G6DF577880		NISM
50	1G6DS57V890		NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
60	1G6KD57Y17U [REDACTED]	NISM
61	1G6KD57947U [REDACTED]	NISM
93	KL1TJ58Y05B [REDACTED]	NISM
103	KL1TD66E09B [REDACTED]	NISM
105	KL1TD56E19B [REDACTED]	NISM
106	2G1FC1EV0A9 [REDACTED]	NISM
115	1G1AK55F267 [REDACTED]	PAR
119	1G1AK15F967 [REDACTED]	NISM
129	1G1AK55F677 [REDACTED]	NISM
132	1G1AK58F887 [REDACTED]	NISM
135	1G1AM58B187 [REDACTED]	NISM
147	1G1YY26W185 [REDACTED]	LIT
161	2CNFLGEYXA6 [REDACTED]	NISM
171	3GNDA13D57S [REDACTED]	NISM
185	2G1WF52E349 [REDACTED]	NISM
186	2G1WF52E659 [REDACTED]	NISM
187	2G1WH52K359 [REDACTED]	NISM
188	2G1WF52E859 [REDACTED]	NISM
189	2G1WF52E659 [REDACTED]	NISM
190	2G1WF52E359 [REDACTED]	NISM
192	2G1WC581469 [REDACTED]	NISM
193	2G1WB58K669 [REDACTED]	NISM
194	2G1WB58K069 [REDACTED]	NISM
215	2G1WB5ENXA1 [REDACTED]	NISM
231	1G1ZG57BX84 [REDACTED]	NISM
239	1G1ZH57B69F [REDACTED]	NISM
242	1G1ZK57749F [REDACTED]	NISM
271	2GCEK19T541 [REDACTED]	NISM
278	1GCEK19C47Z [REDACTED]	NISM
281	2GCEK19J171 [REDACTED]	NISM
297	1GCHK73K79F [REDACTED]	NISM
321	1GNEC13T75R [REDACTED]	LIT
326	2CNBJ13C036 [REDACTED]	NISM
342	1GNDD13S142 [REDACTED]	NISM
344	1GNDD13S042 [REDACTED]	NISM
349	1GNDD13S852 [REDACTED]	NISM
350	1GNDD13S352 [REDACTED]	NISM
352	1GNDD13S362 [REDACTED]	NISM
355	1GNDS13SX62 [REDACTED]	NISM
375	1GNDV23178D [REDACTED]	PAR
384	1GKER137X8J [REDACTED]	NISM
386	1GTDS43E888 [REDACTED]	LIT
450	1G2AL18H797 [REDACTED]	NISM
451	1G2AS18H197 [REDACTED]	NISM
452	1G2AS18H297 [REDACTED]	NISM
462	1G2ZH57N784 [REDACTED]	NISM
467	1G2ZG57N994 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
471	1G2ZM577194 [REDACTED]	PAR
478	2G2WP552061 [REDACTED]	LIT
495	1G8ZS57B49F [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 62 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

982.2(b)(1)

FOR COURT USE ONLY

ATTORNEY OR PARTY WITHOUT ATTORNEY (Name, state the number, and address)
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POWAY, CALIFORNIA 91766
 TELEPHONE NO: 909-469-5127 FAX NO: 909-469-5126

ATTORNEY FOR PLAINTIFF'S

VENDOR NAME OF COURT: SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COURT

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET

Complex Case Designation
☐ Counter ☐ Joinder
 Filed with first appearance by defendant (Cal. Rules of Court, rule 1811)

CASE NUMBER

ASSIGNED JUDGE:

Please complete all five (5) items below.

1. Check one box below for the case type that best describes this case:

Auto Tort
☒ Auto (22)
 Other PIP/NOV (Personal Injury/Property Damage/Wrongful Death) Tort
☐ Asbestos (24)
☐ Product liability (24)
☐ Medical malpractice (40)
☐ Other PIP/NOV (23)
 Non-PIP/NOV (Other) Tort
☐ Business tort/unfair business practice (27)
☐ Civil rights (e.g., discrimination, false arrest) (24)
☐ Detention (e.g., gender, race) (13)
☐ Fraud (16)
☐ Intellectual property (12)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PIP/NOV tort (35)
☐ Employment
☐ Wrongful termination (35)

Contract
☐ Breach of contract/warranty (26)
☐ Collections (e.g., money owed, open bank accounts) (29)
☐ Insurance coverage (18)
☐ Other contract (37)
 Real Property
☐ Eminent domain/expropriation/condemnation (14)
☐ Wrongful eviction (33)
☐ Owner real property (e.g., quiet title) (20)
 Unlawful Detainer
☐ Commercial (21)
☐ Residential (32)
☐ Drugs (24)
 Judicial Review
☐ Asset forfeiture (56)
☐ Probation/parole violation (11)

Writ of mandamus (22)
 Other judicial review (39)
 Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 1800-1812)
☐ Arbitration/Trade regulation (23)
☐ Construction defect (16)
☐ Claims involving mass tort (24)

Next Image
 Previous Image
 Next page Ctrl+PgDn
 Previous page Ctrl+PgUp
 Full screen image Ctrl+F11
 Slide show F10
 Fit Scale to fit F5
 1:2 Scale 50% F6
 1:1 Scale 100% F7
 2:1 Scale 200% F8

Rotate left Ctrl+Alt+L
 Rotate right Ctrl+Alt+R
 Rotate by 180°
 Copy to clipboard
 Copy file to... Ctrl+C
 Move file to... Ctrl+X
 Rename file... F2
 Delete file... Del
 EXIF Image Information...
 Preferences... Ctrl+R

2. This case ☒ is ☐ is not complex under rule 1803 of the California Rules requiring exceptional judicial management.

a. ☒ Large number of separately represented parties d. ☒ Large number of
 b. ☒ Extensive motion practice raising difficult or novel issues that will be time consuming to resolve e. ☐ Coordination and
 c. ☒ Substantial amount of documentary evidence f. ☐ Substantial post

3. Type of remedies sought (check all that apply):
 a. ☒ monetary b. ☐ nonmonetary, declaratory or injunctive relief c. ☐

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., S/B# 147836
 (TYPE OR PRINT NAME)

NOTICE
 Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (ex
 under the Probate, Family, or Welfare and Institutions Code) (Cal. Rules of Court, rule
 1800).
 • If this case is complex under rule 1800 it req. of the California Rules of Court, you must
 other parties to the action or proceeding.
 • Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

Form adopted by the Judicial Branch of the State of California
 6807001 (Rev. January 1, 2006)

CIVIL CASE COVER SHEET

Step 7: Next File (Image)

Step 7: Next Page

Step 8: Scale Image

Step 7: Image Properties

DI10-006
119 36453227 – 677891
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	PAR- Inadvertent Airbag
Address	City Dilley	Involved Dir	Brown Chevrolet Company Inc	Safety	Yes
State TX ZipCd	Con Acct	Source	Phone	Updated	8/28/2009 04:43:22 PM
Serial #VIN 1G1AK15F907	Model Year 2006	Priority	Medium License #	Owner	RJOHNS36
Make Chevrolet	Warr. Start 06/23/2005	Status	Open	Opened	8/27/2009 03:02:11 PM
Model Cobalt	Mileage 72000	Sub-Status	Satisfied	Closed	
Abstract (Pending ESIS) Restraints - (SIR) - Driver Front (Inadvertent)					
Customer Description This is a BRC PAR File. Please do not Assume. DO NOT ADVISE. Forward all inquiries to Renea Soto @ ext 11072					

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond	Fire Report#	Police Report#
Owner	8/26/2009 03:30:37 PM	Y	0	3	Asphalt	Dry	N/A	N/A
Driver Last Name	Driver First Name	Height	DOR	Disabilities				
		57		None				
Insurance Agent Last Name	Insurance Agent First Name	Phone	Insurance Agency					
Patterson	Jimmy		Farmers Insurance					
Incident Loc	Southbound on the side of Herman St	Incident Desc	Customer was Southbound on the side of Herman St waiting to pick up her children, she left the car on and smelt like a fire was burning, when the kids were putting on their sit belts, and after i spoke with my husband on my phone, the airbag inflated without a reason. The horn just started					
Component	Air bag	Damage Desc	Steering wheel					
Vehicle Loc	Brown Chevrolet 340 IH 35 SOUTH DEVINE, TX 78016-8016 830-665-4435	Add'l Info						
Emgcy Svc Names	N/A	Main Loc	Walmart					

PAR Detail

Collision	Non Collision	Y	Property Damage	N	Thermal Evt	N	Spec Equip	New Tires/Rims, Fuel Saver Added, Stereo (The tires/rims and stereo were recently purchased about month ago)
Vehicle Speed	0		Weather Condition	Clear & Dry			Prop Owner	n/a
Last Service Date			Loc Last Service				Property Location	n/a
Veh Est Repair Cost	\$0.00		Spec Equip Installer	Tires -unknown, Stereo - son, Fuel Saver -unknown			Prop Damage Description	n/a
Primary Veh Use	Personal		Inspection Type	Restraint System SIR/Seat Belt			Inspected By	Inspection Not Performed
Veh Damage Description	Steering Wheel						Explain Other	File Forward to ESIS; Injuries
								Inspection Date/Time

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seat Belt
Injury Description		Medical Rpt#		Treatment Location		Treated By
Burning Sensation on Right Arm/Hand from the Wrist up to elbow. Bruised Palm/Wrist. Lump on Left Arm		N/A		Community General Hospital		Dr ER
Street Address			City	State	Zip Code	
			Diley	TX		

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/31/2009 03:14:19 PM	RJOHNS36	RJOHNS36	Scheduled Follow-up	Other	Scheduled Alarm		ESIS Pick up
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
ESIS Pick up							

Escalation Date: 8/31/09
10 business day: 9/11/09

Renea Soto/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/31/2009 03:11:16 PM	MARQUEM O	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Assign to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Injuries							

Monica Marquez/BRC/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/31/2009 09:10:03 AM	KINZERTH	MARQUEMO	Notify CRM		Done	8/31/2009 03:11:14 PM	ESIS - Injuries
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 04:46:52 PM	RJOHNS36	KINZERTH	BRC PAR	ESIS- Injuries	Done	8/31/2009 09:10:02 AM	Escalation to ESIS -Injuries
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Air Bag Allegation (inadvertent deployment)
Driver sustained injuries and received medical consultation

Renea Soto/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 04:45:49 PM	RJOHNS36	RJOHNS36	BRC PAR	Business Case	Done	8/28/2009 04:46:51 PM	PAR Case Assessment
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Customer's allegation is the air bag inadvertently deployed
Driver sustained injuries and received medical consultation.
CRS will be forwarding case to ESIS for further handling.
Renea Soto/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 04:40:16 PM	RJOHNS36	RJOHNS36	Ownership Changed	Ownership Escalated to BRC	Done	8/28/2009 04:40:16 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 03:42:43 PM	RJOHNS36	RJOHNS36	Outbound Call Dealer	Made Contact	Done	8/28/2009 04:09:10 PM	called Svc Mgr Bill Deeson @ (830) 665-4435 from Brown Chevrolet Company Inc
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS spoke with SVC MGR Bill Deeson

Svc mgr states that his svc advisor was informed by the customer, the wife was driving and the wife bruised and sought medical attention

What vehicle services including maint have been performed on the vehicle at the dlr?

Expressed the concern about the air bag light

Steering Column, SIR coils were replaced into the vehicle.

Are there any known product concerns that relate to the customer's allegation?

8/10/09 Air Bag Light being on

Replaced the horn, SIR Coil

8/25/09

Expressed the concern about the air bag light

Replaced SIR coils into the vehicle. The coil shorted and made the air bag deploy.

-Contacted TAC but informed that a case would need to be sent to PAR.

If an inspection becomes necessary would you host that EAA inspection? yes

If the result of the inspection is repairs, will your dealership be able to complete the repairs? yes

If the customer needs to a rental, will your dealership be able to provide a rental? yes

CRS advised this case may go to ESIS if the customer sought medical attention or involved the insurance company. Otherwise an inspection would need to be completed

Renea Soto/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:25:44 AM	GARCIAJR	RJOHNS36	Ownership Changed		Done	8/28/2009 11:25:44 AM	Service Request Ownership has changed FROM: DIVIVACA TO: RJOHNS36
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:25:10 AM	GARCIAJR	RJOHNS36	BRC PAR	Initial Contact- Phone	Done	8/28/2009 04:40:09 PM	called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS verified pre-PAR and PAR detail information.

Crs spoke with [REDACTED]

Cust sts: Customer was Southbound on the side of Herman St waiting to pick up her children, she left the car on and smelt like a tire was burning, when the kids were putting on their sit belts, and after I spoke with my husband on my phone, the airbag inflated without a reason. The horn just started to go off and it would not stop. Customer has received injuries and have seeked medical consultation.

Prior to the incident, The customer states the vehicle was hard to turn. The vehicle towed in Corpus Christi and the dealership fixed a coil on the steering wheel and the vehicle was driveable. The vehicle was being driven and didn't want to take it back. When taking off, and smoke from the steering wheel, steering wheel begin to lock /rubbing noise.

CRS advised : due to the nature of the case, the file will be sent to The Central Claims ESIS Office. It can take up to 10 business days for the case to picked by Central Claims. By the 10 business day (14 calendar days) the office will then release their new daim number and assigned representative. If you have not received, a call from the Central Claims office by the 10th business day, give me call and by that time they should have released the information to me. crs provided customer my contact information.

Renea Soto/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:25:04 AM	GARCIAJR	RJOHNS36	BRC PAR	Initial Contact- Dealer	Done	8/28/2009 01:35:21 PM	called Svc Mgr @ (830) 665-4435 from Brown Chevrolet Compa ny Inc
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

called Svc Mgr Bill Deeson @ (830) 665-4435 from Brown Chevrolet Company Inc

CRS attempted to speak with SVC MGR Bill Deeson but was at lunch

Crs spoke with Svc Advisor Paul Parker.

Paul stated it would be best to speak with Bill regarding his case. He is out to lunch but will return at 1:30cst.

Crs requested to be sent to the svc mgrs voicemail to leave message.

Crs left message on voicemail with the case number, vehicle information and my contact information.

Renea Soto/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:24:55 AM	GARCIAJR	RJOHNS36	BRC PAR	Initial Contact- AVM	Done	8/28/2009 01:29:04 PM	called FDVM Christensen Chad 972075 8091
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

DVM Name: Chad Christensen
Node/Mailbox: 972075 8091
This is Renea Soto calling from the GM Product Allegation Dept to make you aware of a file that was received in your area.
The request number is: 71-753630000
The Customer's name is: [REDACTED]
The dealer involved is: BROWN CHEVROLET
Located in: Devine, TX
The vehicle is a: 2006 Chevrolet Cobalt
With current mileage: 72,000
The last 8 digits of the VIN# are: 67 [REDACTED]
This involves: Customer allegation is the driver's front air bag inadvertently deployed.
This message is for informational purposes only. However if you do have any questions please feel free to give me a call. My phone number is 866-790-5600 ext 11072.
Renea Soto/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:24:50 AM	GARCIAJR	RJOHNS36	BRC PAR	Acknowledgement	Done	8/28/2009 04:35:49 PM	called [REDACTED]
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

This is Renea Soto calling from the GM Product Allegation Dept. I have received your file and do require further information. Do you have about 10-15 minutes to speak to me?

Cust sts: Yes

Continued in Initial.

Renea Soto/ PAR/ ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:24:44 AM	GARCIAJR	RJOHNS36	Notify CRM		Done	8/28/2009 01:12:00 PM	File assigned
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Received							

Renea Soto/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:24:30 AM	GARCIAJR	RJOHNS36	Research		Done	8/28/2009 04:10:15 PM	Research vin
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
No Open Related Recalls							

Service Informational Item

EI 09110 SIR/AIRBAG LIGHT ILLUMINATED, DTC B0081 SET(REF, TSB 09-09-41-003) 05/05/2009 See Bulletin

Previous Related Claim History

8/25/09 35 01 B C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMEN 15923770 - COIL G N/A \$ 154.58 N

8/24/09

35 01 B C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMEN 15923770 - COIL G N/A \$ 154.58 N

8/10/09

34 01 B C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMEN 15923770 - COIL G N/A \$ 162.34 N

No Branded Title

No Warranty Block

Customer/ VIN Scan: No Previous Related Cases

Renea Soto/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/28/2009 11:24:01 AM	GARCIAJR	RJOHNS36	BRC PAR	Case Assigned	Done	8/28/2009 01:12:02 PM	File assigned to Renea soto 11072
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Received

Renea Soto/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/27/2009 03:12:25 PM	DIVIVACA	GARCIAJR	Escalation	Initiate PAR	Done	8/28/2009 11:14:30 AM	Assigning activity to PAR QUEUE
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Received and assigned in PAR.

Joe G/ATX/Workflow Per

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/27/2009 03:03:02 PM	DIVIVACA	DIVIVACA	Inbound Call Customer	Complex Request	Done	8/27/2009 03:11:33 PM	Complaintg Vehicle
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts:

-smelling burnt rubber and then the airbag inflated without a reason. the horn just started to go on and it would not stop .

Cust sks:

Who would pay for the steering wheel

CRS advised customer that their information will be forwarded to the Product Allegation Department within the BRC

Carlo Martin/CAC/Mla/T1/iviD

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Inadvertent Deployment	Restraints - (SIR) - Driver Front

Report Generated for toporowm

on 9/1/2009

Page 8 of 8

TA000104213

GM Vehicle Inquiry System Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK15F967
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK37 -2006 COBALT 2-DOOR LS COUPE		Warranty Start Date :		06/23/2005		
BARS Order Type :	50 - FLEET						
Delivering Dealer :	WALDEN FLEET GROUP, INC. 6 SYLVAN WAY PARSIPPANY , NJ 07054-3826		Selling Source :		13 - CHEVROLET		
			Site Code :		04681		
			Business Associate Code :		111571		
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Type	Number	Description	Posted Date	Status
RC	05084	DAYTIME RUNNING LAMPS INOPERATIVE	N/A	Closed
RC	06217	HEAD IMPACT PROTECTION	N/A	Closed

SERVICE INFORMATIONAL ITEMS

Type	Number	Description	Posted Date	Status
EI	09110	SIR/AIRBAG LIGHT ILLUMINATED, DTC B0081 SET(REF. TSB 09-09-41-003)	05/05/2009	See Bulletin

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	06/23/2005	10 miles	06/23/2008	36010 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	06/23/2005	10 miles	06/23/2011	100010 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	06/23/2005	10 miles	06/23/2013	80010 miles
36/36000 FEDERAL EMISSION	06/23/2005	10 miles	06/23/2008	36010 miles

60/60000 POWERTRAIN - U.S. LIMITED WARRANTY	06/23/2005	10 miles	06/23/2010	60010 miles
---	------------	----------	------------	-------------

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
08/25/2009	055927	B	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMENT	2601 miles
08/24/2009	055872	B	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMENT	72545 miles
08/10/2009	055587	B	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMENT	72412 miles
06/19/2008	078478	#	V1556 - 06217 - INSTALL ENERGY ABSORBING DEVICE	56651 miles
07/30/2006	334759	#	N1720 - FUSE REPLACEMENT	27490 miles
06/21/2005	A00736	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Claim History

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK15F967 (b) (6)
-------	---------------------

CLAIM HISTORY

Repair Order Date : 08/25/2009		Repair Order Number : 055927		Odometer Reading : 72601 miles					
Serviced By :	BROWN CHEVROLET COMPANY INC PO DWR G DEVINE, TX 78016 (830) 665-4435			Selling Source : 13 - CHEVROLET					
				Site Code : 30081					
				Business Associate Code : 114899					
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
08/28/2009	34	01	B	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMENT	15923770 - COIL	G	N/A	\$ 154.58	N

Repair Order Date : 08/24/2009		Repair Order Number : 055872		Odometer Reading : 72545 miles					
Serviced By :	BROWN CHEVROLET COMPANY INC PO DWR G DEVINE, TX 78016 (830) 665-4435			Selling Source : 13 - CHEVROLET					
				Site Code : 30081					
				Business Associate Code : 114899					
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
08/28/2009	35	01	B	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMENT	15923770 - COIL	G	N/A	\$ 154.58	N

Repair Order Date : 08/10/2009		Repair Order Number : 055587		Odometer Reading : 72412 miles					
Serviced By :	BROWN CHEVROLET COMPANY INC PO DWR G DEVINE, TX 78016 (830) 665-4435			Selling Source : 13 - CHEVROLET					
				Site Code : 30081					
				Business Associate Code : 114899					
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments

08/25/2009	34	01	B	C8800 - STEERING WHEEL INFLATABLE RESTRAINT MODULE COIL REPLACEMENT	15923770 - COIL	G	N/A	\$ 162.34	N
------------	----	----	---	--	--------------------	---	-----	-----------	---

Repair Order Date :		06/19/2008		Repair Order Number :		078478		Odometer Reading :		56651 miles	
Serviced By :	PURSCH MOTORS, INC. 2207 W OAKLAWN PLEASANTON, TX 78064-4610 (830) 569-2241					Selling Source :		11 - BUICK			
						Site Code :		56839			
						Business Associate Code :		118962			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
07/25/2008	920	01	#	V1556 - 06217 - INSTALL ENERGY ABSORBING DEVICE		25844441 - ABSORBER		P	N/A	\$ 53.75	N

Repair Order Date :		07/30/2006		Repair Order Number :		334759		Odometer Reading :		27490 miles	
Serviced By :	AVIS RENT A CAR 6 SYLVAN WAY PARSIPPANY, NJ 07054-3826					Selling Source :		13 - CHEVROLET			
						Site Code :		99021			
						Business Associate Code :		126373			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
09/05/2006	723	01	#	N1720 - FUSE REPLACEMENT		N/A		N/A	N/A	\$ 14.02	N

Repair Order Date :		06/21/2005		Repair Order Number :		A00736		Odometer Reading :		0 miles	
Serviced By :	AVIS RENT A CAR 6 SYLVAN WAY PARSIPPANY, NJ 07054-3826					Selling Source :		13 - CHEVROLET			
						Site Code :		99021			
						Business Associate Code :		126373			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
06/24/2005	598	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 71.96	N

CHECK HISTORY

Vehicle Has No Associated Check History.

GM Vehicle Inquiry System

Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	1G1AK15F967
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK37 -2006 COBALT 2-DOOR LS COUPE		
Gross Vehicle Weight Rating :	1681 kg (3707 lb)	Order Number :	JDXDNZ
Build Date :	06/21/2005	Build Plant :	167A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AR9 - DELUXE FRONT BUCKET SEAT
AU0 - REMOTE KEYLESS ENTRY	AU3 - POWER DOOR LOCKS W/REMOTE KEYLESS ENTRY
BQ2 - AVIS RENT A CAR	B0G - GM PRODUCTION WEEK #25
B34 - FLOOR MATS	B35 - REAR FLOOR MATS
B84 - BODY COLOR BODYSIDE MOLDINGS	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	DT4 - ASHTRAY AND LIGHTER
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FE9 - FEDERAL EMISSIONS
FLT - FLEET PROCESSING OPTION	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	J41 - POWER DISC FRONT BRAKES
K34 - CRUISE CONTROL	K64 - 115 AMP GENERATOR
LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO	L61 - 2.2L DOHC 4 CYL ENGINE
MN5 - 4 SPEED AUTO TRANSMISSION	MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE
NT7 - FEDERAL EMISSION TIER 2	N46 - 4 SPOKE STEERING WHEEL
PG1 - 15" STEEL WHEEL	QTU - P195/60R15 TOURING BW TIRES
R6F - IDENTIFY B-CODE USERS	R6P - PREMIUM PAINT
T43 - REAR DECK-LID SPOILER	UN0 - AM/FM STEREO W/CD & RDS
UQ4 - BASE SPEAKER SYSTEM	VK3 - FRONT LICENSE PLATE MOUNT
VN9 - DAILY RENTAL REPURCHASE PROGRAM	V2G - FULL FUEL FILL CREDIT

V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA	1LS - 1LS BASE PACKAGE
1SZ - OPTION PACKAGE DISCOUNT	14B - GRAY
14I - GRAY	6AR - FRONT SPRING
7AR - FRONT SPRING	8AA - REAR SPRING
9AA - REAR SPRING	91U - ARRIVAL BLUE METALLIC

© 2009 General Motors. All Rights Reserved.

CDR File Information

User Entered VIN	1G1AK15F967
User	PHILLIP NOTTINGHAM
Case Number	677891
EDR Data Imaging Date	Monday, September 21 2009
Crash Date	Wednesday, August 26 2009
Filename	1G1AK15F967 ACM.CDR
Saved on	Monday, September 21 2009 at 04:36:54 PM
Collected with CDR version	Crash Data Retrieval Tool 3.2
Reported with CDR version	Crash Data Retrieval Tool 3.2
EDR Device Type	airbag control module
Event(s) recovered	None

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event contains Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also contains Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data

- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```

$01 00 00 00 00 2F 00 00
$02 30 0C 06 00 00 00 00
$03 06 00 00 00 00 00 00
$04 02 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 0A 00 00 0A 90 11
$07 00 09 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 00 B7 A1 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 05 0F 00 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F A2 00 00 00 00 00 00
$10 47 31 41 4B 31 35 46
$11 39 36 37 36 30 30 37
$12 33 36 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 07 07 03 03 00 00 00
$18 02 02 00 00 00 00 00
$19 07 07 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 4F 00 00 4F 00 01 00
$1F 3B C1 00 00 00 23 00
$20 40 00 00 00 00 00 00
$21 FF 01 00 00 70 00 00
$22 00 B1 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 80 00 C4 00 05 00 00
$2F 00 40 26 BA 00 00 00
$30 9D 00 00 00 00 00 00
$31 FF FF FF FF FF 80 00
$32 F8 80 FF 80 00 00 00
$33 FF FF FF FF FF 80 00
$34 FF FF FF FF FF 80 00
$35 FF FF FF FF FF 80 00
$36 FF FF FF FF FF 80 00
$37 F8 80 F8 0F 0F CA FE
$38 FF 80 C0 80 FF C0 FC
$39 FF FF FF FF FF 80 00
$3A FF FF FF FF FF 80 00
$3B 7F 0F 1F 1F 3F 00 00
$3C FF FF FF FF FF FF C0
$3D FF FF FF FF FF FF 00

```

```

$3E FF FF FF FF 00 00 00
$3F 00 00 F0 00 00 00 00
$40 E0 FF 00 00 00 00 00
$41 F8 F8 90 00 00 00 00
$42 80 FF FF FF FF 00 00
$43 FF FF FF 00 00 00 00
$44 FF FF FF FF FF FF 00
$45 FF FF FF FF FF FF 00
$46 FF FF FF FF FF FF 00
$47 FF FF FF FF FF FF 00
$48 FF FF FF FF FF FF 00
$49 FF FF FF FF FF FF 00
$4A FF FF FF FF FF FF 00
$4B FF FF FF FF FF FF 00
$4C FF FF FF FF FF FF 00
$4D FF FF FF FF FF FF 00
$4E FF FF FF FF FF FF 00
$4F FF FF FF FF FF FF 00
$50 FF FF FF FF FF FF 00
$51 F0 00 00 F0 00 00 00
$52 81 FF FF FF 00 00 00
$53 FF FF FF 00 00 00 00
$54 82 FF FF 00 00 00 00
$55 FF FF FF FF FF FF 00
$67 A0 FF 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 35 31 30 39 33 30 39 38 4C
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 08 31 32 38 38 31 32 55
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 33 19 2A B4 E6 87 91 9A
$22 90 11
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA

```

```
$26 32 41 FA FA FA FA FA
$40 00 00
$41 3F 00 00 02 00 1A
$42 F0 C4
$43 00 00 8E 80
$44 C6 00 00 FC C0 C0
$45 07 01 07 01 05 01
$46 FF 1A 1A 64 64
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 39 30 31 31 32 31 30 38 47 4D 20 20 20 20
$B7 50 AA 04 0F 03
$B8 41 57 68 09 19
$C1 30 46 30 33
$CA 30 46 30 33
$CB 01 5A D1 33
$CC 01 5A D1 33
$D1 00 00
$DB 00 00
$DC 00 00
```

Comments

- DOWNLOADED AT 340 IH35 SOUTH, DEVINE, TEXAS (BROWN CHEVROLET)
- SIR LAMP FLASHED ON AND OFF AND REMAINED ON
- CONNECTED TO DLC
- VEHICLE BATTERY STILL POWERING VEHICLE SYSTEMS
- MILEAGE: 72,710

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.