


EWR D&I ANNOTATION

FAN-000001L111001DP121-8493

Artemis # : 000001L111001DP121**Record Created Date :** 08/11/2011**Printed Date :** 08/11/2011**Description :**

DI11-072 SEQUENCE ID 121: A SERVICE REQUEST DETAIL LOG FOR GENERAL MOTORS LLC MAKES THE ALLEGATION THAT A 2007 CHEVROLET COBALT IS POTENTIALLY DANGEROUS DUE TO AN AIR BAG NONDEPLOYMENT. THE LOG STATES THAT THE COBALT WAS INVOLVED IN AN ACCIDENT WHEREBY ANOTHER VEHICLE SWERVED INTO ITS LANE THUS CAUSING THE DRIVER TO APPLY THE BRAKES. THE COBALT WAS UNABLE TO STOP IN TIME AND STRUCK THE VEHICLE IN FRONT AND ALSO WAS STRUCK FROM BEHIND BY ANOTHER VEHICLE. THE SPEED THE VEHICLE'S WERE TRAVELING AND/OR SPEED OF IMPACT WAS NOT PROVIDED. THE LOG CLAIMS THAT THE INCIDENT OCCURED ON LOCAL HIGHWAY. NO INJURIES WERE CLAIMED. FRONT AND REAR DAMAGE TO THE COBALT WERE MENTIONED. NO POLICE REPORTS WERE INCLUDED WITH THE SEQUENCE DOCUMENTATION. FROM A SEARCH NO RECALLS OR PURSUITS WERE FOUND RELATING THIS VEHICLE TO THE ALLEGED SAFETY DEFECT. FROM A VOQ SEARCH, 11 REPORTS WERE FOUND CLAIMING AIR BAG NON DEPLOYMENT OF VARYING SPEEDS AND INCIDENT SPECIFICS. FROM A SEARCH, 21 FIELD REPORTS WERE FOUND WHICH STATED 'NONDEPLOYMENT' IN THE SUMMARY OF THE REPORT. 7 TSBS WERE FOUND FOR THE AIRBAG COMPONENT WHICH ALL MENTION SIR/PASSENGER PRESENCE LIGHTS BEING ILLUMINATED. *NO

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

June 22, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-072

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2011. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 6, 12, 23, 40, 42, 44, 46, 47, 60, 61, 64, 73, 81, 82, 87, 89, 91, 115, 121, 125, 129, 131, 139, 143, 144, 145, 154, 157, 167, 170, 171, 172, 188, 189, 214, 217, 218, 221, 231, 236, 240, 243, 244, 245, 246, 270, 276, 277, 279, 280, 281, 292, 302, 304, 312, 314, 322, 323, 324, 336, 409, 410, 412, 434, 465, 473	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **July 22, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

July 22, 2011

JUL 22 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-072

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated June 22, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2011.

GM's response is comprised of 66 disks for the incidents that are the subject of DI11-072.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 6 333829231-724510 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 6 333829231-724510_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-072
6 333829231-724510
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

6 333829231-724510_01_001- is the first document responsive to Inquiry no.1.

6 333829231-724510_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI11-072, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(66 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
6	5GAEV23D59J	NISM
12	1G4GE5ED8BF	NISM
23	1G4HJ5EM0BU	NISM
40	1G6DS57V290	NISM
42	1G6DU57V090	NISM
44	1G6DE5EG3A0	NISM
46	1G6DP1ED3B0	PAR
47	1G6DS1ED5B0	NISM
60	1GYEE437390	PAR
61	3GYFNCEY2AS	NISM
64	3GYFNBEYXBS	NISM
73	3GNFK12357G	NISM
81	KL1TD66698B	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
82	KL1TD66628B	NISM
87	KL1TG5DEXAE	NISM
89	2G1FJ1EJ0A9	NISM
91	2G1FA1ED6B9	NISM
115	1G1AL55F077	NISM
121	1G1AL15F977	NISM
125	1G1AM15B477	NISM
129	1G1AK18F587	NISM
131	1G1AK18F087	NISM
139	1G1AS18H297	NISM
143	1G1AT58H397	NISM
144	1G1AD1F57A7	NISM
145	1G1AF5F59A7	NISM
154	1G1YY24U555	NISM
157	1G1YY26E185	NISM
167	2CNALBEW2A6	NISM
170	2CNALBEC2B6	NISM
171	2CNFLNEC9B6	NISM
172	2CNALDEC2B6	NISM
188	3GNBABDV7AS	NISM
189	3GNBAADB0AS	NISM
214	2G1WT57N291	NISM
217	2G1WB5EK8A1	NISM
218	2G1WB5EK2A1	NISM
221	2G1WA5EK7A1	NISM
231	1G1ZS58N97F	NISM
236	1G1ZF57588F	NISM
240	1G1ZB5EB5A	LIT
243	1G1ZD5EB6AF	NISM
244	1G1ZB5E17BF	NISM
245	1G1ZA5E1XBF	NISM
246	1G1ZB5E11BF	NISM
270	3GCEC13C28G	LIT
276	3GCEC23089G	NISM
277	1GCSCSE08AZ	NISM
279	1GCRKSE37BZ	NISM
280	1GCRCSE00BZ	NISM
281	UNKNOWN	NISM
292	1GC1KXC89BF	NISM
302	1GNFC16J47J	Rumor
304	3GNFC16087G	PAR
312	1GNFC13047R	PAR
314	1GNFC13J78R	NISM
322	1GNSCAE06BR	NISM
323	1GNSKDFJ9BR	Rumor
324	1GNSKCE0XBF	NISM
336	1GNDT13S052	NISM
409	2CTFLEEW0A6	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
410	2CTALSEC6B6	NISM
412	2CTALSEC2B6	NISM
434	KL2TD66E39B	NISM
465	1G2ZG57B694	NISM
473	2G2WP552781	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 66 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

CIVIL CASE COVER SHEET

Case Name: CARDONA V. CHEVROLET

Case Number: 902-409-1126

Case Description: [] Limited [X] Unlimited

Check one box below for the case type that best describes the case:

Auto Tort

☒ Auto (22)

☐ Other (23)

Personal Injury/Property Damage/Personal Injury Tort

☐ Automobile (24)

☐ Product liability (25)

☐ Medical malpractice (26)

☐ Other (27)

Real Property

☐ Real property (28)

☐ Real property (29)

☐ Real property (30)

☐ Real property (31)

☐ Real property (32)

☐ Real property (33)

☐ Real property (34)

☐ Real property (35)

☐ Real property (36)

☐ Real property (37)

☐ Real property (38)

☐ Real property (39)

☐ Real property (40)

☐ Real property (41)

☐ Real property (42)

☐ Real property (43)

☐ Real property (44)

☐ Real property (45)

☐ Real property (46)

☐ Real property (47)

☐ Real property (48)

☐ Real property (49)

☐ Real property (50)

☐ Real property (51)

☐ Real property (52)

☐ Real property (53)

☐ Real property (54)

☐ Real property (55)

☐ Real property (56)

☐ Real property (57)

☐ Real property (58)

☐ Real property (59)

☐ Real property (60)

☐ Real property (61)

☐ Real property (62)

☐ Real property (63)

☐ Real property (64)

☐ Real property (65)

☐ Real property (66)

☐ Real property (67)

☐ Real property (68)

☐ Real property (69)

☐ Real property (70)

☐ Real property (71)

☐ Real property (72)

☐ Real property (73)

☐ Real property (74)

☐ Real property (75)

☐ Real property (76)

☐ Real property (77)

☐ Real property (78)

☐ Real property (79)

☐ Real property (80)

☐ Real property (81)

☐ Real property (82)

☐ Real property (83)

☐ Real property (84)

☐ Real property (85)

☐ Real property (86)

☐ Real property (87)

☐ Real property (88)

☐ Real property (89)

☐ Real property (90)

☐ Real property (91)

☐ Real property (92)

☐ Real property (93)

☐ Real property (94)

☐ Real property (95)

☐ Real property (96)

☐ Real property (97)

☐ Real property (98)

☐ Real property (99)

☐ Real property (100)

NOTICE

Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (or under the Probate, Family, or Welfare and Institutions Code, Cal. Rules of Court, rule 100.5) in the case.

If this case is exempt under rule 100.5 of the California Rules of Court, you must file this cover sheet with the action or proceeding.

Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

CIVIL CASE COVER SHEET

Step 7: Next File (Image)

Step 7: Next Page

Step 8: Scale Image

Step 7: Image Properties

DI11-072
121 333828676-723184
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No.	71-905640291	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Collision
Address		City	Alton	Involved Dir		Safety	Yes
State	VA ZipCd	Con Acct		Source	Phone	Updated	1/6/2011 02:46:34 PM
Serial #/VIN		Model Year	2007	Priority	Medium License #	Owner	SANCHERI
Make	Chevrolet	Warr. Start		Status	Open	Opened	1/6/2011 02:06:28 PM
Model	Cobalt	Mileage	91000	Sub-Status	Disassembled	Closed	
Abstract	airbag did not deploy						
Customer Description	***This is a BRC PAR Case. Please do not assume. Forward any inquiries to Rita Sanchez at ext.31227 ***						

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond	Fire Report#	Police Report#				
Owner	12/23/2010 06:15:57	Y	4	2	Asphalt	Dry	na	unknown				
Driver Last Name	Driver First Name	Height	DOB	Disabilities								
		5'9		none								
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency									
unknown	Reyna		state farm									
Incident Loc	29 south bound greensborough NC				Incident Desc	he was driving and the two lanes merge and this other car swooped into our lane and the car in front of us slammed on its brakes to avoid hitting it but hit it anyways my boyfriend hit the brakes but still hit the charger the vehicle behind us hit us pushing us further into the charger and						
Component	airbags				Damage Desc	front and rear end damage						
Vehicle Loc	towing (sheps towing and recovery)				Add'l Info	I dont have the claim number with me						
Emgcy Svc Names	greensburg city police				Maint Loc	na						

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	na
Vehicle Speed	45	Weather Condition	clear	Prop Owner	na	Property Type	na	
Last Service Date		Loc Last Service		Property Location	na	Prop Est Repair Cost	\$0.00	
Veh Est Repair Cost	\$0.00	Spec Equip Installer	na	Prop Damage Description	the person that caused the collision is being held responsible for all other vehicles			
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	front and rear end damage			Explain Other	sent to esls			

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Front Passenger	seatbelt
Injury/Description	Medical Rpt #	Treatment Location	Treated By			
back strain	na	hollowfax county hospital	Er doctor			
Street/Address	City	State	Zip Code			
	Alton	VA				

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/7/2011 05:10:52 PM	GARCIAJR	ESISBQU	Escalation	ESIS - Injuries	In Progress		Injures - ESIS
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
back sprain - went to hollowfax county hospital							
Joe G/PAR/ATX							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:52:17 PM	SANCHERI	SANCHERI	Scheduled Follow-up		Scheduled Alarm		/u esis pick up
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:51:54 PM	SANCHERI	GARCIAJR	Notify CRM		Done	1/7/2011 05:10:25 PM	esis - injuries
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:46:34 PM	SANCHERJ	SANCHERJ	Ownership Changed	Ownership Escalated to BRC	Done	1/6/2011 02:46:35 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:46:05 PM	SANCHERJ	SANCHERJ	Ownership Changed		Done	1/6/2011 02:46:05 PM	Service Request Ownership has changed FROM: LIMEF TO: SANCHERJ

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:22:22 PM	SANCHERJ	SANCHERJ	BRC PAR	Initial Contact-AVM	Done	1/6/2011 02:51:34 PM	call Coggins Usa 404082 8081

Contact Last Name	Contact First Name	Account	BAC Code

Comments

This is Rita Sanchez calling from gm par dept.

Customer:

Service Request:71905640281

Vehicle Information:07 chevy cobalt

Last 8 of the VIN: na

Involved Dealership:none

Nature of allegation: akbag non deployment

CRS adv if you have any additional information pertaining to customer or vehicle please contact me at 1-888-790-6600 X 31227 If not then this is an FYI to let you know what is going on in your district.

Rita Sanchez/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:22:19 PM	SANCHER	SANCHER	BRC PAR	Initial Contact- Dealer	Done	1/6/2011 02:45:35 PM	call
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

no vin available - customer states vehicle is not in her possession and she cant get the vin at this time

rita sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:22:01 PM	SANCHER	SANCHER	BRC PAR	Initial Contact- Phone	Done	1/6/2011 02:45:10 PM	call
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

verified customer allegation and information

provided esls statements

cust sls i want to proceed

crs sls what happened

custs sls i dont have the vin and dont believe i can get that for you, but my boyfriend was driving and the two lanes merge and this other car swooped into our lane and the car in front of us slammed on its brakes to avoid hitting it but hit it anyways my boyfriend hit the brakes but still hit the charger the vehicle behind us hit us pushing us further into the charger and our airbags didnt deploy, i was taken to the hospital for evaluation

crs sls i understand what i will do is get this over to our central claims department and they will be contacting you within 7-10 business days

cust sls ok thanks

rita sanchez/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/8/2011 02:21:55 PM	SANCHER	SANCHER	Research		Done	1/8/2011 02:40:09 PM	vin

Contact Last Name	Contact First Name	Account	BAC Code

Comments

no vin available - customer states vehicle is not in her possession and she cant get the vin at this time

rita sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/8/2011 02:21:46 PM	SANCHER	SANCHER	BRC PAR	Acknowledgement	Done	1/8/2011 02:23:15 PM	call

Contact Last Name	Contact First Name	Account	BAC Code

Comments

See Initial Contact

Rita Sanchez/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/8/2011 02:21:17 PM	SANCHER	SANCHER	BRC PAR	Case Assigned	Done	1/8/2011 02:21:45 PM	File assigned to Rita Sanchez @ ext 31227

Contact Last Name	Contact First Name	Account	BAC Code

Comments

File received and reviewed

Rita Sanchez/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/6/2011 02:08:00 PM	LIMEF	LIMEF	Inbound Call Customer	Complex Request	Done	1/6/2011 02:11:08 PM	airbag did not deploy
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

cust sts:

-23rd of dec at 6:15pm est
while driving there is two lane the right lane merges
-there was a veh come staming all vehicles and its like domino effect
-we hit the charger and the grand am hit me from behide as well
-airbags did not deploy
-i had to go to the hospital for the pain at my back
-the veh is at Shet's owing and recovery
-the veh is nnot drivable anymore

cust aks:

-asking for assistance

crs advised:

-will forward the copncem to our PAR department to assist further
-apologize for the inconvenience

John Lim/MAN/CAC T1/Lv1

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	No Symptom Indicated	Restraints - (SIR) - Driver Front

[Logout](#)

July 7, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary

②

This screen allows IVH users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

Vehicle Information

VIN: 1G1AL15F977

Model: 1AL37-2007 COBALT 2-DOOR LT COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 50 - FLEET

Field Actions: [0 Open](#)

For this vehicle:

[View Vehicle Summary](#)[Service Contract](#)[Branded Title](#)[Warranty Block](#)[View Vehicle Build](#)[View Vehicle Component Summary](#)[View Vehicle](#)[Transaction History Detail](#)[View Vehicle Delivery Information](#)

Required Field Actions

Open field actions are highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N100023	10023	LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR	03/18/2010	Closed
Product Safety Recall	N090226	09226	FUEL ODOR OR SPOTTING ON GROUND - REPLACE FUEL PUMP MODULE	01/27/2010	Closed

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Corrosion Limited Warranty	02/21/2010	09/15/2006	10 MI	09/15/2012	100,010 MI
	Bumper to Bumper Limited Warranty	02/21/2010	09/15/2006	10 MI	09/15/2009	36,010 MI
	Emission Select Component Ltd Wty	02/21/2010	09/15/2006	10 MI	09/15/2014	80,010 MI

Powertrain Limited
Warranty

02/21/2010 09/15/2006 10 MI 09/15/2011 100,010 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
10/13/2010	737635	ZFAT—Field Action Recall		V2220 - 10023 - Replace Power Steering Assist Motor (including Test Drive)	82,451 MI
10/13/2010	737635	ZFAT—Field Action Recall		V2149 - 09226 - Inspect & Install New Fuel Pump Module	82,451 MI
09/14/2006	A62511	ZPDI—Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.


[Logout](#)

July 7, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build



This screen allows IVH users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN: 1G1AL15F977

Model: 1AL37-2007 COBALT 2-DOOR LT COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 50 - FLEET

Field Actions: [0 Open](#)

For this vehicle:

→ [View Vehicle Summary](#)→ Service
Contract

→ Branded Title

→ Warranty Block

→ [View Vehicle Build](#)→ [View Vehicle](#)→ [Component Summary](#)→ [View Vehicle](#)→ [Transaction History](#)
Detail→ [View Vehicle Delivery](#)
Information

Vehicle Build

Model: 1AL37-2007 COBALT 2-DOOR LT COUPE

Order Number: KHDD0K

Gross Vehicle Weight: 1,731

Build Date: 09/14/2006

Build Plant: 7-

Option Codes

*IVH is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

192 - EBONY

19I - EBONY

1SZ - OPTION PACKAGE
DISCOUNT

3LT - 3LT-SPORT PACKAGE *WHEELS, 16" ALUMINUM, MACHINE FACED
(REPLACES STD/OPT WHEELS) *16" TOURING TIRES *ANTILOCK BRAKE
SYSTEM *CONVENIENCE NET, CARGO *CRUISE CONTROL *BODY
COLOR, BODYSIDE MOLDINGS *CHROME EXHAUST TIP *REAR SPOILER
*WHITE FACED GAUGES *LEATHER WRAP STEERING WHEEL, STEERING
WHEEL AUDIO CONTROLS *LEATHER WRAPPED SHIFT KNOB

6AP - FRONT SPRING

74U - VICTORY RED

7AP - FRONT SPRING

8AB - REAR SPRING

9AB - REAR SPRING

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS

ALO - SENSOR INDICATOR
INFLATABLE RESTRAINT, FRT
PASS/CHILD PRESENCE
DETECTOR

AP9 - CONVENIENCE NET, CARGO

AR9 - DELUXE FRONT
BUCKET SEAT

AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING

AU0 - REMOTE KEYLESS
ENTRY

AU3 - POWER DOOR LOCKS W/REMOTE KEYLESS ENTRY

B0V - GM PRODUCTION
WEEK #38

B34 - FLOOR MATS, FRONT/REAR

B35 - REAR FLOOR MATS

B84 - BODY COLOR, BODYSIDE MOLDINGS

BQ2 - AVIS RENT A CAR

C67 - ELECT. FRONT AIR CONDITIONER

CF5 - POWER SUNROOF

DC4 - INTERIOR REARVIEW MIRROR W/DUAL READING LAMPS

DG7 - BODY COLOR POWER
MIRRORS

DT4 - ASHTRAY AND LIGHTER

FE1 - SUSPENSION SYSTEM-
SOFT RIDE

FE9 - FEDERAL EMISSIONS

FLT - FLEET PROCESSING
OPTION

FY1 - TRANS/AXLE 3.63 RATIO

IP2 - TRIM INTERIOR DESIGN

JM4 - ANTILOCK BRAKE SYSTEM

K34 - CRUISE CONTROL

K64 - 115 AMP GENERATOR

KA1 - FRONT SEAT HEATER

L61 - ENGINE, 2.2L DOHC 4V ECOTEC

LOD - ASSEMBLY PLANT -
LORDSTOWN, OHIO

MN5 - 4 SPEED AUTO TRANSMISSION

MX0 - TRANSMISSION, 4 SPD
AUTOMATIC

N34 - 3 SPOKE LEATHER STEERING WHEEL

NT7 - FEDERAL EMISSION

NW7 - TRACTION CONTROL

TA000113978

TIER 2

NZ0 - 16" MACHINED-FACE ALUMINUM WHEELS	QLG - TIRE ALL P205/55R16-89H BW
R6F - IDENTIFY B-CODE USERS	R6K - ONSTAR
R6P - PREMIUM PAINT	R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS
RE8 - UPGRADE ORNAMENTATION	T43 - REAR SPOILER
TV5 - SPORT PACKAGE	UK3 - LEATHER WRAP STEERING WHEEL, STEERING WHEEL AUDIO CONTROLS
UQ3 - AUDIO SYSTEM, HIGH PERFORMANCE WITH 7 PIONEER SPEAKERS	US8 - AM/FM STEREO, CD PLAYER & MP3 PLAYER
V2G - FULL FUEL FILL CREDIT	V73 - STATEMENT OF VEHICLE CERT.-U.S. /CANADA
VN9 - DAILY RENTAL REPURCHASE PROGRAM	VT7 - OWNERS MANUAL ENGLISH
VY7 - LEATHER SHIFT KNOB	

Added Option Codes


Vehicle has no current record of SAIO codes.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

TA000113979


[Logout](#)

July 7, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary



This screen allows IVH users to view the information on various major components added to the VIN selected during vehicle build.

Vehicle Information

VIN: 1G1AL15F977

Model: 1AL37-2007 COBALT 2-DOOR LT COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 50 - FLEET

Field Actions: [0 Open](#)

For this vehicle:

→ [View Vehicle Summary](#)→ Service
Contract

→ Branded Title

→ Warranty Block

→ [View Vehicle Build](#)→ [View Vehicle
Component Summary](#)→ [View Vehicle
Transaction History
Detail](#)→ [View Vehicle Delivery
Information](#)

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY

Source Plant: T-CPC TONAWANDA, NEW YORK

Date Scanned: 09/14/2006

Traceability: 609081379

Part / Number Broadcast: AWD

Time Scanned: 01:39:00 Scan Station: 04

Component Code: 61-TRANSMISSION

Source Plant: J-HYDRAMATIC WINDSOR, ONTARIO

Date Scanned: 09/14/2006

Traceability: 3JA6

Part / Number Broadcast: 7EHJ

Time Scanned: 01:39:00 Scan Station: 04

Component Code: 74-ELECTRON BRAKE & TRACTION CTRL
MOD ASM

Source Plant: P-

Date Scanned: 09/14/2006

Traceability: 1996G4576

Part / Number Broadcast:
7529Time Scanned: 07:13:00 Scan Station:
04Component Code: 86-ELECTRONIC CONTROL MODULE
(ECM)

Source Plant: 2-

Date Scanned: 09/14/2006

Traceability: 16184010G

Part / Number Broadcast:
YPCXTime Scanned: 10:48:00 Scan Station:
06

Component Code: 87-BODY CONTROL MODULE

Source Plant: R-

Date Scanned: 09/14/2006

Traceability: A62450235

Part / Number Broadcast: 6911

Time Scanned: 10:48:00 Scan Station: 04

Component Code: AB-IR-MODULE ASM-INFLATOR

Source Plant: M-MORTON-THIOKOL

Date Scanned: 09/14/2006

Traceability: 2A2480882

Part / Number Broadcast: 6196

Time Scanned: 06:55:00 Scan Station: 04

Component Code: AL-IR-MODULE ASM-I/P

Source Plant: I-INLAND

Date Scanned: 09/13/2006

Traceability: G251D2234

Part / Number Broadcast: 5892

Time Scanned: 22:25:00 Scan Station: 04

Component Code: BK-INTERNATIONAL TRANS. CONTROL
MODULE

Source Plant: K-

Date Scanned: 09/14/2006

Traceability: 062525855

Part / Number Broadcast:
YHRLTime Scanned: 10:48:00 Scan Station:
04

Component Code: CB-SEQ NUM (FLEX) BODY ASM

Source Plant: -

Date Scanned: 09/12/2006

Traceability: 0660385

Part / Number Broadcast: 1ZZ

Time Scanned: 05:28:00 Scan Station:

TA000113980

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

July 7, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail



This screen allows IVH users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN: 1G1AL15F977 [REDACTED] Model: 1AL37-2007 COBALT 2-DOOR LT COUPE
Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
Order Type: 50 - FLEET
Field Actions: [0 Open](#)

[REDACTED]

For this vehicle:

[View Vehicle Summary](#)[Service Contract](#)[Branded Title](#)
[Warranty Block](#)[View Vehicle Build](#)[View Vehicle Component Summary](#)[View Vehicle Transaction History Detail](#)[View Vehicle Delivery Information](#)

Job Card Date: 10/13/2010

Job Card Number: 737635

Repair Service Agent: 113973
CITY CHEVROLET
5101 E INDEPENDENCE BLVD
CHARLOTTE NC 28212-6167
7045361410

Odometer Reading: 82,451 MI
Authorization Code:

Process Date:
10/13/2010

Transaction Type:
ZFAT—Field Action Recall

Transaction Expense Category:
Field Action Recall

Customer Complaint Code:
-

Job Card Line #: 2

Transaction Adjustment:

Cause Code: -

Labour Op V2220-10023 - Replace Power Steering Assist Motor (including Test Drive)

Causal Part Number

[See other Parts and/or Net Items](#)

Job Card Date: 10/13/2010

Job Card Number: 737635

Repair Service Agent: 113973
CITY CHEVROLET
5101 E INDEPENDENCE BLVD
CHARLOTTE NC 28212-6167
7045361410

Odometer Reading: 82,451 MI
Authorization Code:

Process Date:
10/13/2010

Transaction Type:
ZFAT—Field Action Recall

Transaction Expense Category:
Field Action Recall

Customer Complaint Code:
-

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op V2149-09226 - Inspect & Install New Fuel Pump Module

Causal Part Number

[See other Parts and/or Net Items](#)

Job Card Date: 09/14/2006

Job Card Number: A62511

TA000113982

Repair Service Agent: 126419
AVIS RENT A CAR
TAMPA INTL AIRPORT
TAMPA FL 33622-0000

Odometer Reading: 0 MI
Authorization Code:

Process Date:
09/19/2006

Transaction Type:
ZPDI---Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time


Causal Part Number

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

TA000113983

[Logout](#)

July 7, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information

②

This screen allows IVH users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN: 1G1AL15F977

Model: 1AL37-2007 COBALT 2-DOOR LT COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 50 - FLEET

Field Actions: [0 Open](#)

For this vehicle:

[→ View Vehicle Summary](#)[→ Service Contract](#)[→ Branded Title](#)[→ Warranty Block](#)[→ View Vehicle Build](#)[→ View Vehicle](#)[→ Component Summary](#)[View Vehicle](#)[→ Transaction History](#)[Detail](#)[→ View Vehicle Delivery Information](#)

Invoice Information

Invoicing Service Agent: 111571

Invoice Date: 09/14/2006

CAR/TRUCK CITY

1405 MAIN ST S

PINE CITY MN 55063-9092 3206296751

Ship to Information

Invoicing Service Agent: 141661

Ship to Date: N/A

AVIS RENT-A-CAR

TAMPA INTERNATL AIRPORT

TAMPA FL 33622-1433

Delivery Information

Delivery Service Agent: 111571

Delivery Date: 09/15/2006

CAR/TRUCK CITY

Delivery Type: 020—DAILYRENTAL

1405 MAIN ST S

Delivery Odometer: 10

PINE CITY MN 55063-9092 3206296751

In Service Information

Invoicing Service Agent:

In Service Date: N/A

In Service Type: 0000

In Service Odometer: 0

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

TA000113984

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G1AL15F977
User	
Case Number	723184
EDR Data Imaging Date	02/22/2011
Crash Date	12/23/2010
Filename	FILE#723184 1G1AL15F977 ACM.CDRX
Saved on	Tuesday, February 22 2011 at 12:56:52
Collected with CDR version	Crash Data Retrieval Tool 3.5.1
Reported with CDR version	Crash Data Retrieval Tool 3.5.1
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

Comments

DOWNLOAD LOCATION: SHEP'S TOWING & RECOVERY 211 WEBSTER ROAD GREENSBORO, NC 27406
CONNECTION: DCL USED
OTHER PERSONS PRESENT: NONE
POWER SUPPLY: EXTERNAL POWER TO FUSE BLOCK
MILEAGE: 91576
SIR LAMP: FLASHED WENT OUT

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record up to 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

- Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.
- Pre-Crash data is recorded asynchronously.
- Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:
 - the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
 - no data is received from the module sending the pre-crash data
 - no module is present to send the pre-crash data
- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMEps_r002

Multiple Event Data

Associated Events Not Recorded	1
An Event(s) Preceded the Recorded Event(s)	No
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	Yes
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	Yes

System Status At AE

Vehicle Identification Number	**1AL15F*7*
Low Tire Pressure Warning Lamp (If Equipped)	OFF
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Fourth Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	No
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	36
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	No	No
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	49	46	43	38	18
Engine Speed (RPM)	1664	1536	1408	1216	960
Percent Throttle	17	16	16	16	19
Accelerator Pedal Position (percent)	0	0	0	0	0
Antilock Brake System Active (If Equipped)	No	No	No	Yes	Yes
Lateral Acceleration (feet/s ²) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	9954
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	7653
Ignition Cycles At Event	9954
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	UNBUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Valid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Not Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	6.10
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	130
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Vehicle Event Data (Pre-Crash) Associated With This Event	Yes
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	-0.68	-0.68	-1.36	-2.03	-2.71	-3.39	-3.39	-4.07	-4.74	-5.42	-5.42	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 00 00 00 00 51 00 00
$02 30 00 00 00 00 00 00
$03 02 00 00 00 00 00 00
$04 02 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 0A 00 00 0A 39 15
$07 10 29 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 00 5D 5D 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 05 0F 00 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F BA 00 00 00 00 00 00
$10 47 31 41 4C 31 35 46
$11 39 37 37 31 36 32 35
$12 31 31 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 03 03 03 02 00 00 00
$18 03 03 00 00 00 00 00
$19 07 07 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 4F 00 00 4F 00 01 00
$1F 33 C1 00 00 00 23 00
$20 40 00 00 00 00 00 00
$21 FF FF 00 00 50 00 00
$22 00 94 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 1D E6 00 00
$2F 00 FE 26 E2 00 00 00
$30 9D 00 00 00 00 00 00
$31 00 00 00 00 00 00 00
$32 00 00 00 00 00 00 00
$33 31 28 28 2A 2B 00 00
$34 0F 13 16 18 1A 00 00
$35 1D 3D 45 4A 4F 00 00
$36 00 00 00 00 00 00 00
$37 C0 00 00 04 04 00 20
$38 55 00 40 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
```

```

$3D 31 41 4C 31 35 46 00
$3E 37 16 25 11 00 00 00
$3F 29 00 90 00 00 00 00
$40 20 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 1D E5 00 00
$43 FE 26 E2 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 00 00 FF 00 FF 00
$48 00 FE 00 FD 00 FC 00
$49 00 FB 00 FB 00 FA 00
$4A 00 F9 00 F8 00 F8 00
$4B 00 00 00 00 00 00 00
$4C 00 00 00 00 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 50 00 00 00 00 00 00
$52 01 00 00 00 00 00 00
$53 0D 00 51 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 36 31 37 32 32 43 4E 39 48
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 06 32 33 37 36 42 31 46
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 37 35 E1 72 6A 74 91 9A
$22 39 15

```

```
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA
$26 32 41 FA FA FA FA FA
$40 00 00
$41 3F 00 00 02 00 1A
$42 D0 C4
$43 00 00 8E 80
$44 C6 00 00 FC C0 C0
$45 07 01 07 01 05 01
$46 FF 1B 1B 64 28
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 33 39 31 35 32 32 31 4E 59 33 20 20 20 20
$B7 50 AA 04 0F 07
$B8 43 48 70 02 09
$C1 30 46 30 37
$CA 30 46 30 37
$CB 01 89 6E 6B
$CC 01 89 6E 6B
$D1 00 00
$DB 00 00
$DC 00 00
```

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.