

NIMBUS DISPLAY SYSTEMS

N50 Smart Display

Service-oriented user manual

Model	Nimbus N50
Product code	NIM-N50-2024
Edition	Manual 1.8
Source	s5b-nimbus-manual

This manual applies only to the Nimbus N50. Its error codes must not be transferred to an Aurelia product.

Read the identification, safety and applicability information before relying on this document.

2. Contents

Section	Page
Identification	3
Code H17	4
Ventilation	5
Connections	6
Service	7
Specifications	8

3. Product identification

Applicability

This document applies only to Nimbus N50, product code NIM-N50-2024.

Rating label

Confirm the product code before using service-code definitions.

Different code set

Nimbus assigns codes independently. A matching number or letters on another brand can mean something entirely different.

Service boundary

Cabinet repair and internal fan testing require qualified personnel.

4. Nimbus code H17

Definition

On the Nimbus N50, product code NIM-N50-2024, H17 indicates that the internal cooling-fan tachometer signal is absent or outside its permitted range.

User response

Turn the display off and check that external vents are not blocked. Do not insert an object into a vent or open the cabinet.

Service response

A qualified technician checks fan rotation, the tachometer lead, supply voltage and controller input.

Not transferable

This Nimbus definition does not apply to the Aurelia Q62. It also does not establish lightning, external surge or any insurance cause.

Product	Code	Meaning
Nimbus N50 / NIM-N50-2024	H17	Cooling-fan tachometer signal fault

5. Ventilation and temperature

Clearance

Maintain 12 cm clearance above and behind the display.

Dust

Clean the outside of vents with power disconnected. Internal cleaning is a service task.

Thermal protection

The display can reduce brightness or shut down when internal temperature is excessive.

Repeated H17

Do not continue repeated restart attempts if H17 returns after vents are checked.

6. Connections

Cable changes

Power off connected equipment before replacing a cable.

Code separation

An HDMI fault on this model is not represented by Nimbus code H17.

Port	Use
HDMI 1-3	Video sources; HDMI 1 supports ARC
USB	Media and service
Ethernet	Wired network
Optical	Digital audio

7. Service records

Report

Record the product code, code history, temperature, fan observations and tests.

Parts

Use parts approved for Nimbus N50 airflow and electrical ratings.

Evidence limit

A service code identifies a diagnostic path; it does not alone establish the legal or insurance cause of damage.

Document

Nimbus manual N50-UM-18, synthetic evaluation edition.

8. Technical summary

Dataset role

This complete wrong-product manual is a hard negative for model-identity and error-code separation.

Model	Nimbus N50
Product code	NIM-N50-2024
Screen	50-inch 4K
HDMI	3
Cooling	Active internal fan
H17	Fan tachometer signal fault
Applicability to Aurelia Q62	None