# Acceptance Sampling - Step 7: Take Follow-up Action

## Step 7: Take Follow-up Action

After the decision to accept or reject the lot, appropriate follow-up actions must be taken. These actions ensure that quality issues

are addressed and that only conforming products are delivered or used.

## Typical actions include:

- Accepted lot: Proceed with shipping, use in production, or storage
- Rejected lot: Perform 100% inspection, rework, return to supplier, or scrap the lot

## Example:

The lot of 5,000 LED bulbs was rejected because 7 defects were found in a sample of 200 (exceeding the acceptance number of 5).

### Follow-up action options:

- 1. 100% inspection: Inspect all 5,000 bulbs and remove defects
- 2. Rework: Repair defective bulbs and re-inspect
- 3. Return: Send the lot back to the supplier with a rejection report
- 4. Scrap or downgrade: Dispose of or sell as lower-grade items

These steps ensure quality is maintained and customers receive reliable products.