

Modbus TCP App

Modbus TCP Communication for ctrlX OS
Version 4.6.0

Copyright

© Bosch Rexroth AG 2026-03

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAG-SW (MiNi/PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.0	4
3.1	New functions	4
3.1.1	Feature 1174892: Modbus TCP string handling optimized	4
3.2	Resolved defects and modifications	4
3.2.1	Bug 1053553: Modbus TCP FC23 display is incorrect	4
3.2.2	Bug 1148052: Modbus TCP – Corrupt JSON file configurations can cause the app to crash	4
3.2.3	Bug 1153311: Modbus TCP UI reports an error if the device name contains special characters	5
4	Version 4.4.1	5
4.1	New functions	5
4.1.1	Feature 669082: Modbus TCP Client - Configuring the byte sequence	5
4.1.2	Feature 1079080: Modbus TCP improvements	5
5	Service and support	6
6	Index	7

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2024 – 11	Release notes for the Modbus TCP App, Version 4.4.1
02	2026 – 03	Release Notes for the Modbus TCP App, Version 4.6.0

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.0

3.1 New functions

3.1.1 Feature 1174892: Modbus TCP string handling optimized

Description

Strings are now handled correctly and displayed as contiguous text.

3.2 Resolved defects and modifications

3.2.1 Bug 1053553: Modbus TCP FC23 display is incorrect

Description

Modbus TCP FC23 is not displayed with input and output registers.

Troubleshooting

Modbus TCP FC23 is now displayed with input and output registers.

3.2.2 Bug 1148052: Modbus TCP – Corrupt JSON file configurations can cause the app to crash

Description

The app can crash if the following information is missing. This can happen if the user copies the Data Layer configuration into a JSON file and tries to load it.

```
"$persistence_header": {  
    "bfbs": "../bfbs/device.bfbs",  
    "version": "0.0.2"  
},  
"$schema": "../types/device_schema.json",
```

3.2.3 Bug 1153311: Modbus TCP UI reports an error if the device name contains special characters

Description

If the configuration for the names contains special characters such as "-" or "#", the diagnostic message "404: DL_INVALID_ADDRESS" is displayed when opening the Modbus TCP page. The affected device and the subscriptions are not displayed. Everything is created and displayed correctly in the Data Layer. The device works with the subscriptions.

Troubleshooting

Special characters such as "-" or "#" are now supported in configuration and device names. Applications such as the PLC convert the special characters into an underscore "_" so that the names are IEC-compliant.

4 Version 4.4.1

4.1 New functions

4.1.1 Feature 669082: Modbus TCP Client - Configuring the byte sequence

Description

The byte sequence can be configured on the Modbus TCP register.

A BYTE, WORD or DWORD swap is possible.

The configuration is carried out via the Data Layer or the JSON configuration.

4.1.2 Feature 1079080: Modbus TCP improvements

Description

- Modbus TCP API available.
- Support of additional data types:
 - uint64
 - int32
 - int64
 - double
- Supporting FC1 Read Coil and FC2 Read Discrete Input in the Modbus TCP Client.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: ➔ service.svc@boschrexroth.de

Internet: ➔ <http://www.boschrexroth.com>

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

H

Helpdesk 6

Hotline 6

I

Important information 4

P

Product information 4

S

Service hotline 6

Support 6

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

