

VPN Client App

Virtual Point-to-Point Connection Software for ctrlX OS
Version 4.6.0

Copyright

© Bosch Rexroth AG 2026

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAX (TaDo/PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.0	4
3.1	New functions	4
3.1.1	Feature 1000136: Internal library update	4
4	Version 4.4.0	4
4.1	New functions	4
4.1.1	Feature 1000136: Internal library update	4
4.2	Resolved defects and modifications	4
4.2.1	Bug 1000685: Renewal of the certificate during an active connection results in unexpected behavior	4
5	Service and support	5
6	Index	7

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025-11	VPN Client App Version 4.4.0
02	2026-03	VPN Client App Version 4.6.0

Further information

- See ➔ [VPN Client App, Application Manual](#)

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.0

3.1 New functions

3.1.1 Feature 1000136: Internal library update

Description

The internal libraries have been updated.

4 Version 4.4.0

4.1 New functions

4.1.1 Feature 1000136: Internal library update

Description

The internal libraries have been updated.

4.2 Resolved defects and modifications

4.2.1 Bug 1000685: Renewal of the certificate during an active connection results in unexpected behavior

Description

If a certificate used in an active connection is renewed, the new certificate was not loaded due to caching, even if the connection was restarted. This could result in the VPN connection being terminated.

Bugfixing

If it is detected that a certificate has been renewed in the VPN certificate store, the new certificate is loaded immediately.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: [↗ service.svc@boschrexroth.de](mailto:service.svc@boschrexroth.de)

Internet: [↗ http://www.boschrexroth.com](http://www.boschrexroth.com)

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

B

Bug 1000685 4

F

Feature 1000136 4

H

Helpdesk 5

Hotline 5

I

Important information 4

Internal changes 4

N

New functions version 4.4.0 4

New functions version 4.6.0 4

P

Product information 4

R

Renewal of the certificate during an active
connection results in unexpected behavior . . 4

Resolved defects and modifications version
4.4.0 4

S

Service hotline 5

Support 5

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

