Mauser Karabiner 98k / Gewehr 98

Mauser Werke / Sauer / Steyr / DWM • The Benchmark of Bolt-Action Military Rifles (7.92x57mm / 8mm Mauser)

Manufacturer:	Mauser Werke / Sauer / Steyr / DWM	**Category:**	Rifles & Carbines
Action Type:	Controlled Round Feed (CRF) 3-Lug Bolt Action	**Era / Service:**	Military & Sporting Benchmark (1898–Present)
Calibers:	7.92x57mm Mauser (8x57 IS), 6.5x55mm Swedish, 7x57mm Mauser	**Covered Models:**	Gewehr 98 (WWI), Karabiner 98k (WWII Standard), Yugoslavian M48, Swedish Mauser M96 (6.5x55mm)

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Bolt Shroud Disassembly (Flag Safety Mid-Position) • Claw Extractor Removal without Bending • Floorplate Cartridge Release (Bullet Tip Catch) • Stock Recoil Crossbolt Torquing • Headspace Gauging

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
SAFETY SYSTEM	Three-position flag safety on bolt shroud (Left: Fire; Vertical: Disassembly & safe bolt operation; Right: Complete lock)
THIRD SAFETY LUG	Auxiliary locking lug at rear of bolt body enters bridge recess in catastrophic failure
GAS SHIELD	Flanged bolt sleeve directs escaping gas away from shooter's face into magazine well
EXTRACTOR COLLAR	Spring steel collar rotates around bolt body capturing the long spring claw extractor

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Decocked Bolt Removed from Action (Bolt Shroud Locked) **Bolt was removed with safety in FIRE position and decocked; cocking cam slipped forward and cannot be reinserted into receiver**	• Accidentally twisting bolt shroud or pulling trigger while extracting bolt.	**Immediate Action: Catch cocking piece bottom lug on edge of wooden workbench. Pull bolt body forward with muscle until cocking piece snaps into full-cock notch. Turn flag safety up to vertical, then slide bolt smoothly into receiver.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Mauser 98 Complete Disassembly, Claw Extractor & Safety Tuning	Mark Novak / Anvil Gunsmithing	Teardown of the Mauser 98 bolt: lifting and removing the claw extractor without bending, disassembling the firing pin spring, and adjusting the flag safety.