Remington Model 700 Rifles

Remington Arms / RemArms • The World's Benchrest & Tactical Standard (.308 Win, .30-06, 6.5 Creedmoor, .223)

Manufacturer:	Remington Arms / RemArms	**Category:**	Rifles & Carbines
Action Type:	Push-Feed 2-Lug Bolt Action	**Era / Service:**	Modern Precision Standard (1962–Present)
Calibers:	.308 Winchester, .30-06 Springfield, 6.5 Creedmoor, .300 Win Mag, .223 Remington	**Covered Models:**	Model 700 BDL (Deluxe), Model 700 SPS (Synthetic), Model 700 Police (PSS / 5R), M24 SWS (US Army), M40A1–A6 (USMC)

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Action Screw Torque (Front 55–65 in-lbs, Rear 45 in-lbs) • Bolt Shroud Disassembly (Shoelace / Tool Method) • Recoil Lug Alignment Jig Setup • Pillar & Glass Bedding Action • Timney / TriggerTech Trigger Upgrade

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
THREE RINGS OF STEEL	Remington safety design: Recessed bolt face enclosed by barrel counterbore, enclosed by thick front receiver ring
ACTION SCREWS TORQUE	Front action screw: 55 to 65 in-lbs (into front receiver ring); Rear action screw: 45 in-lbs (do NOT overtighten rear to prevent binding rear tang)
EXTRACTOR DESIGN	Riveted circular spring-steel C-clip snapped into groove inside bolt face recess
BARREL THREADS	1-1/16" x 16 TPI (Threads Per Inch) with 60° V-thread profile
HEADSPACE 308 WIN	GO = 1.6300", NO-GO = 1.6340", FIELD = 1.6380"

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Walker Trigger Accidental Discharge on Safety Release **Moving safety from SAFE to FIRE causes rifle to fire without finger touching trigger**	• Vintage pre-2006 Walker trigger design where connector floats free from trigger shoe; dirt, dried grease, or over-adjusted sear engagement allows connector to slip off sear when safety cam lifts. • User backing out sear engagement screw to lighten trigger pull.	**Immediate Action: DANGEROUS CONDITION. Never load rifle. Gunsmith Action: Mandatory upgrade: Remove factory Walker trigger group. Install modern enclosed sear trigger (TriggerTech Primary or Timney 510) featuring true captured sear design and zero creep.**
Stoppage 2: Riveted Extractor Slips Off Cartridge Rim **Bolt pulls rearward but fails to extract fired case from chamber**	• Broken or collapsed circular spring-steel extractor clip in bolt face. • Chamber corrosion creating high extraction force.	**Gunsmith Action: Use Remington extractor riveting tool to install fresh factory spring clip, or machine bolt face for Sako-style or M16-style sliding claw extractor conversion.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY

Remington 700 Bolt Disassembly, Cleaning & Firing Pin Service	Brownells Gunsmithing Bench	Step-by-step teardown of the Remington 700 bolt using the coin or shoelace method, checking firing pin protrusion, and cleaning the firing pin spring.