



**Investigation Report:
Aircraft Parking Position
Deviation During Marshalling
Operations of Flight EK338**
Version 01

This document contains the investigation report on the Aircraft Parking Guidance Deviation During Marshalling involving Emirates Flight EK338. It presents the facts and relevant information gathered during the investigation to determine the circumstances of the occurrence and support the implementation of appropriate safety measures.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	-----	2
1. Factual Information	-----	3
1.1 Operational Irregularity		
1.2 Risk Index		
1.3 Personnel's Information		
2. Analysis	-----	3
3. Root Cause	-----	3
4. Immediate Actions/Corrective Action	-----	4
5. Preventive Action	-----	4
6. References	-----	4
7. Investigation Team	-----	4

Executive Summary:

On 30 June, 2026 at approximately 1630H, during the arrival of Emirates Flight EK338, the assigned marshaller conducted standard aircraft marshalling procedures as the aircraft taxied toward its designated parking stand. As the aircraft approached the designated stop position, the marshaller transitioned from the "Proceed Straight Ahead" signal to the "Slow Down" signal. However, before the "Stop" signal could be given, the aircraft came to a complete stop at an incorrect aircraft stop position marking.

No injuries, aircraft damage, or damage to ground equipment were reported as a result of the occurrence. The investigation determined that the marshaller was performing marshalling duties in accordance with established procedures. This report presents the facts surrounding the incident, examines the circumstances that contributed to the aircraft stopping at the incorrect position, and provides recommendations to enhance operational safety and prevent similar occurrences.

1. Factual Information

1.1 Operational Irregularity

'Aircraft stopped at an incorrect designated stop position during marshalling, prior to the marshaller issuing the prescribed "Stop" signal.'

1.2 Risk Index

2D - LOW

1.3 Personnel Information

ID Number	M61348
Position	Ground Equipment Operator
Date of Hiring	October 26, 2023
Trainings	All trainings /courses are current

2. Analysis

- At the time of the occurrence, the EO was displaying the "straight ahead" hand signal, as the marshalling sequence had not yet progressed to the "stop" signal. Due to misjudgment of the aircraft's remaining distance, the EO continued providing the "straight ahead" signal, and the stop hand signal was not yet given. The flight crew visually interpreted the ongoing marshalling signal as the cue to stop and brought the aircraft to an immediate halt, resulting in the aircraft coming to rest short of the designated stop position (undershoot).
- The occurrence indicates a breakdown in the final phase of aircraft parking coordination, where proper communication and adherence to marshaller instructions are essential.
- While no injury, damage, or operational impact occurred, stopping at an incorrect position presented a potential risk to aircraft clearance, ground equipment positioning, and ramp safety.
- The investigation determined that the marshaller complied with established procedures. Continued emphasis on flight crew adherence to marshalling signals and accurate recognition of designated stop positions is recommended to prevent recurrence.

3. Root Cause:

- Inadequate Marshalling Signal Execution and Operator Miscalculation** – The equipment operator miscalculated the aircraft's remaining stopping distance during marshalling, resulting in the continued use of the straight-ahead hand signal beyond the appropriate point, which led the flight crew to interpret the signal as the cue to stop before reaching the designated stop position.

4. Immediate/Corrective Action

- Conduct a safety briefing and refresher training for all marshallers emphasizing the importance of clear, deliberate, and standardized execution of marshalling signals, particularly during the final aircraft stopping phase.
- Review the visibility and condition of aircraft stop position markings to ensure they are clearly identifiable and do not contribute to misinterpretation during aircraft parking operations.

5. Preventive Action

- a) Implement periodic competency assessments and refresher training for marshalling personnel to ensure continuous compliance with standard aircraft marshalling procedures and proper signal execution.
- b) Conduct periodic review of aircraft stand markings, visual guidance aids, and parking procedures to ensure they remain clear, visible, and effective in supporting safe aircraft positioning.
- c) Review and confirm that the visual marshalling signals prescribed in the PAGSS Ground Operations Manual are fully aligned with ICAO, IATA, and Emirates (EK) standard visual marshalling signal conventions, ensuring there are no local variations that could create ambiguity between the "straight ahead" and "stop" signals.

4. References


: Interview with concerned personnel
: Safety Security Report Form

5. Investigation Team

Prepared by:


Catalino M. Z. Borromeo
SSQA – S.H.E Representative

Approved by:


Roy Philip R. Macsaya
SSQA – Vice President (VP)