

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street, Canton, MA 02021
Phone: 617-624-5757 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

January 9, 2026

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
Kiame Mahaniah, Secretary, Executive Office of Health and Human Services (electronic copy)
Clerk, Massachusetts House of Representatives (electronic copy)
Clerk, Massachusetts Senate (electronic copy)
Lieutenant Steve Wilkins, Environmental Health and Safety Officer (electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Essex County Correctional Facility, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Cory J. Holmes
Senior Advisor, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
Traci Mello, RN, MSN, Director, Middleton Health Department (electronic copy)
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
Aaron Eastman, Superintendent (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kiame Mahaniah, MD, MBA
Secretary

Kimberley Driscoll
Lieutenant Governor

Robert Goldstein, MD, PhD
Commissioner

November 7, 2025

Kevin F. Coppinger, Sheriff
Essex County Sheriff's Department Headquarters
20 Manning Avenue
Middleton, MA 01949 (electronic copy)

Re: Facility Inspection – Essex County Correctional Facility, Middleton

Dear Sheriff Coppinger:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Essex County Correctional Facility on October 15 and 16, 2025 accompanied by Lieutenant Steven Wilkins, Environmental Health and Safety Officer and Captain Jotham Garbin, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 131 total deficiencies: 51 new deficiencies under the Required Standards (.100 and .200 series), 29 repeat deficiencies under the Required Standards, 37 new deficiencies under the Recommended Standards (.300 series), 14 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Visits Area

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies were found during the inspection:

1.	Records Hallway	IT Offices # 1003	105 CMR 451.353	Interior Maintenance: Mold observed on ceiling vent
2.	Records Hallway	IT Offices # 1003	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged

Holding Unit Hallway

Deficiencies under the Required Standards (.100 and .200 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	New Interview Room Hallway	Staff Dining # 1041	105 CMR 451.200*	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b).
----	----------------------------	---------------------	------------------	--

Food Service Area

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Entire Kitchen		105 CMR 451.200*	Design, Construction, and Installation; Cleanability: Floors not smooth and easily cleanable, floor damaged and stained throughout food service area. Standard found in 105 CMR 590; FC 6-201.11.
2.	Mechanical Tray Warewash Area		105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, warewash machine out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).
3.	3-Compartment Sink		105 CMR 451.200*	Materials for Construction and Repair; Indoor Areas: Floor surface not smooth and easily cleanable, paint damaged on access panel on floor near drying rack. Standard found in 105 CMR 590; FC 6-101.11(A)(1).
4.	Freezer # 2		105 CMR 451.200*	Design, Construction, and Installation; Cleanability: Floors not smooth and easily cleanable, floorboards warped and uneven throughout freezer. Standard found in 105 CMR 590; FC 6-201.11.
5.	Walk-In Cooler # 3		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B).
6.	Kettle Hood Area		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, kettle # 3 out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A).

7. Serving Line		105 CMR 451.200	Design and Construction, Functionality: Temperature measuring device not designed to be easily readable. Standard found in 105 CMR 590; FC 4-204.112(D). ** Corrected On-Site **
8. Serving Line		105 CMR 451.200*	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Time/temperature control for safety food not held at 135°F or above (P), Special Diet meals recorded at 94°F and not stored in an operational hot holding unit. Standard found in 105 CMR 590; FC 3-501.16(A)(1).
9. Hallway	Loading Dock	105 CMR 451.200*	Design, Construction, and Installation; Functionality: Exterior door not tight-fitting, loading dock door not weather tight. Standard found in 105 CMR 590; FC 6-202.15(A)(3).
10. 3-Compartment Sink		105 CMR 451.200	Protection of Clean Items, Storing: Metal Serving Trays not stored in a self-draining position. Standard found in 105 CMR 590; FC 4-903.11(B)(1).
11. 3-Compartment Sink		105 CMR 451.200	Protection of Clean Items, Storing: Plastic Food Trays not stored in a self-draining position. Standard found in 105 CMR 590; FC 4-903.11(B)(1). ** Corrected On-Site **
12. 3-Compartment Sink		105 CMR 451.200	Protection of Clean Items, Storing: Metal Trays not stored in a self-draining position. Standard found in 105 CMR 590; FC 4-903.11(B)(1). ** Corrected On-Site **

H.S.U.

Deficiencies under the Required Standards (.100 and .200 series)

8 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Inmate Bathroom # 2002	105 CMR 451.123*	Maintenance: Baseboard damaged
2. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Door frame rotted
3. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling left unfinished
4. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Trim around shower damaged
5. R5 Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor dirty
6. R5 Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall near toilet dirty
7. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Shower door frame rusted in shower
8. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Door frame rotted
9. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Walls damaged
10. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling left unfinished
11. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Shower door frame rusted in shower
12. R6 Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor dirty

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Nurse's Office # 2003	105 CMR 451.353	Interior Maintenance: Ceiling vent dirty
2. Entrance	105 CMR 451.350	Structural Maintenance: Front door rotted, door not rodent/weatherproof
3. Nurse's Office # 2003	105 CMR 451.353	Interior Maintenance: Ceiling vent dirty
4. I1-Isolation Room # 2005	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged

240 Building (J)**Deficiencies under the Required Standards (.100 and .200 series)**

29 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1. A Block	Shower Area	105 CMR 451.123*	Maintenance: Wall paint damaged in shower # 2, 3, 4 and 9
2. A Block	Shower Area	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 5 and 8
3. A Block	Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 5 and 8
4. A Block	Shower Area	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6
5. A Block	Shower Area	105 CMR 451.123*	Maintenance: Floor rusted in shower # 7
6. A Block	Handicapped Shower	105 CMR 451.123	Maintenance: Wall paint damage
7. B Block	Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, ice machine dirty
8. B Block	Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 3
9. B Block	Shower Area	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 2, 4, 5, 6, 7, 8, and 9
10. B Block	Shower Area	105 CMR 451.123	Maintenance: Wall paint damage in shower # 1, 2, 6, 7, 8, and 9
11. B Block	Shower Area	105 CMR 451.123*	Maintenance: Wall paint damage in shower # 3, 4, and 5
12. B Block	Shower Area	105 CMR 451.123*	Maintenance: Floor paint damage in shower # 3
13. B Block	Shower Area	105 CMR 451.123	Maintenance: Floor paint damage in shower # 4, 5, 6, 7, 8, and 9
14. C Block	Shower Area	105 CMR 451.123	Maintenance: Floor cracked outside showers
15. C Block	Shower Area	105 CMR 451.123	Maintenance: Ceiling cracked in shower # 4
16. D Block	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking
17. D Block	Shower Area	105 CMR 451.123*	Maintenance: Floor damaged throughout shower area
18. D Block	Handicapped Shower	105 CMR 451.123	Maintenance: Floor cracked at entrance

Deficiencies under the Recommended Standards (.300 series)

11 new deficiencies were found during the inspection:

1. Building Entrance		105 CMR 451.350	Structural Maintenance: Exterior entrance door not rodent and weathertight
2. B Block	Common Area	105 CMR 451.353	Interior Maintenance: Wall vents dusty near ice machine

3.	B Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent rusted/corroded in cell # 643, 654, and 655
4.	B Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 643
5.	C Block	Common Area	105 CMR 451.360	Protective Measures: Bird observed
6.	C Block	Common Area	105 CMR 451.353	Interior Maintenance: Wall vents dusty
7.	D Block	Common Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles water stained
8.	D Block	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Floor rusted/corroded next to sink
9.	D Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 838

Program Building (K)

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies were found during the inspection:

1.	Upper Programs	Male Staff Bathroom # 2024	105 CMR 451.123	Maintenance: Ceiling vent dusty
2.	Upper Programs	Male Staff Bathroom # 2024	105 CMR 451.123	Maintenance: Ceiling tiles water damaged

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 2 repeat deficiency (indicated by an *) were found during the inspection:

1.	Lower Programs	Exterior Hallway Door	105 CMR 451.350	Structural Maintenance: Exterior entrance door not rodent and weathertight, weather stripping damaged
2.	Upper Programs	Offices	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged in office # 2011 and 2031

Vocational Education Building

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies were found during the inspection:

1.	Second Floor	M.A.T. Area Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty
2.	Second Floor	M.A.T. Area Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling tiles water damaged
3.	Second Floor	M.A.T. Area Exam Room	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 133°F at handwash sink

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	Second Floor	M.A.T. Offices	105 CMR 451.353	Interior Maintenance: Ceiling vents dusty
----	--------------	----------------	-----------------	---

120 Building (F)

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	B Block	Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1, 3, and 5
2.	A Block	Shower Area	105 CMR 451.123*	Maintenance: Pooling water on floor outside of showers
3.	B Block	Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, ice scoop in ice machine dirty

Deficiencies under the Recommended Standards (.300 series)

8 new deficiencies and 10 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A Block	Cells	105 CMR 451.353	Interior Maintenance: Floor dirty in cell # 151, 152, 156, 158, and 159
2.	A Block	Common Area	105 CMR 451.360*	Protective Measures: Bird observed
3.	A Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 108
4.	A Block	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 122
5.	A Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 101 and 130
6.	A Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 121, 123, 125, and 130
7.	B Block	Slop Sink Room	105 CMR 451.360	Protective Measures: Drain flies observed in first floor slop sink room
8.	B Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 219 and 225
9.	B Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 217

60 Building (G)**Deficiencies under the Required Standards (.100 and .200 series)**

2 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	Cell Block	Upper Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 5
2.	Cell Block	Upper Shower Area	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6
3.	Control	Control Bathroom	105 CMR 451.123	Maintenance: Feminine hygiene product dispenser rusted/corroded

Deficiencies under the Recommended Standards (.300 series)

7 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	Entrance		105 CMR 451.350	Structural Maintenance: Exterior siding damage
2.	Cell Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vents rusted/corroded in cell # 302, 311, 320, and 325
3.	Control		105 CMR 451.353	Interior Maintenance: Floor tiles damaged inside entrance
4.	Cell Block		105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 349
5.	Cell Block		105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 340

80 Building (H)**Deficiencies under the Recommended Standards (.300 series)**

2 new deficiencies were found during the inspection:

1. Lower 80 – First Floor	Common Area	105 CMR 451.353	Interior Maintenance: Fan dusty
2. Upper 80 - Second Floor	Dorm Room # 420	105 CMR 451.353	Interior Maintenance: Floor tile damaged at entrance

Gym Building (I)

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies were found during the inspection:

1. Gym	105 CMR 451.353	Interior Maintenance: Wall vents dusty
2. Inmate Bathroom	105 CMR 451.353	Interior Maintenance: Wall damage above entrance

SECTION 2: Areas Found to be in Compliance

EHRS inspected 212 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 5 areas of the facility because they were either in use, locked, or under repair:

1. 60 Building (G)	Cell Block	Upper Shower Area	Unable to Inspect Showers # 7, 8, 9 - In Use
2. Visits Area	Shift Commanders Office #1014		Unable to Inspect - Locked
3. Visits Area	Records Hallway	Property Room # 1013	Unable to Inspect - Locked
4. Vocational Education Building	Voke 1 (Unoccupied)		Unable to Inspect - Under Construction
5. Vocational Education Building	Voke 2 (Unoccupied)		Unable to Inspect - Under Construction

SECTION 4: Plan of Correction

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 4: Observations and Recommendations

1. The inmate population was 824 at the time of inspection.
2. During the inspection EHRS staff recommended:
 - a. Continue with monthly plans for shower drain maintenance to ensure proper function; and

- b. Continue to work with a professional pest control company to treat drain flies. Prior to treatment, EHSO's should assess and document areas throughout the facility that require treatment that is then shared with the pest control company.
3. During the Kitchen Inspection:
 - a. EHRS staff noted metal baking sheets/pans and plastic serving trays stacked wet and not dried properly. EHRS strongly recommended:
 - i. Both metal baking sheets/pans and plastic trays be *separated* to be allowed to fully air dry; and
 - ii. More drying racks be obtained to provide spacing to dry metal baking sheets/pans and plastic trays.
4. The warewash machine was out-of-order and being serviced at the time of inspection. As an interim measure, the facility stated they would utilize Styrofoam trays and manually wash, rinse, and sanitize additional dishware until repairs are made.
5. In 120 Building (F), there were many dirty cells that were unoccupied, particularly in the Behavioral Stabilization Unit. It is recommended to establish a policy to have cells cleaned out upon exit, for them to be ready upon move in as needed.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#), available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Cory Holmes
Senior Advisor, EHRS, BCEH



ESSEX COUNTY SHERIFF'S OFFICE

Fire Safety Office Environmental Health and Safety Office

20 MANNING AVE.
MIDDLETON, MA 01949-2807

KEVIN F. COPPINGER
Sheriff

AARON EASTMAN
Superintendent

Telephone
(978)750-1900 x3280
Fax: (978) 750-1995
www.eccf.com

November 21, 2025

Cory Holmes, Senior Advisor, EHRS, BCEH
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021

Good afternoon Mr. Holmes,

This letter is in response to the plan of correction letter dated November 7, 2025. I hope the attached corrective action report answers your concerns in full. If you have any questions regarding this report or our response, please do not hesitate to contact Lieutenant Steven Wilkins at (978)750-1900 ext.3280 or myself at (978)750-1900 ext.3356.

Sincerely,

A handwritten signature in black ink, appearing to read 'A. Eastman', written over a horizontal line.

Aaron Eastman
Superintendent
Essex County Correctional Facility, Middleton Massachusetts



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kiame Mahaniah, MD, MBA
Secretary

Kimberley Driscoll
Lieutenant Governor

Robert Goldstein, MD, PhD
Commissioner

November 7, 2025

Kevin F. Coppinger, Sheriff
Essex County Sheriff's Department Headquarters
20 Manning Avenue
Middleton, MA 01949 (electronic copy)

Re: Facility Inspection – Essex County Correctional Facility, Middleton

Dear Sheriff Coppinger:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Essex County Correctional Facility on October 15 and 16, 2025 accompanied by Lieutenant Steven Wilkins, Environmental Health and Safety Officer and Captain Jotham Garbin, in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 131 total deficiencies: 51 new deficiencies under the Required Standards (.100 and .200 series), 29 repeat deficiencies under the Required Standards, 37 new deficiencies under the Recommended Standards (.300 series), 14 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Visits Area

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies were found during the inspection:

1.	Records Hallway	IT Offices # 1003	105 CMR 451.353	Interior Maintenance: Mold observed on ceiling vent Ceiling vent was cleaned by inmate worker. Completed 10/16/25.
2.	Records Hallway	IT Offices # 1003	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged Ceiling tiles scheduled for painting or replacement by facility maintenance staff. Estimated completion 12/15/25.

Holding Unit Hallway

Deficiencies under the Required Standards (.100 and .200 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	New Interview Room Hallway	Staff Dining # 1041	105 CMR 451.200*	Cleaning of Equipment and Utensils, Frequency: Accumulation of soil observed on interior surfaces of ice machine. Standard found in 105 CMR 590; FC 4-602.11(E)(4)(b). Ice machine cleaned by inmate worker. Completed 10/16/25.
----	----------------------------	---------------------	------------------	---

Food Service Area

Deficiencies under the Required Standards (.100 and .200 series)

6 new deficiencies and 6 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Entire Kitchen		105 CMR 451.200*	Design, Construction, and Installation; Cleanability: Floors not smooth and easily cleanable, floor damaged and stained throughout food service area. Standard found in 105 CMR 590; FC 6-201.11. Due to the large cost and current budget constraints, the floor is being scheduled for repair in sections. Estimated completion fall 2026.
2.	Mechanical Tray Warewash Area		105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, warewash machine out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A). Warewash machine fixed by contracted vendor. Completed 10/24/25
3.	3-Compartment Sink		105 CMR 451.200*	Materials for Construction and Repair; Indoor Areas: Floor surface not smooth and easily cleanable, paint damaged on access panel on floor near drying rack. Standard found in 105 CMR 590; FC 6-101.11(A)(1). Floor panel scheduled for replacement by facility maintenance with new smooth finish surface. Estimated completion Jan 2026.

4. Freezer # 2		105 CMR 451.200*	Design, Construction, and Installation; Cleanability: Floors not smooth and easily cleanable, floorboards warped and uneven throughout freezer. Standard found in 105 CMR 590; FC 6-201.11. Floor scheduled for repair by facility maintenance. Estimated completion 2/15/26
5. Walk-In Cooler # 3		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged. Standard found in 105 CMR 590; FC 4-501.11(B). Gaskets scheduled for replacement by contracted vendor. Estimated completion 12/15/25.
6. Kettle Hood Area		105 CMR 451.200	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, kettle # 3 out-of-order. Standard found in 105 CMR 590; FC 4-501.11(A). Contracted kitchen vendor has three quotes pending for the replacement of the kettle. Estimated completion Jan 2026.
7. Serving Line		105 CMR 451.200	Design and Construction, Functionality: Temperature measuring device not designed to be easily readable. Standard found in 105 CMR 590; FC 4-204.112(D). ** Corrected On-Site **
8. Serving Line		105 CMR 451.200*	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Time/temperature control for safety food not held at 135°F or above (P), Special Diet meals recorded at 94°F and not stored in an operational hot holding unit. Standard found in 105 CMR 590; FC 3-501.16(A)(1). Hot hold cart was taken out of service and a properly functioning cart placed into service by contracted kitchen vendor. Completed 10/16/25
9. Hallway	Loading Dock	105 CMR 451.200*	Design, Construction, and Installation; Functionality: Exterior door not tight-fitting, loading dock door not weather tight. Standard found in 105 CMR 590; FC 6-202.15(A)(3). Gasket scheduled for replacement by facility maintenance staff. Estimated completion 12/15/25.
10. 3-Compartment Sink		105 CMR 451.200	Protection of Clean Items, Storing: Metal Serving Trays not stored in a self-draining position. Standard found in 105 CMR 590; FC 4-903.11(B)(1). Trays arranged in a manner that they could self drain by contracted kitchen vendor. Completed 10/16/25. In addition, the contracted kitchen vendor has bids out for new drying racks for trays. Estimated completion Jan 2026
11. 3-Compartment Sink		105 CMR 451.200	Protection of Clean Items, Storing: Plastic Food Trays not stored in a self-draining position. Standard found in 105 CMR 590; FC 4-903.11(B)(1). ** Corrected On-Site **
12. 3-Compartment Sink		105 CMR 451.200	Protection of Clean Items, Storing: Metal Trays not stored in a self-draining position. Standard found in

H.S.U.

Deficiencies under the Required Standards (.100 and .200 series)

8 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Inmate Bathroom # 2002	105 CMR 451.123*	Maintenance: Baseboard damaged Baseboard scheduled for repair by facility maintenance staff. Estimated completion 2/15/26.
2. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Door frame rotted Door frame schedule for repair/replacement by facility maintenance staff. Estimated completion 2/15/26.
3. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling left unfinished Ceiling scheduled for repair by facility maintenance. Estimated completion 2/15/26.
4. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Trim around shower damaged Trim scheduled for repair by facility maintenance. Estimated completion 2/15/26.
5. R5 Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor dirty Floor cleaned by inmate workers. Completed 10/16/25.
6. R5 Dorm Bathroom	105 CMR 451.123*	Maintenance: Wall near toilet dirty Wall cleaned by inmate workers. Completed 10/16/25.
7. R5 Dorm Bathroom	105 CMR 451.123	Maintenance: Shower door frame rusted in shower Door framed scheduled for repair by facility maintenance. Estimated completion 2/15/26
8. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Door frame rotted Door framed scheduled for repair by facility maintenance. Estimated completion 2/15/26.
9. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Walls damaged. Walls scheduled for repair by facility maintenance. Estimated completion 2/15/26.
10. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Ceiling left unfinished Ceiling scheduled for repair by facility maintenance. Estimated completion 2/15/26.
11. R6 Dorm Bathroom	105 CMR 451.123	Maintenance: Shower door frame rusted in shower Door frame scheduled for repair by facility

		maintenance. Estimated completion 2/15/26
12. R6 Dorm Bathroom	105 CMR 451.123*	Maintenance: Floor dirty Floor cleaned by inmate workers. Completed 10/16/25.

Deficiencies under the Recommended Standards (.300 series)

3 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Nurse's Office # 2003	105 CMR 451.353	Interior Maintenance: Ceiling vent dirty Vent cleaned by inmate workers. Completed 10/16/25
2. Entrance	105 CMR 451.350	Structural Maintenance: Front door rotted, door not rodent/weatherproof Door is scheduled for replacement by a contracted vendor. Estimated completion 12/15/25
3. Nurse's Office # 2003	105 CMR 451.353	Interior Maintenance: Ceiling vent dirty Ceiling vent cleaned by inmate workers. Completed 10/16/25
4. I1-Isolation Room # 2005	105 CMR 451.353*	Interior Maintenance: Floor tiles damaged Floor tiles scheduled for repair by facility maintenance. Estimated completion 12/15/25

240 Building (J)

Deficiencies under the Required Standards (.100 and .200 series)

29 new deficiencies and 13 repeat deficiencies (indicated by an *) were found during the inspection:

1. A Block	Shower Area	105 CMR 451.123*	Maintenance: Wall paint damaged in shower # 2, 3, 4 and 9 Shower walls painted by inmate workers. Completed 10/19/25
2. A Block	Shower Area	105 CMR 451.123	Maintenance: Wall paint damaged in shower # 5 and 8. Shower walls painted by inmate workers. Completed 10/19/25
3. A Block	Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 5 and 8 Shower walls cleaned by inmate workers. Completed 10/17/25
4. A Block	Shower Area	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6 Shower walls cleaned by inmate workers. Completed 10/17/25
5. A Block	Shower Area	105 CMR 451.123*	Maintenance: Floor rusted in shower # 7 Floor cleaned and painted by inmate workers. Completed 10/19/25
6. A Block	Handicapped Shower	105 CMR 451.123	Maintenance: Wall paint damage Shower wall painted by inmate workers. Completed 10/19/25
7. B Block	Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, ice machine dirty Ice machine cleaned by inmate workers. Completed 10/16/25
8. B Block	Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 3 Shower wall cleaned by inmate workers. Completed 10/16/25
9. B Block	Shower Area	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 2, 4, 5, 6, 7, 8, and 9 Shower walls cleaned by inmate workers. Completed 10/16/25.
10. B Block	Shower Area	105 CMR 451.123	Maintenance: Wall paint damage in shower # 1, 2, 6, 7, 8, and 9 Shower walls cleaned and painted by inmate workers. Completed 10/19/25

11. B Block	Shower Area	105 CMR 451.123*	Maintenance: Wall paint damage in shower # 3, 4, and 5 Shower walls cleaned and painted by inmate workers. Completed 10/19/25.
12. B Block	Shower Area	105 CMR 451.123*	Maintenance: Floor paint damage in shower # 3 Shower floor painted by inmate workers. Completed 10/19/25
13. B Block	Shower Area	105 CMR 451.123	Maintenance: Floor paint damage in shower # 4, 5, 6, 7, 8, and 9 Shower floor painted by inmate workers. Completed 10/19/25
14. C Block	Shower Area	105 CMR 451.123	Maintenance: Floor cracked outside showers Floor scheduled for repair by contracted vendor. Estimated completion May 2026.
15. C Block	Shower Area	105 CMR 451.123	Maintenance: Ceiling cracked in shower # 4 Ceiling scheduled for repair by facility maintenance. Estimated completion 12/15/25
16. D Block	Slop Sink Room	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking Faucet is scheduled for repair by facility plumber. Estimated completion 12/15/25
17. D Block	Shower Area	105 CMR 451.123*	Maintenance: Floor damaged throughout shower area Floor scheduled for repair by contracted vendor. Estimated completion May 2026
18. D Block	Handicapped Shower	105 CMR 451.123	Maintenance: Floor cracked at entrance Floor scheduled for repair by contracted vendor. Estimated completion May 2026

Deficiencies under the Recommended Standards (.300 series)

11 new deficiencies were found during the inspection:

1. Building Entrance		105 CMR 451.350	Structural Maintenance: Exterior entrance door not rodent and weathertight Door scheduled for repair by contracted vendor. Estimated completion May 2026
2. B Block	Common Area	105 CMR 451.353	Interior Maintenance: Wall vents dusty near ice machine Wall vent cleaned by inmate workers. Completed 10/16/25
3. B Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent rusted/corroded in cell # 643, 654, and 655 Wall vents cleaned by inmate workers and painted. Completed 10/19/25
4. B Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 643 Vent unblocked by inmates. Completed 10/16/25
5. C Block	Common Area	105 CMR 451.360	Protective Measures: Bird observed Facility EHSO is working with contracted pest control company to humanely catch and remove the birds. Estimated completion 12/15/25
6. C Block	Common Area	105 CMR 451.353	Interior Maintenance: Wall vents dusty Wall vents cleaned and painted by inmate workers. Completed 10/19/25
7. D Block	Common Area	105 CMR 451.353	Interior Maintenance: Ceiling tiles water stained Ceiling tiles scheduled for painting/replacement by facility maintenance staff. Estimated completion 12/15/25
8. D Block	Slop Sink Room	105 CMR 451.353	Interior Maintenance: Floor rusted/corroded next to sink Floor cleaned and painted by inmate workers. Completed 10/19/25

9.	D Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 838 Vent unblocked by inmates. Completed 10/16/25
----	---------	-------	-----------------	--

Program Building (K)

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies were found during the inspection:

1.	Upper Programs	Male Staff Bathroom # 2024	105 CMR 451.123	Maintenance: Ceiling vent dusty Vent cleaned by inmate worker. Completed 10/16/25
2.	Upper Programs	Male Staff Bathroom # 2024	105 CMR 451.123	Maintenance: Ceiling tiles water damaged Ceiling tile scheduled for painting/replacing by facility maintenance. Estimated completion 12/15/25

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 2 repeat deficiency (indicated by an *) were found during the inspection:

1.	Lower Programs	Exterior Hallway Door	105 CMR 451.350	Structural Maintenance: Exterior entrance door not rodent and weathertight, weather stripping damaged Door scheduled for repair by facility maintenance. Estimated completion 12/15/25.
2.	Upper Programs	Offices	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged in office # 2011 and 2031 Ceiling tiles schedule for painting/replacing by facility maintenance. Estimated completion 12/15/25.

Vocational Education Building

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies were found during the inspection:

1.	Second Floor	M.A.T. Area Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling vent dusty Ceiling vent cleaned by staff. Completed 10/16/25
2.	Second Floor	M.A.T. Area Staff Bathroom	105 CMR 451.123	Maintenance: Ceiling tiles water damaged Ceiling tiles scheduled for painting/replacing by facility maintenance. Estimated completion 12/15/25
3.	Second Floor	M.A.T. Area Exam Room	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 133°F at handwash sink Hot water temperature adjusted to 120 degrees by facility plumber. Completed 10/17/25

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	Second Floor	M.A.T. Offices	105 CMR 451.353	Interior Maintenance: Ceiling vents dusty Ceiling vent cleaned by staff. Completed 10/16/25.
----	--------------	----------------	-----------------	--

120 Building (F)

Deficiencies under the Required Standards (.100 and .200 series)

1 new deficiency and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	B Block	Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1, 3, and 5 Showers cleaned by inmate workers. Completed 10/16/25
2.	A Block	Shower Area	105 CMR 451.123*	Maintenance: Pooling water on floor outside of showers Water squeegeed into floor drain by inmate workers. Wet floor signs placed at drain pad. Completed 10/16/25
3.	B Block	Common Area	105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, ice scoop in ice machine dirty Ice scoop removed from service by staff. A new ice scoop was placed into service. Completed 10/17/25.

Deficiencies under the Recommended Standards (.300 series)

8 new deficiencies and 10 repeat deficiencies (indicated by an *) were found during the inspection:

1.	A Block	Cells	105 CMR 451.353	Interior Maintenance: Floor dirty in cell # 151, 152, 156, 158, and 159 Floors cleaned by inmate workers. Completed 10/16/25.
2.	A Block	Common Area	105 CMR 451.360*	Protective Measures: Bird observed Facility EHSO is working with contracted pest control company to humanely catch and remove the birds. Estimated completion 12/15/25
3.	A Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 108 Vent unblocked by inmates. Completed 10/16/25
4.	A Block	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 122 Cell painted by inmate workers. Completed 10/19/25
5.	A Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 101 and 130 Cell painted by inmate workers. Completed 10/19/25
6.	A Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 121, 123, 125, and 130 Vent unblocked by inmates. Completed 10/16/25
7.	B Block	Slop Sink Room	105 CMR 451.360	Protective Measures: Drain flies observed in first floor slop sink room Drain was cleaned by facility plumber. Completed 10/20/25
8.	B Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 219 and 225 Cell painted by inmate workers. Completed 10/19/25
9.	B Block	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 217 Vent unblocked by inmates. Completed 10/16/25.

60 Building (G)

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	Cell Block	Upper Shower Area	105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 5 Showers cleaned by inmate workers. Completed 10/16/25
2.	Cell Block	Upper Shower Area	105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6 Showers cleaned by inmate workers. Completed 10/16/25
3.	Control	Control Bathroom	105 CMR 451.123	Maintenance: Feminine hygiene product dispenser rusted/corroded Dispensing machine scheduled for

removal by facility maintenance. Estimated completion 12/15/25

Deficiencies under the Recommended Standards (.300 series)

7 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1. Entrance		105 CMR 451.350	Structural Maintenance: Exterior siding damage Siding scheduled for repair by facility maintenance. Estimated completion 2/15/26
2. Cell Block	Cells	105 CMR 451.353	Interior Maintenance: Wall vents rusted/corroded in cell # 302, 311, 320, and 325 Vents scraped and painted by inmate workers. Completed 10/19/25
3. Control		105 CMR 451.353	Interior Maintenance: Floor tiles damaged inside entrance Tiles scheduled for repair by facility maintenance. Estimated completion 12/15/25
4. Cell Block		105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 349 Cell painted by inmate workers. Completed 10/19/25
5. Cell Block		105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 340 Cell painted by inmate workers. Completed 10/19/25

80 Building (H)

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies were found during the inspection:

1. Lower 80 – First Floor	Common Area	105 CMR 451.353	Interior Maintenance: Fan dusty Fan cleaned by inmate workers. Completed 10/16/25
2. Upper 80 - Second Floor	Dorm Room # 420	105 CMR 451.353	Interior Maintenance: Floor tile damaged at entrance Floor tiles scheduled for repair by facility maintenance. Estimated completion 12/15/25

Gym Building (I)

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies were found during the inspection:

1. Gym	105 CMR 451.353	Interior Maintenance: Wall vents dusty Vent scheduled for cleaning by facility maintenance due to height. Estimated completion 12/15/25
2. Inmate Bathroom	105 CMR 451.353	Interior Maintenance: Wall damage above entrance Wall scheduled for repair by facility maintenance. Estimated completion 12/15/25

SECTION 2: Areas Found to be in Compliance

EHRS inspected 212 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 5 areas of the facility because they were either in use, locked, or under repair:

1. 60 Building (G)	Cell Block	Upper Shower Area	Unable to Inspect Showers # 7, 8, 9 - In Use
2. Visits Area	Shift Commanders Office #1014		Unable to Inspect - Locked

3. Visits Area	Records Hallway	Property Room # 1013	Unable to Inspect - Locked
4. Vocational Education Building	Voke 1 (Unoccupied)		Unable to Inspect - Under Construction
5. Vocational Education Building	Voke 2 (Unoccupied)		Unable to Inspect - Under Construction

SECTION 4: Plan of Correction

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice. The Plan of Correction must include:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 4: Observations and Recommendations

1. The inmate population was 824 at the time of inspection.
2. During the inspection EHRs staff recommended:
 - a. Continue with monthly plans for shower drain maintenance to ensure proper function; and
 - b. Continue to work with a professional pest control company to treat drain flies. Prior to treatment, EHSO's should assess and document areas throughout the facility that require treatment that is then shared with the pest control company.
3. During the Kitchen Inspection:
 - a. EHRs staff noted metal baking sheets/pans and plastic serving trays stacked wet and not dried properly. EHRs strongly recommended:
 - i. Both metal baking sheets/pans and plastic trays be *separated* to be allowed to fully air dry; and
 - ii. More drying racks be obtained to provide spacing to dry metal baking sheets/pans and plastic trays.
4. The warewash machine was out-of-order and being serviced at the time of inspection. As an interim measure, the facility stated they would utilize Styrofoam trays and manually wash, rinse, and sanitize additional dishware until repairs are made.
5. In 120 Building (F), there were many dirty cells that were unoccupied, particularly in the Behavioral Stabilization Unit. It is recommended to establish a policy to have cells cleaned out upon exit, for them to be ready upon move in as needed.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#), available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:


- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,

A handwritten signature in blue ink, appearing to read 'C. J. Holmes', is positioned above the printed name.

Cory Holmes
Senior Advisor, EHRS, BCEH



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021
Phone: 617-624-5454

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

December 9, 2025

Kevin F. Coppinger, Sheriff
Essex County Sheriff's Department Headquarters
20 Manning Avenue
Middleton, MA 01949 (electronic copy)

Re: Plan of Correction – Essex County Correctional Facility, Middleton

Dear Sheriff Coppinger:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction in response to my inspection on October 15 and 16, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted and requests additional information.

Your Plan of Correction states you have a contracted vendor for several repairs needed throughout the facility. The EHRS appreciates the repair plans in regards to:

1. Kitchen floor repairs to be completed in the Fall of 2026;
2. 240 Building C and D Block shower floor repairs to be completed in May 2026; and
3. 240 Building entrance door repairs to be completed in May 2026.

Due to the length of time needed for the repairs, the EHRS would also like to be informed of your facilities interim measures you have implemented to ensure the health and safety of inmates and staff in these areas.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A blue ink signature of Cory J. Holmes.

Cory J. Holmes
Senior Advisor, EHRS, BCEH

cc: Aaron Eastman, Superintendent
Lieutenant Steven Wilkins, Environmental Health and Safety Officer

(electronic copy)
(electronic copy)



ESSEX COUNTY SHERIFF'S OFFICE

Fire Safety Office Environmental Health and Safety Office

20 MANNING AVE.
MIDDLETON, MA 01949-2807

KEVIN F. COPPINGER
Sheriff

AARON EASTMAN
Superintendent

Telephone
(978)750-1900 x3280
Fax: (978) 750-1995
www.eccf.com

December 30, 2025

Cory Holmes, Senior Advisor, EHRS, BCEH
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021

Good afternoon Mr. Holmes,

This letter is in response to the plan of correction letter dated December 9, 2025. In regards to the long-term repair concerns, below are the steps that the facility is taking to ensure inmate and staff safety while we await the repairs.

1-Kitchen Floors—The facility, along with our contracted kitchen vendor, thoroughly scrubbed the kitchen floor and filled in the existing cracks to try and make the floor as smooth as possible. The floors are mopped throughout the day with Quat 64 Lemon, which is a disinfectant. In areas which are still in a condition that could be less than desirable, we have placed Wet Floor signs over the affected area.

2-240 C and D Shower Floors- In order to ensure safety of staff and inmates, we have instituted that after every shower use, a squeegee is used to push the water away from the cracked flooring and into the shower drains. Wet Floor signs are then placed until the floor is dry. The floor is mopped throughout the day with Quat 64 Lemon, which is a disinfectant.


3-240 Building Entrance Doors-The facility maintenance staff has used physical and mechanical force to bend the door back in such a manner that it now closes. They have also ordered a large bottom door sweep that will make the door weather and rodent tight. That will be installed once the part comes in.

I hope these corrective actions answers your concerns in full. If you have any questions regarding this report or our response, please do not hesitate to contact Lieutenant Steven Wilkins at (978)750-1900 ext.3280 or myself at (978)750-1900 ext.3356.

Sincerely,

A handwritten signature in black ink, appearing to read 'Aaron Eastman', with a stylized, flowing script.

Aaron Eastman
Superintendent
Essex County Correctional Facility, Middleton Massachusetts



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021
Phone: 617-624-5454

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

December 30, 2025

Kevin F. Coppinger, Sheriff
Essex County Sheriff's Department Headquarters
20 Manning Avenue
Middleton, MA 01949 (electronic copy)

Re: Plan of Correction – Essex County Correctional Facility, Middleton

Dear Sheriff Coppinger:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction in response to my inspection on October 15 and 16, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink, appearing to read "C. J. Holmes".

Cory J. Holmes
Senior Advisor, EHRS, BCEH

cc: Aaron Eastman, Superintendent
Lieutenant Steven Wilkins, Environmental Health and Safety Officer

(electronic copy)
(electronic copy)