INA3221::reset

INA3221::setAveragingMode

INA3221::setBusConversionTime

INA3221::setBusMeasDisable

INA3221::setBusMeasEnable

INA3221::setModeContinious

INA3221::setModePowerDown

INA3221::setModeTriggered

INA3221::setShuntConversionTime

INA3221::setShuntMeasDisable

INA3221::setShuntMeasEnable

INA3221:: write