

Левая боковина 2 секции (начало)				
	Цепи переменного тока В1			Х
		1	Х:1	SG1:2
		2	Х:2	SG1:4
		3	Х:3	SG1:6
		4	Х:4	SG1:8
		5	Х:5	SG1:10
		6	Х:6	SG1:12
		7		
		8		
	Цепи переменного тока В2			Х
		9	Х:7	SG2:2
		10	Х:8	SG2:4
		11	Х:9	SG2:6
		12	Х:10	SG2:8
		13	Х:11	SG2:10
		14	Х:12	SG2:12
		15		
		16		
	Цепи переменного тока В3			Х
		17	Х:17	SG3:2
		18	Х:18	SG3:4
		19	Х:19	SG3:6
		20	Х:20	SG3:8
		21	Х:21	SG3:10
		22	Х:22	SG3:12
		23		
		24		
	Цепи переменного тока В4			Х
		25	Х:25	SG4:2
		26	Х:26	SG4:4
		27	Х:27	SG4:6
		28	Х:28	SG4:8
		29	Х:29	SG4:10
		30	Х:30	SG4:12
		31		
		32		
	Цепи переменного тока В5			Х
		33	Х:33	SG5:2
		34	Х:34	SG5:4
		35	Х:35	SG5:6
		36	Х:36	SG5:8
		37	Х:37	SG5:10
		38	Х:38	SG5:12
		39		
		40		

Левая боковина 2 секции (продолжение на листе 2)

Правая боковина 2 секции (начало)				
Х	Выходные цепи			
A1-M2.XB-2	Х:135	135		
A1-M2.XB-4	Х:136	136		
A1-M2.XB-6	Х:137	137		
A1-M2.XB-8	Х:138	138		
A1-M2.XB-10	Х:139	139		
A1-M2.XB-12	Х:140	140		
A1-M2.XB-14	Х:141	141		
A1-M2.XB-16	Х:142	142		
A1-M2.XB-18	Х:143	143		
A1-M2.XB-20	Х:144	144		
A1-M2.XB-22	Х:145	145		
A1-M2.XB-24	Х:146	146		
A1-M2.XB-26	Х:147	147		
A1-M2.XB-28	Х:148	148		
A1-M2.XB-30	Х:149	149		
A1-M2.XB-32	Х:150	150		
A1-M3.XB-2	Х:151	151		
A1-M3.XB-4	Х:152	152		
A1-M3.XB-6	Х:153	153		
A1-M3.XB-8	Х:154	154		
A1-M3.XB-10	Х:155	155		
A1-M3.XB-12	Х:156	156		
A1-M3.XB-14	Х:157	157		
A1-M3.XB-16	Х:158	158		
A1-M3.XB-18	Х:159	159		
A1-M3.XB-20	Х:160	160		
A1-M3.XB-22	Х:161	161		
A1-M3.XB-24	Х:162	162		
A1-M3.XB-26	Х:163	163		
A1-M3.XB-28	Х:164	164		
A1-M3.XB-30	Х:165	165		
A1-M3.XB-32	Х:166	166		
A1-M4.XB-2	Х:167	167		
A1-M4.XB-4	Х:168	168		
A1-M4.XB-6	Х:169	169		
A1-M4.XB-8	Х:170	170		
A1-M4.XB-10	Х:171	171		
A1-M4.XB-12	Х:172	172		
A1-M4.XB-14	Х:173	173		
A1-M4.XB-16	Х:174	174		
		175		
		176		
		177		
		178		
		179		
		180		
		181		
		182		
		183		
		184		

Правая боковина 2 секции (продолжение на листе 2)

Условные обозначения

