

Левая боковина (начало)				
	Цепи переменного тока В1			Х
		1	X:1	SG1:2
		2	X:2	SG1:4
		3	X:3	SG1:6
		4	X:4	SG1:8
		5	X:5	SG1:10
		6	X:6	SG1:12
		7		
		8		
	Цепи переменного тока В2			Х
		9	X:7	SG2:2
		10	X:8	SG2:4
		11	X:9	SG2:6
		12	X:10	SG2:8
		13	X:11	SG2:10
		14	X:12	SG2:12
		15		
		16		
	Цепи переменного тока В3			Х
		17	X:17	SG3:2
		18	X:18	SG3:4
		19	X:19	SG3:6
		20	X:20	SG3:8
		21	X:21	SG3:10
		22	X:22	SG3:12
		23		
		24		
	Цепи переменного тока В4			Х
		25	X:25	SG4:2
		26	X:26	SG4:4
		27	X:27	SG4:6
		28	X:28	SG4:8
		29	X:29	SG4:10
		30	X:30	SG4:12
		31		
		32		
	Цепи переменного тока В5			Х
		33	X:33	SG5:2
		34	X:34	SG5:4
		35	X:35	SG5:6
		36	X:36	SG5:8
		37	X:37	SG5:10
		38	X:38	SG5:12
		39		
		40		

Левая боковина (продолжение на листе 2)

Правая боковина (начало)				
	Цепи фиксации присоединений			Х
		136		
		137		
		138		
		139		
		140		
		141		
		142		
		143		
		144		
		145		
		146		
		147		
A1-M8.XB:11	X:148	148		
A1-M8.XB:13	X:149	149		
A1-M8.XB:15	X:150	150		
A1-M8.XB:17	X:151	151		
A1-M8.XB:19	X:152	152		
A1-M8.XB:21	X:153	153		
A1-M8.XB:23	X:154	154		
A1-M8.XB:25	X:155	155		
A1-M8.XB:27	X:156	156		
A1-M8.XB:29	X:157	157		
A1-M8.XB:31	X:158	158		
A1-M9.XB:1	X:159	159		
A1-M9.XB:3	X:160	160		
A1-M9.XB:5	X:161	161		
A1-M9.XB:7	X:162	162		
A1-M9.XB:9	X:163	163		
A1-M9.XB:11	X:164	164		
A1-M9.XB:13	X:165	165		
		166		
		167		
		168		
		169		
		170		
		171		
		172		
A1-M8.XB:12	X:173	173		
		174		
Х	Выходные цепи			
A1-M2.XB:2	X:175	175		
A1-M2.XB:4	X:176	176		
A1-M2.XB:6	X:177	177		
A1-M2.XB:8	X:178	178		
A1-M2.XB:10	X:179	179		
A1-M2.XB:12	X:180	180		
A1-M2.XB:14	X:181	181		

Правая боковина (продолжение на листе 2)

Условные обозначения

