

	Цепи переменного тока ЛЭП		X			
		1	X:1	SG1:2	#	
		2	X:2	SG1:4	#	
			3	X:3	SG1:6	#
			4	X:4	SG1:8	#
			5	X:5	SG1:10	#
			6	X:6	SG1:12	#
			7			
			8			
	Цепи переменного тока 3/0 ЛЭП		X			
		9	X:9	SG2:2	#	
		10	X:10	SG2:4	#	
	Цепи переменного напряжения		X			
		11	X:11	SG3:2	+	
		12	X:12	SG3:4	+	
		13	X:13	SG3:6	+	
		14	X:14	SG3:8	+	
		15	X:15	SG4:2	+	
		16	X:16	SG4:4	+	
		17	X:17	SG4:6	+	
		18	X:18	SG4:8	+	
	Цепи отбора напряжения ЛЭП		X			
			19	X:19	SG5:2	+
			20	X:20	SG5:4	+
			21	X:21	SG5:6	+
	Цепи оперативного тока		X			
			22	X:22	UZ1:1	+
			23	X:23	SG1:14	—
			24			
			25			
			26			
			27			
			28			
		29	X:29	A1-M3.XB:1	—	
		30	X:30	A1-M3.XB:3	—	
		31	X:31	A1-M3.XB:5	—	
		32	X:32	A1-M3.XB:7	—	
		33	X:33	A1-M3.XB:9	—	
		34	X:34	A1-M3.XB:11	—	
		35				
		36				
		37				
		38				
		39				
		40				
		41				

Условные обозначения

