

| Category | Complaints |

|||

| Tyre Wear | 938 |

| Engine Overheating | 871 |

| Battery Issue | 861 |

| Low Mileage | 853 |

| Oil Leakage | 840 |

| Battery Drain | 839 |

| Suspension Noise | 306 |

| Fuel Leakage | 284 |

| Clutch Issue | 283 |

| Brake Noise | 282 |

BRANCH COMPLAINT VOLUME

| Branch | Complaints |

|||

| Tallakulam | 419 |

| Porur | 418 |

| Saibaba Colony | 399 |

| Anna Nagar Madurai | 393 |

| KK Nagar Trichy | 387 |

| Thillai Nagar | 382 |

| Suramangalam | 379 |

| RS Puram | 378 |

| Ammapet | 375 |

| Omalur | 374 |

HIGH PRIORITY ISSUES

| Category | Complaints |

|||

| Engine Overheating | 871 |

| Fuel Leakage | 284 |

| Brake Failure | 272 |

CUSTOMER SATISFACTION

Average Rating: 3.44

SUMMARY:

- Customers frequently report issues with tyre wear, engine overheating, and battery problems.
- Tallakulam branch experiences the highest volume of complaints among allocations.
- Engine overheating and fuel leakage are identified as high-priority concerns.

RECOMMENDATIONS:

- Increase inventory of spare tyres at Tallakulam branch to address frequent tyre wear issues.
- Implement regular maintenance checks for engine overheating in vehicles to prevent critical failures.
- Enhance communication channels with customers regarding battery issues, offering quick fixes or replacements.