

Batch	Remarks
SHNC ₂	DEV-130359: Stopper height adjustment in filling recipe. DEV-130440 and DEV-130431 also on this batch.
SHRV ₉	DEV-115094: Defective suction cups during filling, opening of isolator.