TWAIN Errata

For Version 2.2

January 17th, 2012



Contents

ICAP_XFERMECH......3

ICAP_XFERMECH

Page 10-197 (PDF page 603)

Error

A TWAIN driver must support TWSX_MEMORY and TWSX_NATIVE, therefore it must use TW_ENUMERATION when ICA_XFERMECH is queried using MSG_GET. Applications must still be prepared to handle TW_ONEVALUE returns; however any TWAIN 2.2 driver that does this has not passed TWAIN Certification.

Instructions for change

Add the red text.

Containers

MSG_GET	TW_ONEVALUE (permitted TWAIN 2.1 and earlier) TW_ENUMERATION (required TWAIN 2.2 and later)
MSG_GETCURRENT	TW_ONEVALUE
MSG_GETDEFAULT	TW_ONEVALUE
MSG_SET	TW_ONEVALUE
MSG_SETCONSTRAINT	TW_ONEVALUE
	TW_ENUMERATION
MSG_RESET	TW_ONEVALUE
MSG_QUERYSUPPORT	TW_ONEVALUE