

Surveillance 1

Report for:

PT Molindo Raya Industrial

LR reference: JKT6015008 / 3136134

Assessment dates: 14-November-2019 - 15-November-2019

Reporting date: 15-November-2019

Client address: Jl. Sumber Waras No. 255,Lawang,Malang ,

ID

Assessment criteria: OHSAS 18001:2007
Assessment team: Hartono, Sugeng
LR Client Facing Office: JKT Indonesia OU

Lloyd's Register Group Limited, its affiliates and subsidiaries, including Lloyd's Register Quality Assurance Limited (LRQA), and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'.Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.



Contents

01. Executive report	3
02. Assessment findings	4
03. Assessment summary	12
04. Next visit details	15
05. Appendix	16

Attachments:

JKT6015008_APP_AP Sv1 OHS.doc JKT6015008_RC_SV1_OHS_SH.doc

This report was presented to and accepted by:

Name: Ms. Erlies Sartini

Job title: Management Representative



01. Executive report

Assessment outcome:

This visit was to assess the compliance of the management system of PT Molindo Raya Industrial against OHSAS 18001:2007 as defined in the audit planning documentation. The outcome of the visit is recorded below.

Although there were findings on this audit, the findings were minor findings. In general, organizations have been able to demonstrate fulfilment to standard.

Continual improvement:

Improvement can be found by activities of measuring quality objectives, correcting audit results, analysis of data, internal audit, and corrective actions and management review. Including Corrective action to finding from last visit had been done.



Areas for senior management attention:

Please ensure consistence to make incident report.



02. Assessment findings

Where scheme requirement differs to the standard definition below, the scheme definition will take preference

Major Nonconformity

The absence of, or the failure to implement and maintain, one or more management system elements, or a situation which would, on the basis of the available objective evidence, raise significant doubt of the management to achieve: The policy, objectives or public commitments of the organisation, compliance with the applicable regulatory requirements, conformance to applicable customer requirements, conformance with the audit criteria deliverables.

Minor Nonconformity

A finding indicative of a weakness in the implemented and maintained system, which has not significantly impacted on the capability of the management system or put at risk the system deliverables, but needs to be addressed to assure the future capability of the system.

Reference number	879872_JKASHS01	Assessment Criteria (Clause)	OHSAS 18001:2007 (4.3.1)		
Grade	Minor NC	Issue Date	08-August-2018		
Status Closed		Process / Aspect	HIRADC Area "Parkir Depan"		
Location(s)		Jl. Sumber Waras No. 255	Jl. Sumber Waras No. 255,Malang,ID		
Statement of I	Non Conformity	Found no HIRADC in the "f from traffic movement	front parking" area. The potential of risk is		
Requirement		Clause 4.3.1 Hazard identification	fication, risk assessment and determining		
Evidence		There is no evidence of HII "Parkir Depan"	RADC regarding traffic movement at		
Proposed cor	rection, corrective action	Company will make HIRAD	OC. Timescale : end of August 2018		
Correction	_	Control not sufficient. In ge movement truck was not ye However only Assembly po movement of man still havi	Risk Assessment had been done. However the all Risk according to a man hit by heave the well controlled. Sign had been seen. Dint, Parking Direction. In fact; the ang risk to be hit by heavy truck (Example Company need to do more corrective		
		action and be verified at ne	ext audit. rocedure of parking INF/IK-03/04 for		



Root Cause analysis		
	HIRADC had been demonstrate	ed.
Corrective action	Finding can be closed. The cor	rective action had been done with
	effective.	
LR has reviewed and verified the implementation of actions taken.	Date of closure	14-November-2019



	0074700 1144 000404		011040 40004 0007 (400)	
Reference number	2274760_JKACBX01	Assessment Criteria (Clause)	OHSAS 18001:2007 (4.3.3)	
Grade Minor NC		Issue Date	30-January-2019	
Status	Open	Process / Aspect	Mandatory Element	
Location(s)		Jl. Sumber Waras No. 255,N	//alang,ID	
Statement of Non Conformity The Objective and target has not been set on safety and health at each department. T accident which is already achieved for man address to K3L department only.		department. The existing target only for hieved for man years and also it is target		
Requirement		OHSAS 18001:2007		
Evidence		Audit at each department		
Proposed correand timescales	ection, corrective action	To established improvement target and cascade to relevant department		
Correction		There are already objectives and targets in each department. But only called zero accident and zero ilness. There are no objectives that contain the relevance of departmental activities related to safety and health.		
Root Cause an	alysis			
Corrective acti	on	Finding still open		
	ed and verified the n of actions taken.	Date of closure		



Reference number	2274760_JKACBX02	Assessment Criteria (Clause)	OHSAS 18001:2007 (4.4.6)		
Grade	Minor NC	Issue Date	30-January-2019		
Status	Closed	Process / Aspect	Contractor and Supplier (Work Permit and inspection)		
Location(s)		Jl. Sumber Waras No. 255,	Jl. Sumber Waras No. 255,Malang,ID		
Statement of Non Conformity		Some weakness were identify on work permit system: a. The work permit has not been made specific for high hazard work hot work, confine space, working at height, etc). Therefore, the welding work on 28 January 2019 by contractor PT. Duta Amana Persada has no requirements for fire extinguisher, monitoring the flammable gas, etc. b. during audit at production, it was observed un used vessel has no control of access for confined space and the main hole was open. c. It was observed the subcontractor Building Work (CV Lumayan Jaya), there was no permit posted at location and the scafolding has not identify whether already inspected or not. It was observed one of three operator did not properly use the safety harness. The inspection of incoming truck has a weakness: a. The incoming truck inspection has no clear criteria to make decision whether the truck allow to enter and who is authorised to give a waiver if identify the discrepancy. b. No inspection on fence system on ethanol truck which is the heigh about 3 meter. During audit, it was observed one employee checking			
Dec. Second		fence of Sinarjaya Intimper	uck due to the hydraulic system for the kasa could not be operated.		
Requirement		fence of Sinarjaya Intimper OHSAS 18001:2007	kasa could not be operated.		
Evidence		fence of Sinarjaya Intimper OHSAS 18001:2007 Reviewing the work permit	document and during site visit		
Evidence	ction, corrective action	fence of Sinarjaya Intimper OHSAS 18001:2007	kasa could not be operated. document and during site visit		
Evidence Proposed correct	ction, corrective action	fence of Sinarjaya Intimper OHSAS 18001:2007 Reviewing the work permit To improve the system for Dangerous Work Procedur The latest is SHE / P-02 March	document and during site visit		



	Finding closed. Corrective action found effective.	
LR has reviewed and verified the Date of implementation of actions taken.	osure 14-November-2019	

Reference number	2274760_JKACBX03	Assessment Criteria (Clause)	OHSAS 18001:2007 (4.4.6)	
Grade	Minor NC	Issue Date	30-January-2019	
Status	Open	Process / Aspect	Operational Control	
Location(s)		Jl. Sumber Waras No. 255,Malang,ID		
Statement of No	Some weakness were identify during tour at production and log a. At Pembibitan area found the rotating belt of pump has no p guarding. Also the platform into valve has no fence. b. At propagator area (pH 4) has no emergency shower facilities. The valve for secondary containment located at risky area at cause people would reluctant to consistently closing the valve at therefore potentially cause the bund wall is not effective. d. Two out of six pump of product ethanol tank has not grounding system e. The product storage secondary containment need to be reviterm of the height of wall which is seem low at some location considering the contour and also it was found the outlet into riving without any valve.		nd the rotating belt of pump has no proper in into valve has no fence. 4) has no emergency shower facilities a containment located at risky area and may ant to consistently closing the valve and the bund wall is not effective. For oduct ethanol tank has not grounding condary containment need to be review in which is seem low at some location	
Requirement		OHSAS 18001:2007		
Evidence		During tour at Production and Logistic		
Proposed correct and timescales	ction, corrective action	To improve the facilities ac	ccordingly	
Correction		Finding still open.		
		term of the height of wall w	ndary containment need to be review in which is seem low at some location and also it was found the outlet into river	



	Finding can not be closed.
LR has reviewed and verified the implementation of actions taken.	Date of closure

Reference number	2274760_JKACBX04	Assessment Criteria (Clause)	OHSAS 18001:2007 (4.4.2)		
Grade Minor NC		Issue Date	30-January-2019		
Status Closed		Process / Aspect	HRD		
Location(s)		Jl. Sumber Waras No. 255,M	Jl. Sumber Waras No. 255,Malang,ID		
The competency has not been made in line with the result assessment. Such as the production operater has not be on job profile to be trained on working at height, work perfection to the profile for Warehouse operator has not been idented as the production and laboratory been evaluated profile for Warehouse operator has not been idented as the production and laboratory been fulfil the job profile training requirement but has not the follow up action as Year 2018 training has not been properly implemented as 30 % out of training program was implemented. Requirement The competency has not been made in line with the result assessment. Such as the production operator has not been evaluated profile for Warehouse operator has not been idented as the production operator has not been idented as the production operator has not been idented as the production and laboratory in the profile training requirement but has not the follow up action as the profile training program was implemented. OHSAS 18001:2007		duction operater has not been identify a working at height, work permit system, has not been evaluated properly, i.e.: operator has not been identify yet Employee review during audit has not ing requirement but has not determined been properly implemented. Only about			
Evidence		Training and job profile recor	ds		
Proposed corrand timescale	rection, corrective action s	To determine jo profile in line with HIRA and evaluated the gap need to be followed up			
Correction		Job Profile for Warehouse operator and Electircian has been identified yet The focus on SAP; However from December 2019 Job profile and review on safety competency already exists. Training schedule for 2019 has been fulfilled. Example Job Profile for Warehouse operator and Electrical staff.			
Root Cause a	nalysis	Root cause : The job profile r	not specific.		
Corrective act	ion	Finding can be closed. The c	orrective found effective.		
LR has review	red and verified the	Date of closure	14-November-2019		



implementation of actions taken.

Reference number	2274760_JKASHS01	Assessment Criteria (Clause)	OHSAS 18001:2007 (4.4.7)	
Grade Minor NC		Issue Date 29-January-2019		
Status Closed		Process / Aspect	Emergency preparadness	
Location(s)		Jl. Sumber Waras No. 2	55,Malang,ID	
in the form of work tools and materials. F and material. This will hinder the evacua cause tripping or getting hit.		direction specified, there are many obstacles and materials. For example grinding, weldin nder the evacuation process and potentially		
Requirement Evidence		Site visit to Workshop Static		
		·		
and timescales	ction, corrective action	Evacuation routes will be cleared of obstructions and clarified. Time scale: end of January 2019.		
Correction		Corrective action had been done.		
Root Cause and	llysis	Root cause had been solved.		
Corrective action	on	Corrective action found	effective. Finding closed.	
LR has reviewed and verified the implementation of actions taken.		Date of closure	14-November-2019	



Reference number	3136134_JKASHS01	Assessment Criteria (Clause)	OHSAS 18001:2007 (4.5.3)		
Grade Minor NC		Issue Date	14-November-2019		
Status New		Process / Aspect	Incident investigation		
Location(s)		Jl. Sumber Waras No. 255	s,Malang,ID		
Statement of Non Conformity At the time of the site visit to area front parking, there was a collapsed iron fence pedestrian. It was told by PIC that the pocollapsed because it was hit by a truck. After the interview, the were no incident reports.		strian. It was told by PIC that the pole			
Requirement		Clause 4.5.3	Clause 4.5.3		
Evidence		Site visit	Site visit		
Proposed correction, corrective action and timescales		Report will be made including investigation to find root cause and corrective action. Time: 16 Nov 2019.			
Correction					
Root Cause and	ılysis				
Corrective action	on				
LR has reviewed and verified the implementation of actions taken.		Date of closure			



03. Assessment summary

Visit generic objective:

This was a Surveillance 1 visit, conducted against objectives previously notified to the client. The objectives of the next visit, including any applicable visit specific objective (theme / focus), are confirmed in the audit plan attached to this report.

Client attendees at the opening and closing meeting:

Opening meeting 14 Nov 2019time: 08.00 Closing meeting 15 Nov 2019 time: 17.00

Attendance:

Opening and closing meeting attended by top management, MR, and relevant manager/staff:

-Ms. Erlis (MR and represnting top management);

The management legally responsible for occupational health and safety);

-Mr. Umar; -Ms. Kartika; -Mr. Joko; -Mr. Eko

Visit specific objective:

.

Introduction:

The following is an assessment report. Summary of this report has been explained in the closing meeting held after the assessment.

The Assessment is based on a sampling process of the available information.

Every evaluation and conclusion are based on sampling/evidence taken/shown during audit day.



Assessment Please see audit of:

-Ms. Erlis
-Mr. Umar
-Ms. Kartika
-Mr. Joko
-Mr. Eko

Audit trails and sources of evidence:

Audit area:

Verification at last audit

Mandatory Element

Legal compliance and the evaluation

Objective and programme

Communication, participation and consultation

Incident Investigation

Hazard identification, risk assessment and determining control

HRD (Competence, training and awareness); Resource roles and responsibility

Emergency preparedness and response

Utilities:

Maintenance:

Internal audit 22-29 May 2019 Management review 11 January 2019 Emergency simulation 3 Oct 2019 Daftar Pemeriksaan Hydran

Lift Certificate: 566/387/Elevator/108-5-Mlg/VIII/2018

Checklist Fire Extinguisher.
Safety Patrol Checklist

Zero accident in category "besar" dan "kecil"

Evaluation and conclusions:

Verification at last audit: Please See Finding Log

Mandatory Element: Management Review had been done properly and had been resulted relevant recommendation. Internal Audits had been done in order. Beside of internal audit, organization also done safety patrol. All of activities had been in accordance with procedure. Corrective action, and Continual Improvement had been demonstrated, example by giving action to result of audit and patrol. Complaint Management – As explain by auditee: No complaint received. Using of LRQA logo had been in accordance with guidance.

Legal compliance and the evaluation: Legal and other requirements had been accessed and the compliance had



been evaluated.

Objective and programme: Had been set for company. But need improvement for department. Please refer finding log.

Communication, participation and consultation: Communication and participation and consultation internally had been made by tool box meeting. Externally had been demonstrated by induction meeting, and communication with government by P2K3 report.

Incident Investigation: reported no incident. Please refer finding log.

Hazard identification, risk assessment and determining control: HIRADC had been review and updated.

HRD (Competence, training and awareness); Resource roles and responsibility: Found improved. Please refer also to Finding log (closed finding).

Emergency preparedness and response: Emergency preparedness and response had been demonstrated by showing completeness checking for: APAR, Hydran, Alarm and doing drill/simulation.

Site tour to Utilities and Maintenance: In general safety hazard and risk had been identified and the control had been defined. Instruction and direction or other information related with safety available.

Emergency respond had been prepared such as evacuation plan, Fire Extinguisher, Alarm, and Hydrant. People using relevant PPE such as helmet, safety shoes etc. Awareness and competency of people had been well demonstrated.

Areas for attention:

Opportunity for improvement:

- # Please consider there always a security to be traffic officer for large vehicles
- # Please consider if the need for SO written information is addressed to procurement.
- #There should be a checklist that proves that in carrying out internal audit procedures have been accessed by the auditor.
- #Parameter of successful participation should be there.
- #Please Review LOTO procedure
- #Please explore identification

New Minor Finding:

#No accident report (fence hit by truck)



04. Next visit details

Standard(s) / Scheme(s)	OHSAS 18001:2007	Visit type	Surveill	ance 2
Audit days	Due date	Februa	ry, 2020	
Team				
Site			Audit days	Activity codes
Jl. Sumber Waras No. 255,Malang,ID			2.00 DAY	066503



05. Appendix



1. Audit Programme/Plan

							CR
Visit Type	CR	SV1	SV2	SV3	SV4	SV5	Visit
Due Date	Feb	Aug	Feb	Aug			Feb
	2019 27 Jan	/2019 14 Nov	2020	2020			2021
Start Date	2019	2019					
End Date	30 Jan	15 Nov					
	2019	2019					
Audit Days	6	2	2	2	2	2	6
Any change in workforce							
numbers that may impact	N	N	\//NI	N/NI	N/NI	V/NI	Y/N
visit duration (if yes add			Y/N	Y/N	Y/N	Y/N	
new number)	Final sol	ection of th	o activitios	to be audite	d during th	o current vis	it will be determined
Process / aspect / location	i iliai sei			nagement ele			
Management Review	√	√	√	√	√ √	√ √	
Internal Audits	V	√	√	V	√	√	
Continual Improvement	V	√	√	√	√	√	
Management of change	V	√	√	√	√	√	
Corrective action	√	√	√	√	√	√	
Preventive action	√	√	√	√	√	√	
Complaint Management	V	√	√	√	√	√	
Use of Logo	V	√	√	√	√	√	
Legal compliance and the	√	V	√		√ √		
evaluation							
Objective and programme	V	1	1	√	1		
Communication,	√	1	√		1		
participation and							
consultation							
Incident Investigation	V			√	√		
Hazard identification, risk	√	,	,			√	
assessment and		√	√	$\sqrt{}$			
determining control	,						
HRD (Competence, training	√	,	,			1	
and awareness); Resource		√ √	√				
roles and responsibility							
Emergency preparedness and response	√	√	√			√	
Performance measurement	√					1 1	
and monitoring	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		√	√		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Purchasing and Contractor	V		,	,		1	
management (CSMS)	,		√			'	
Production:	√						
- Ethanol (Fermentation,	,						
Distillation,							
Control room and							
Production Lab)							
- Main Laboratory							
Warehouse (Logistic):	√						
- Raw Material (storage							
tank)			,			,	
- Supporting material			√			√	
- Finished Goods (storage							
tank)							
- Filling station area		<u> </u>		1			

1.0000000000000000000000000000000000000	D 4 60	
MSBSF43015	Page 1 of 2	Revision 0.1, 04 August 2015
WODOI 1 30 I3	1 490 1 01 2	I TOUSION O. I. 04 Addust 2015



Visit Type	CR	SV1	SV2	SV3	SV4	SV5	CR Visit
- Spare part							
Utilities :	$\sqrt{}$						
- Cooling system							
- Boiler, Generator		\ \ \		, v	\ \ \		
- Coal stock pile, Crusher							
Maintenance :	$\sqrt{}$						
- Mechanical - Rotary						V	
- Electrical and Instrument		\ \ \		'		V	
- Workshop - Static							
Transport (Trucking)	$\sqrt{}$						
General Area :	$\sqrt{}$						
- Office							
- Security							
- First Aid Room							
- Company transport							

Scope of the	Manufacture of Ethanol.
management	
system	
Exclusion	None

Note: if the visit involves more than one team member and/or is more than one day duration, an additional plan detailing the activities of each member of the team on each day will be required.



1. Report Considerations

LRQA Report considerations		
Have there been any deviation from the original assessment plan:	Yes /No	If yes detail these in the introduction section of the report along with the reasons for the deviations
Have there been any significant issues impacting on the audit programme:	Yes/No	If yes detail these in the introduction of the report and amend the APP
Have there been any significant changes that affect the management system of the client since the last audit took place:	Yes /No	If yes detail these within the executive summary section of the report
Have any unresolved issues been identified during the assessment:	Yes /No	If yes detail these within the executive summary section of the report
Was the audit undertaken a combined or integrated audit:	Yes /No	If yes confirm what type of audit and the standards covered in the introduction to the report.
Was the organization effectively controlling the use of the certification documents and marks:	Yes/ No	if no document within the reporting table covering the mandatory elements
If applicable has the organization taken effective corrective action regarding previously identified nonconformities:,	Yes/ No	Record outcome in the findings log against the relevant findings.
Does the management system of the organization continue to meet the applicable requirements and meet the expected outcomes:	Yes/ No	If no details reasons within the executive summary of the report
Does the scope of certification continue to be appropriate to the activities/products/services of organization:	Yes/ No	If no then document the actions necessary in relation to the scope in the executive summary of the report and amend the APP as required.
Were the objectives of the visit as defined in the APP fulfilled during the visit:		If no detail the reasons and any necessary actions in the executive summary of the report and amend/update the APP

Additional information

opportunities for improvement

If we identify opportunities to improve your already compliant system, we will either record them in the process table applicable to the area being assessed or in the Executive summary of the report if they can deliver improvement at a strategic level.

Confidentiality

We will treat the contents of this report, together with any notes made during the visit, in the strictest confidence and will not disclose them to any third party without written client consent, except as required by the accreditation authorities.

Sampling

The assessment process relies on taking a sample of the activities of the business. This is not statistically based but uses representative examples. Not all of the detailed nature of a business may be sampled so, if no issues are raised in a particular process, it does not necessarily mean that there are no issues, and if issues are raised, it does not necessarily mean that these are the only issues.

Legal entity

The accredited legal entity and client facing office that has provided the assessment service in this report is referenced in the applicable agreement for this service.

Form: LRMS03-04-11J Rev 1.0 13 March 2017