PW-200

Personal Digital Platform Scale

INSTRUCTION MANUAL V1.0



www.andmercury.com.au

Table of Contents

1.	General Description	1
2.	Preparation for Use	1
3.	Installing the batteries	2
4.	Display & Symbols	3
5.	Weighing	4

1. General Description

The PW-200 is a purpose built digital platform scale specifically designed for patient comfort and ease of use in the healthcare environment. The weight is displayed on a battery powered digital indicator in clear numbers on a high contrast liquid crystal display. The platform features a non slip surface making the unit ideal for personal weighing.

All surfaces are easy to clean and may be wiped with a damp cloth.

2. Preparation for use


2.1. Power source

The PW-200 Personal scale may be powered from dry batteries, or an AC power adapter, or from an optional rechargeable battery pack (AD-1681). When fitting the batteries in your scale please refer to page 2, "Installing the Batteries".


3. Installing the Batteries

Step 1 Turn off the display.

Step 1




Step 2 Press and slide to open the external cover. Press the hook of the internal cover to the left side and lift the cover.



Step 3 Insert six new dry cells ensuring correct polarity (+,-). Battery size is `D'



Step 4 Close the covers opened in step 2.



Cautions

Replace used dry cells with six new ones, when BATT is displayed.

Do not mix used and new batteries. It may cause damage to the battery or product.

Check the polarity when installing the batteries. If you do not observe this it may cause battery leakage. Also if the polarity of a battery is wrong the scale may only work temporarily.

The battery life is dependent upon the environmental temperature. Remove batteries from the display unit when the scale is not to be used for a long time. They may leak and cause damage.

Damage which is due to battery leakage is not covered under warranty.

4. Display and Symbols

STABLE	Stability mark. When the current weight value is not changing, this mark is displayed. The reading may now be taken.
NET ▼ ZERO	Zero point mark. With nothing on the pan and pressing the Switch, this mark is displayed. The zero point is the starting point to weighing.
NET ▼ ZERO	Net mark. After pressing the TARE switch this mark is displayed to show net weight is displayed
PT or PT	Preset tare mark. When storing a tare with digital input this mark blinks.
BATT	When the battery power is low this mark is displayed. Replace with six new batteries.
Weighed mass value unit STABLE O	Example: -Display of zero (zero point). With an empty weighing pan by pressing the ZERO switchThe Zero mark is displayedThe stability mark is displayed.

5. Weighing

To weigh a patient the following steps should be carried out:

- 1. Ensure that the scale is correctly positioned on a level surface, using the level vial as reference, with the levelling legs adjusted to ensure there is no tipping of the scale.
- 2. Ensure the scale is empty and switch on the scale.
- 3. Wait for the reading to show 0.00 kg
- 4. The person can now step onto the scale platform ensuring there feet are postioned in the area identified by the "blue feet" on the platform surface
- 6. Watch for the STABLE circle to light and then read the weight from the display.
- 7. Person can step off of the scale.



HEAD OFFICE:

32 Dew Street, Thebarton, S.A. 5031

Tel: (08) 8352-3033 Fax:(08) 8352-7409

VICTORIAN OFFICE:

Unit 4

313 Arden Street, Kensington, VIC. 3031

Tel: (03) 9372-1522 Fax:(03) 9372-1193

NSW OFFICE:

Unit 4, 14 Abbott Road, Seven Hills, NSW 2147

Tel: (02) 9674-5466 Fax:(02) 9674-2544

Internet Address:

http://www.andmercury.com.au