

## **SC/SE MODEL Set Up Procedure**

- Press and hold TARE and ZERO keys, and press the ON/OFF key. Continue pressing the TARE and Zero keys.
- Release the ZERO key while still holding the TARE key and press the ZERO key twice. Release the TARE key.
- Board version is now displayed e.g. "P1.04". Press the PRINT key to display "TYPE" setting.
- Press the TARE key to enter the setting. The model setting is now display e.g. "310000"

Capacity	TYPE
30kg	31 0 000
60kg	32 0 000
150kg	33 0 000
3kg	34 0 000 #
6kg	35 0 000 #
15kg	36 0 000 #
Certified	**1***
Uncertified	**0***
Software version	# P 1.80 only

## Please note certify mode disables the UNITS key.

- Use the PRINT (Λ) and UNITS (>) keys to adjust the model type. Press the TARE key to save the model type.
- Turn Scale off/on to return to normal weighing mode.