Complete HS Test

Vehicle Damage Assessment Report

Report No. 5487B4D7
Date: 03.04.2026

Vehicle Information

Manufacturer	Lada
Type	DOKKER
Subtype	DOKKER 1.5 dCi
VIN	UU1KG7Z04GJXXXXXX
KBA Number	8212/ADW00092
First Registration	04.06.2019
Last Registration	27.03.2019
Power	66 kW / 90 PS
Displacement	1.461 ccm
Vehicle Type	kombilimousine

Accident Information

Accident Date	15.03.2026
Accident Scene	Kreuzung B1/B2, Berlin-Mitte

Claimant

Name	Thomas Müller
Company	Autohaus Müller GmbH
Address	Friedrichstraße 100, 10117, Berlin
Email	thomas@autohaus-mueller.de
Phone	+493012345678
License Plate	CE N 668

Opponent

Name	Stefan Braun
Insurance Company	HUK-COBURG
Insurance Number	HUK-2026-789012

Visits

Type	claimant_residence
Address	Friedrichstraße 100, 10117, Berlin
Date	20.03.2026

Expert	Dr. Hans Turnes

Expert Opinion

Expert Name	Dr. Hans Turnes
File Number	HB-2026-001
Case Date	16.03.2026
Issued Date	01.04.2026
Mediator	Mark Cooper

Vehicle Condition

General Condition	Well maintained
Body Condition	Minor cosmetic
Interior Condition	Clean, no structural damage.
Paint Type	Metallic
Paint Finish	Original manufacturer paint
Paint Condition	Good
Driving Ability	Roadworthy
Mileage	85.420 km
Estimated Mileage	86.000 km
Next MOT	01.06.2027
Special Features	Klimaanlage, Navi
Full Service History	Yes
Test Drive Performed	Yes
Notes	Fahrzeug in gutem Gesamtzustand. Leichte Kratzer an der linken Seite.
Previous Damage Reported	Rear bumper repair 2024
Existing Damage (Not Reported)	Minor scratch on right mirror
Subsequent Damage	None

Tires

Set 1 | Profile: 4mmmmm | | DOT: —

Invoice

Invoice Number	GH-8861-2026
Invoice Date	03.04.2026

#	Description	Qty	Rate	Amount
1	Grundhonorar Gutachten	LS	-	362,00 €
2	Fotodokumentation (5 Bilder)	LS	-	7,50 €

3	Fahrtkosten	LS	-	40,00 €
4	Schreibkosten	LS	-	25,00 €
5	Porto & Telefon	LS	-	25,00 €

Net Total	0,00 €
VAT (19%)	0,00 €
Gross Total	**0,00 €**

Photo Documentation

Damage Photos (2)

Erhebliche Beschädigungen am rechten vorderen Kotflügel und Scheinwerferbereich. Der vordere Stoßfänger weist ausgeprägte Deformationen,

Schwerer Frontalaufprall mit massiven Deformationen an der rechten Fahrzeugfront. Die gesamte rechte Scheinwerfereinheit ist zerstört, die Mo-

Tire Photos (1)

Moderate wear visible across tread surface, tread pattern still defined, no visible cracking or bulges, even wear pattern suggests proper alignment

Documents (2)



8	04.06.2019	8212	ADW00092 9
1	M1	4 AC	
8	UU1K6720463XXXXXX	3 4	
D.3	DACIA		
	SD		
	00EV		
D.2	NB5CA000M500		
D.3	DOKKER		
2	DACIA (RO)		
	FZ.Z.PERS.BEF.B. 8 SPL.		
5	KOMBILIMOUSINE		
V.9	715/2007*2017/1347AD		
14	EURO6;WLTP;AD;PI/CI; M,		
P.3	BENZIN		
10	0001	36AD	01598
22	DATUM ZUR EMISSIONSKLASSE: 04.06.2019*		

02	01
04390 - -	
1804 - 1846	
-	00075
0175	00180
00900	01020
00900	01020
77	03750
01200	0635
195/55 R16 (91	
195/55 R16 (91	
-	
GRAU/GRAU	
e2*2001/116*03	
27.03.2019	
-	

MINDEN
26.11.2020