


Micro Quadrotor Wiring Diagram

Custom 3D-Printed Micro Quadrotor with Servo Payload Release | Rev A | 2026-08-30



Legend

- VBAT — battery voltage (7.6V, 2S HV)
- Regulated 5V (RX + servo power, from FC/ESC onboard BEC)
- Signal (SBUS, PWM)

GND is common between battery, FC/ESC, motors, receiver, and servo (single ground reference — no separate ground lines shown, standard practice for a build this small). Motor phase wires are soldered directly; no bullet connectors needed at this current level. 5V and PWM/SBUS signal wires run from the FC/ESC board's onboard BEC and servo pad respectively.