
Oil Pressure Gauge
Hydraulic T Line
(From Spindle)
Oil Fill Port
Hydraulic P Line
(To Spindle)
Drain Port
Oil Level Gauge


Pressure Switch
Tank