



ROOF INSPECTION SERVICES CC
PO BOX 675
JUKESKEI PARK
2153
e-mail : office@smuts.biz
TELEPHONE : (011) 818 0031

Building Control Officer
c/o

Ref. No:262934c/lmb

Dear Sir/Madam,

New Timber Roof Structure
Portion 465 Kromdraai,
Bela Bela

In accordance with the requirements of clause A19 of the National Building Regulations and Section 14 (2)A of the National Building Regulations and Buildings Standards Act, we hereby confirm that the timber roof structure for the above has been inspected and, as far as we were able to ascertain, complies with the design specifications and the National Building Regulations

This is a certificate of structural compliance only. We take no responsibility for any aspect of aesthetics or weather tightness. We also can take no responsibility for the quality of the builder's truss tie downs. Neither can we take responsibility for any latent defects which could not reasonably have been observed during the inspection.

Any interference with the roof structure as inspected, by a third party and for whatever reason and which introduces either patent or latent defects, will be the responsibility of said party.

Building owners are respectfully referred to the requirements of Regulation 9(4) of the Construction Regulations 2003, (emanating from The Occupational Health & Safety Act No 85 of 1993) which requires that any structure be inspected regularly to ensure that the structure is safe for continued use. This certificate is contingent on compliance with Regulation 9(4).

Yours faithfully,

Richard L Bailey (870126) Pr Eng
ROOF INSPECTION SERVICES CC

GCF SMUTS
ENGSPS130177

BSIC On: Eng Pr, Eng (870126) MSA/Pr, 8/6/00
Office: 011 363 0484
6 Leonora Road,
Springs
Francois: 081 772 9979

1. This certificate has no legal status unless signed by the Professional Engineer responsible for the design as per Regulation A19 of the National Building Regulations.
2. The engineer whose name appears on the certificate is appointed by the owner under Regulation A19 of the National Building Regulations.

3. In the event of a query with regard to this certificate contact the Roof Inspector on: 081 772 9979 OR Roof Inspection Services on 011 818 0331.
4. This Certificate applies to the Timber Roof Structure only as specified on the "Engineer's Completion Certificate".
5. In terms of section 14(2A) of the National Building Regulations and Building Standards Act – Act 103 (1979) and as read with Regulation A19 of the National Building Regulations (NBR), the Engineer has only accepted liability in respect of the Timber Roof Structure as specified on the "Engineer's Completion Certificate".

This liability is limited to the cost of repairing any structural defects to the roof structure only which can be shown to be as a result of negligence of the roof inspector or the Professional Engineer and for a maximum period of five years from the date of the final inspection up to the following limits of liability:

The upper amount of the following:

- Five times the total inspection fee including costs of inspection and checking and issue of the certificate
- Twenty percent of the cost of replacement of the entire distressed roof structure (excluding roof cover, ceilings and all subsequent damage, but including material and labour for such replacement).

6. This certificate is transferable, when ownership of building changes.
7. This certificate is only applicable to the original design and structure at the time and date of the final inspection.

